Form 3160-5 (June 2015)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

#### 5. Lease Serial No. NMLC065478B

**SUNDRY NOTICES AND REPORTS ON WELLS** Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

SUBMIT IN	TRIPLICATE - Other inst	tructions on	page 2		7. If Unit or CA/Agree NMNM70945X	ment, Name and/or No.
1. Type of Well  ☑ Oil Well ☐ Gas Well ☐ Oth	ner				8. Well Name and No. EMPIRE ABO UN	IT 133B
2. Name of Operator APACHE CORP	Contact: E-Mail: Isabel.Hud	ISABEL HUD son@apachec			9. API Well No. 30-015-22833	
3a. Address 303 VETERANS AIRPARK LA MIDLAND, TX 79705	ANE SUITE 1000	3b. Phone No Ph: 432.81	. (include area code) 8.1142		10. Field and Pool or E EMPIRE; ABO (	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State	
Sec 11 T18S R27E 450FNL 1	175FWL				EDDY COUNTY	, NM
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	, REPORT, OR OTH	IER DATA
TYPE OF SUBMISSION			TYPE OI	F ACTION		
Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Produc	tion (Start/Resume)	☐ Water Shut-Off
_	☐ Alter Casing	🗖 Нус	raulic Fracturing	Reclam	ation	■ Well Integrity
☐ Subsequent Report	Casing Repair	☐ Nev	/ Construction	☐ Recom	plete	Other
☐ Final Abandonment Notice	☐ Change Plans	🗖 Plug	and Abandon	▼ Tempos	rarily Abandon	
	☐ Convert to Injection	🗖 Plug	g Back	☐ Water I	Disposal	
If the proposal is to deepen direction. Attach the Bond under which the wo following completion of the involved testing has been completed. Final Aldetermined that the site is ready for fapache would like to perform Production Casing: 5-1/2? 15. Producing Interval: 5,966-6,060 Objective: Isolate open perfs.	rk will be performed or provided by the perations. If the operation rebandonment Notices must be filter in the following work. Pleas:  5# K-55 Set @ 6,225?	e the Bond No. or sults in a multipled only after all e see attachr	a file with BLM/BI/ le completion or reco requirements, includence.	A. Required su ompletion in a ding reclamation	ibsequent reports must be new interval, a Form 316 on, have been completed a form the following the	filed within 30 days 0-4 must be filed once
Procedure: 1. POOH with rods and tbg 2. Scan tbg and mark junk pip 3. Set CIBP @ 5,940? and du	e Imp bail 35? of cmt	Acci	npted for rec NMOCD # 8/13/1	cord (	SEE ATTACHE CONDITIONS	D FOR
14. I hereby certify that the foregoing is	Electronic Submission #	ACHE CORP,	sent to the Carls	bad		
Name (Printed/Typed) ISABEL H	•			ATORY AN	"	
Signature (Electronic S		DB EEDER/	Date 11/21/2		Jee	
	THIS SPACE FO	OK FEDEKA	L OK STATE	OFFICE U		
Approved By	e Di - am	~	Title 52	PET		2-7-1 Date
Conditions of approval, if any, are attache ertify that the applicant holds legal or equivalent would entitle the applicant to conduct the applicant	uitable title to those rights in the act operations thereon.	e subject lease	Office C1	£0	alo to our June 1	compared to the state of the st
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make if a	crune for any pe	rson knowingly and	winning to m	ake to any department or	agency of the United

## Additional data for EC transaction #358642 that would not fit on the form

# 32. Additional remarks, continued

- 4. Fill casing with fluid and pressure test to 500 psi 5. Record the test on a chart and submit for approval

November 21, 2016

Empire ABO Unit # M-133

Legal Name: Empire ABO Unit #133B

API # 30-015-22833 Eddy County, NM

Production Casing: 5-1/2" 15.5# K-55 Set @ 6,225'

Producing Interval: 5,966-6,064'

Objective: Isolate open perfs and TA wellbore. Well being evaluated for recompletion potential

## Procedure:

- 1. POOH with rods and tbg
- 2. Scan tbg and mark junk pipe
- 3. Set CIBP @ 5,940' and dump bail 35' of cmt
- 4. Fill casing with fluid and pressure test to 500 psi
- 5. Record the test on a chart and submit for approval

	Apache Co	orp.	
	Actual		
LEASE/UNIT:	Empire Abo Unit	DATE:	Nov. 18, 2016
WELL:	M-133	BY:	HJG
API NUMBER:	30-015-22833	COUNTY:	Eddy
LEGAL DESCRIPTION:	Sec 11, T18S, R27E	STATE:	New Mexico
FIELD:	Empire (BP)		
<b>Spud:</b> 5/23/79		KB =	
Rig Release:		GL =	3557'
		201	
11"	8-5/8" 24# K-55 Set @ 100 CMT 500 SX CIRC SURI		
	11		
	11		
	11		
4	5-1/2" 15.5# K-55 Set @ 6	52251	
	CMT W/ 1400 SX CIRC		
7-7/8"	}		
	}		
	1		
	1		
	DV tool @ 3995'		
	}		
	ABO (5/92)		
	Perf: 5966-76' (2 SPF)		
	5/92: Az w/ 1500 gal		
5. 75	ABO (5/92)		
	Perf: 5998-6010' (2 SPF)		
	5/92: Az w/ 1400 gal		
-			
	ABO (6/79)		
	Perf: 6044-64' (2 SPF)	110" 11 10 01 1 1500	.1 .11 11.0 1500 1150
	6/79: 150 gal 15%, 1000 ga	al 10# gelled CaCl wtr, 1500 g	gal gelled LC, 1500 gal 15%  Formation Tops:
<b>_</b>			Queen -
			Grayburg -
TD = 6225'			San Andres -
<b>PBTD</b> = $6180'$			Glorieta -
			Abo - 5939

. .

### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
  - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. The bridge plug is to be capped with 35 feet of cement (if bailed) or 25 sacks (if placed with tubing). If a cement plug is used, the top of the cement must be verified by tagging.
  - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
  - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
  - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
  - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- A procedure to plug and abandon the well.

Well Name: Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of 1 year after successful MIT and subsequent report is submitted.