

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Artesia District II

Received  
4/19/17

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*DAB1711041252*

Name of Company <b>OXY USA INC</b> <i>11010910</i>		Contact <b>CASEY L SUMMER</b>	<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Address <b>PO BOX 4294; HOUSTON, TX 77210</b>		Telephone No. <b>575-513-8289</b>		
Facility Name <b>BANK 18 FEDERAL COM #1H</b>		Facility Type <b>OIL WELL</b>		
Surface Owner <b>BLM</b>	Mineral Owner <b>BLM</b>	API No. <b>30-015-41447</b>		

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	18	23S	29E	133	NORTH	485	WEST	EDDY

Latitude\_32.3124352\_ Longitude\_-104.0305023\_ NAD83

**NATURE OF RELEASE**

Type of Release <b>PRODUCED WATER</b>	Volume of Release <b>120 bbls</b>	Volume Recovered <b>120 bbls</b>
Source of Release <b>3 inch steel line</b>	Date and Hour of Occurrence <b>4-14-2017</b>	Date and Hour of Discovery <b>4-14-2017</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Shelly Tucker-BLM; <del>Orvia Yu-NMOCD</del>; Mike Bratcher-NMOCD; Crystal Weaver-NMOCD</b>	
By Whom? <b>Casey Summers</b>	Date and Hour <b>4-14-2017 9:32 pm</b> <i>*e-mail 4/17/17 @ 9:43am</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

This leak was caused by a 3-inch steel line from the heater treater water leg to the inlet for water tanks failing. Inlet to water tank has been repaired. All fluid was contained within above ground Falcon lined containment.

Describe Area Affected and Cleanup Action Taken.\*

All fluid was recovered via vacuum truck from Falcon lined containment. Pictures have been included of cleaned containment. C141 has been marked as Initial and Final since all fluids were recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>CASEY L SUMMERS</b>	Approved by Environmental Specialist: <i>Crystal Wee</i>	
Title: <b>ENVIRONMENTAL ADVISOR</b>	Approval Date: <i>4/20/17</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>casey_summers@oxy.com</i>	Conditions of Approval: <b>SEE BELOW</b>	Attached <input type="checkbox"/>
Date: <i>4-19-17</i> Phone: <b>575-513-8289</b>		

**COA:** It is OCD's understanding that all impacted material has been removed/replaced, the liner cleaned and inspected for integrity.

**2RP-4177**