Form 3160-5 (June 2015)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR


FORM APPROVED OMB No 1004-0137 Expires January 31, 2018

-				****
ase Serial	No	NM	NM041	5688

BUREA	1	NMNM0415688A				
SUNDRY NO Do not use this for abandoned well. Us		6 If Indian, Allottee or Tribe Name				
SUBMIT IN TR	RIPLICATE - Other instructions	on page 2		ement. Name and or No		
Type of Well	The country country country	- Andrew Agentingson Andrews	8910124050			
Otl Well Gas Wel	ll Other		8 Well Name and No	OLD INDIAN DRAW UNIT #37		
2 Name of Operator Chevron U.S.A. In	IC.	·	9 API Well No 30-0	15-24573		
3a Address 6301 Deauville Blvd. Rm #N3002 Midland, TX 79706 (432) 687-7279			i	10 Field and Pool or Exploratory Area INDIAN DRAW; DELAWARE		
4 Location of Well (Footage, Sec., T., R.M., or Survey Description) 2160' FSL & 1960' FEL, Sec 18, T 22S, R28E			11 Country or Parish EDDY CO., NM	State		
12 CHECI	-	 I) TO INDICATI: NATURE	OF NOTICE. REPORT OR OTH	HER DATA		
TYPE OF SUBMISSION			E OF ACTION			
✓ Notice of Intent	Acidize Alter Casing	Deepen  Hydraulic Fracturing	Production (Start/Resume) Reclamation	Water Shut-Off Well Integrity		
Subsequent Report	Casing Repair Change Plans	New Construction  Plug and Abandon	Recomplete Temporarily Abandon	Other		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal			
	s If the operation results in a mul	ltiple completion or recompl	etion in a new interval, a Form 3	\$160-4 must be filed once testing has been the operator has detennined that the site		
the Bond under which the work will be completion of the involved operations completed Final Abandonment Notice	s If the operation results in a multies must be filed only after all request of the control of t	Itiple completion or recompletion or recomplet	etion in a new interval, a Form 3 ation, have been completed and a completed and compl	160-4 must be filed once testing has been the operator has detennined that the site to the operator has detennined that the site to the left of the le		
the Bond under which the work will be completion of the involved operations completed. Final Abandonment Notice is ready for final inspection.)  1. NOTIFY BLM 24 HRS BEFOR 2. SET CIBP@2500' AND SPOT 3: CIRCULATE WELLBORE WIT 4. SPOT 85SX OF CLASS "C" C 5. CLEAN LOCATION, CUT-OFF	If the operation results in a multies must be filed only after all request of the control of the	Itiple completion or recompletion or recomplet	etion in a new interval, a Form 3 ation, have been completed and a completed and compl	160-4 must be filed once testing has been the operator has detennined that the site to the operator has detennined that the site to the left of the le		
the Bond under which the work will be completion of the involved operations completed. Final Abandonment Notice is ready for final inspection.)  1. NOTIFY BLM 24 HRS BEFOR 2. SET CIBP@2500' AND SPOT 3: CIRCULATE WELLBORE WIT 4. SPOT 85SX OF CLASS "C" C 5. CLEAN LOCATION, CUT-OFF	If the operation results in a multies must be filed only after all request of the control of the	Itiple completion or recompletion or recomplet	Etion in a new interval, a Form 3 ation, have been completed and a second completed and second completed com	160-4 must be filed once testing has been the operator has detennined that the site to the operator has detennined that the site to the left of the le		
the Bond under which the work will be completion of the involved operations completed. Final Abandonment Notice is ready for final inspection.)  1. NOTIFY BLM 24 HRS BEFOR 2. SET CIBP@2500' AND SPOT 3: CIRCULATE WELLBORE WIT 4. SPOT 85SX OF CLASS "C" C 5. CLEAN LOCATION, CUT-OFF	RE OPERATIONS. 60SX THRU TUBING ON TO THE MLF. EMENT FROM 455'-SURFACE WELLHEAD, INSTALL DRY ED SYSTEM.  COPIED OF THE COPIED OF	Itiple completion or recompletion or recompletion or recompletion or recompletion or recompletion of the control of the contro	Etion in a new interval, a Form 3 ation, have been completed and a second completed and second completed com	NOOL CONSERVATION ARTESIA DISTRICT		
the Bond under which the work will be completion of the involved operations completed. Final Abandonment Notice is ready for final inspection.)  1. NOTIFY BLM 24 HRS BEFOR 2. SET CIBP@2500' AND SPOT 3. CIRCULATE WELLBORE WITH 4. SPOT 85SX OF CLASS "C" C. S. CLEAN LOCATION, CUT-OFF ALL FLUIDS WILL BE IN CLOSE	RE OPERATIONS. 60SX THRU TUBING ON TO THE MET FROM 455'-SURFACE WELLHEAD, INSTALL DRY ED SYSTEM.  CONTROL OF WELLHEAD OF THE CONTROL OF THE C	Title  Date  Directory  Directory	Subove 2340 Subove	NM OIL CONSERVATION ARTESIA DISTRICT JUN 06 2017  RECEIVED		
the Bond under which the work will be completion of the involved operations completed. Final Abandonment Notice is ready for final inspection.)  1. NOTIFY BLM 24 HRS BEFOR 2. SET CIBP@2500' AND SPOT 3. CIRCULATE WELLBORE WITH 4. SPOT 855X OF CLASS "C" C. S. CLEAN LOCATION, CUT-OFF ALL FLUIDS WILL BE IN CLOSE ALL FLUIDS WILL BE IN CLOSE M. LEE ROARK Iroark@chevron.  Signature	RE OPERATIONS. 60SX THRU TUBING ON TO THE MET FROM 455'-SURFACE WELLHEAD, INSTALL DRY ED SYSTEM.  CONTROL OF WELLHEAD OF THE CONTROL OF THE C	Itiple completion or recompletion or recompletion or recompletion or recompletion or recompletion or recompletion of the property of the control of the cont	Subove 2340 Subove	NM OIL CONSERVATION ARTESIA DISTRICT JUN 06 2017  RECEIVED		
the Bond under which the work will be completion of the involved operations completed. Final Abandonment Notice is ready for final inspection.)  1. NOTIFY BLM 24 HRS BEFOR 2. SET CIBP@2500' AND SPOT 3. CIRCULATE WELLBORE WITH 4. SPOT 85SX OF CLASS "C" C. S. CLEAN LOCATION, CUT-OFF ALL FLUIDS WILL BE IN CLOSE ALL FLUIDS WILL BE IN CLOSE M. Lee BOARK Iroark@chevron.	RE OPERATIONS. 60SX THRU TUBING ON TO THE MET FROM 455'-SURFACE WELLHEAD, INSTALL DRY ED SYSTEM.  CONTROL OF WELLHEAD OF THE CONTROL OF THE C	Title  Date  Directory  Directory	Subove 2340 Subove	NM OIL CONSERVATION ARTESIA DISTRICT JUN 06 2017  RECEIVED		

(Instructions on page 2)

any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction




### Chevron U.S.A. Inc. Wellbore Diagram: OID UT 37 WSW

@(3079-3100) Plug - Cement-



[Lease] OCA CARLSBAD FMT [Well No.] OLD INDIAN DRAW UT 37 WSW 37Z [Field] INDIAN DRAW [Location] 2160FSL1960FEL [Sec.] N/A [Blk] \_\_\_\_\_\_ [Survey] N/A [County] Eddy [St] New Mexico [Refno] DT8205 [API] 3001524573 [Cost Center] UCRE60100 [Section] E028 [Township] 18 S [Range] S022 E [Current Status] ACTIVE [Dead Man Anchors Test Date] NONE [Directions] \_\_\_\_\_\_



Tubing String Quantity (Top-Bottom Depth) Desc 82 @(14-2623) J-55 2.875 OD/ Unknown Weight/Thread 2.441 ID 2.347 Drift-1 @(2623-2626) Tubing Anchor/Catcher 2.875-13 @(2626-3052) J-55 2.875 OD/ Unknown Weight/Thread 2.441 ID 2.347 Drift-1 @(3052-3053) Seat Nipple - Standard (2.875) Cup Type-Rod String Quantity (Top-Bottom Depth) Desc 1 @(14-36) 1.500 (1 1/2 in.) Spray Metal x 22-1 @(36-42) 0.750 (3/4 in.) (Unknown) x 6 Rod Sub-1 @(42-52) 0.750 (3/4 in.) (Unknown) x 10 Rod Sub-114 @(52-2902) 0 750 (3/4 in.) (Unknown) x 25 Rod-6 @(2902-3052) 1 500 (1 1/2 in.) (Unknown) x 25 Sinker Bar-@(3052-3053) 1.000 (1 in.) (Unknown) x 1 Rod Sub-1 @(3053-3073) Rod Pump (Insert) (NON-SERIALIZED) - 25-200-R H BC -0-0 (Bore = 2.00)-Surface Casing (Top-Bottom Depth) Desc @(14-405) Wellbore Hole OD-12 2500-@(14-404) H-40 9.625 OD/ 32.30# Unknown Thread 9.001 ID 8.845 Drift-@(404-405) Casing Shoe (13.375 OD Casing)-@(14-405) Cement (behind Casing) 280sx CIC w/2% CaCI-Production Casing (Top-Bottom Depth) Desc @(405-3100) Wellbore Hole OD- 8.7500-@(14-3099) J-55 7.000 OD/ 20.00# Unknown Thread 6.456 ID 6.331 Drift-@(3099-3100) Casing Shoe ( 7 000 OD Casing)-@(14-3100) Cement (behind Casing) 600sx CIC Lite, 400 CIC neat-@(2535-3053) Perforations - Delaware - 2spf-Open

# WELLBORE DIAGRAM OLD INDIAN DRAW UNIT #37 PROPOSED

Created: Updated: Lease: Field: Surf. Loc.: Bot. Loc.: County: Status:	INDI	By: By: AN DRAW AN DRAW SL & 1960' F		Well #: API Unit Ltr.: TSHP/Rng: Pool Code: Directions: Chevno:	37 St. Lse:  30-015-24050  Section: 18  T22S / R28E  OGRID:
Surface Case Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:  RSLR 179 Caskle 7/0 Del 2310	9-5/8" 32.3# 405' 280 yes surface 12-1/4"		MLF	Spo	of 85sx of Class "C" Cement from 455'-face, Verify cement at surface. oe/FW/Surface)
Production of Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	Casing 7" 20# 3100' 1000 yes surface 8-3/4"		PBTD 3060 TD 3100'	Cla Per	(w 2485)  t CIBP#2500' and spot 60sx of ass "C" on top to cover rfs/B.Salt.  [99 abov( 2240)  fs: 2535'-3030' (OA)

### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

#### Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.