

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NM OIL CONSERVATION

ARTESIA DISTRICT

OCT 03 2017

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1727827603

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production Company	Contact	Wesley Ryan-Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-390-5436
Facility Name	Sargas 28 Federal Com 4H	Facility Type	Oil
Surface Owner	Federal	Mineral Owner	Federal
		API No	30-015-41560

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	29	18S	31E	1425	FSL	342	FEL	EDDY

Latitude: 32.715168

Longitude: -103.884201

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	1 BBL	Volume Recovered	None
Source of Release	Production Separator	Date and Hour of Occurrence	September 19, 2017 7:00AM	Date and Hour of Discovery	September 19, 2017 7:00AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	BLM- Shelly Tucker & OCD-Mike Bratcher		
By Whom?	Leonard Aguilar-Assistant Foreman	Date and Hour BLM:	September 19, 2017 5:40 PM	OCD:	September 19, 2017 5:43 PM
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

If a Watercourse was Impacted, Describe Fully.*N/A

Describe Cause of Problem and Remedial Action Taken.*

The oil line float valve on the free water knockout separator was malfunctioning and not working correctly causing the separator to fill up. The separator was isolated and by passed to prevent any further release. The separator oil line float valve was repaired.

Describe Area Affected and Cleanup Action Taken.*

1 BBL of Oil was released from the separator. None was recovered. The release originated from the separator that is located on the well pad which over sprayed West off the well pad in an area approximately 150ft x 40ft was affected by the release. An environmental contractor will be contacted to assist with the delineation and remediation of the affected area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Jennifer Reyna	OIL CONSERVATION DIVISION	
Printed Name: Jennifer Reyna	Approved by Environmental Specialist: <i>M. Bratcher</i>	
Title: Field Admin Support	Approval Date: 10/5/17	Expiration Date: N/A
E-mail Address: jennifer.reyna@dvn.com	Conditions of Approval:	
Date: 9/22/2017 Phone: 575.746.5588	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO. <i>ARP-4423</i> LATER THAN: 11/05/2017	

* Attach Additional Sheets If Necessary