Submit 1 Copy To Appropriate District Office	Energy, Minerals and Natural Resources Or., Hobbs, NM 88240 Or., Hobbs,		Form C-103	
<u>District 1</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240			Revised July 18, 2013 WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210			30-015-26623 5. Indicate Type of Le	ase
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No. K-6385	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Time of Well. Oil Well. Many Con Well. Discount of them.			7. Lease Name or Unit Agreement Name Dee 36 SE State	
		K SUCH	8. Well Number 3	
 Type of Well: Oil Well			9. OGRID Number	
EOG Y Resources, Inc.			025575 10. Pool name or Wildcat	
3. Address of Operator 104 South Fourth Street, Artesia,	NM 88210		Canyon; Wolfcamp	8450
4. Well Location				
Unit Letter J :	1650 feet from the South		980 feet from the	East line
Section 36 Township 19S Range 24E NMPM Eddy County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3603' GR				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING				
TEMPORARILY ABANDON				
PULL OR ALTER CASING				
CLOSED-LOOP SYSTEM		OTHER		
	to pressure monitor well pleted operations. (Clearly state all personal points)	OTHER: ertinent details, and	give pertinent dates, inc	cluding estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
EOG Y Resources, Inc. plans to convert this well to a pressure monitor well as follows: NM OIL CONSERVATION ARTESIA DISTRICT				
1. MIRU all safety equipment as needed. POOH with production equipment.				
1. MIRU all safety equipment as needed. POOH with production equipment. 2. Run CBL from 4500' to surface to confirm cement integrity. 3. Set a CIBP at 6350', 100' above current perforations. 4. Perforate 2310'-2320' 6 spf ½" holes. 25 sx Care-1 (class C) work RECEIVED				
4. Perforate 2310'-2320' 6 spf ½" holes.				
 5. Perforate 2450'-2460' 6 spf ½" holes. 6. Perforate 2720'-2730' 6 spf ½" holes. 				
7. RIH with tubing with sensor/packer array. Isolate and pressure monitor each set of perforations. Set packers and test gauges. Packer				
will be testable through tubing and monitored with pressure gauge on end of tubing.				
Spud Date:	Rig Release Dat	e:		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE (Cha) (Lucta) TITLE Regulatory Specialist DATE December 15, 2017				
Type or print name Tina Hu For State Use Only	uerta E-mail address: tina	huerta@eogresour	ces.com PHONE:	575-748-4168
	Cho TITLE STATE	Mer	DATE_/	1-3-18
Conditions of Approval (if any):		- /-		

Dee State #3 Proposed

Casing A 9-5/8" K-55 36# 1201
Casing B 7" K-55 26# 8109
Tubing 2-7/8" J-55 6.5# 6620

Perforations
2310' - 2320'
2450' - 2460'

6450 - 6500

7594 -7804

7902 - 7964

