| Sunday Continue | 263 |
|--|----------------|
| District 1-(757)-748-123 SI S. Firs X. Aresia, NM 88210 1220 South St. Francis Dr. RECEIV Santa Fe, NM 87505 S. Indicate Type of Lease STATE FEE S. | lame |
| SITS First St., Artesia, NM 88210 District III - (1905) 334-6178 RECEIVES and Fe, NM 87505 STATE FEE | lame |
| 1000 Nic Brazos Rd., Azice, NM 87410 | |
| SUBSEQUENT REPORT OF: SUBSEQUENT REPORT Of: SUBSEQUENT REPORT OF: PAND A | |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well | |
| DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well | _line |
| 2. Name of Operator Mewbourne Oil Company 3. Address of Operator PO Box 5270, Hobbs, NM 88241 4. Well Location Unit Letter H : 1980 feet from the North line and 990 feet from the East Section 27 Township 238 Range 28E NMPM County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PAND A PULL OR ALTER CASING MULTIPLE COMPL COMMENCE DRILLING OPNS. PAND A CASING/CEMENT JOB COMMENCE DRILLING OPNS. OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimat of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. | _line |
| 3. Address of Operator PO Box 5270, Hobbs, NM 88241 4. Well Location Unit Letter H : 1980 feet from the North line and 990 feet from the East Section 27 Township 23S Range 28E NMPM County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SIZEMENTALLY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PAND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB COMMENCE DRILLING OPNS PAND A CASING/CEMENT JOB THER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1/25/18: MIRU WS rig. ND WH & NU BOP. Released pkr & POOH w/ tbg. Changed out pkr. 1/28/18: RIH w/ 4 1/2" tbg to 13972'. Displaced csg w/ pkr fluid. Set pkr @ 13964'. ND BOP & NU WH. 1/29/18: Performed MIT test to 400# for 30 minutes, held OK. Richard Inge w/NMOCD witnessed and took chart with him. Ripwol. | _line |
| PO Box 5270, Hobbs, NM 88241 4. Well Location Unit Letter H : 1980 feet from the North line and 990 feet from the East Section 27 Township 23S Range 28E NMPM County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PAND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB COMMENCE DRILLING OPNS TOTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimat of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1/25/18: MIRU WS rig. ND WH & NU BOP. Released pkr & POOH w/ tbg. Changed out pkr. 1/28/18: RIH w/ 4 1/2" tbg to 13972'. Displaced csg w/ pkr fluid. Set pkr @ 13964'. ND BOP & NU WH. 1/29/18: Performed MIT test to 400# for 30 minutes, held OK. Richard Inge w/NMOCD witnessed and took chart with him. Ripwoll. | _line |
| 4. Well Location Unit Letter H : 1980 feet from the North line and 990 feet from the East Section 27 Township 23S Range 28E NMPM County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASIN COMMENCE DRILLING OPNS. ALTERING CASIN COMMENCE DRILLING OPNS. PAND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimat of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1/25/18: MIRU WS rig. ND WH & NU BOP. Released pkr & POOH w/ tbg. Changed out pkr. 1/28/18: RIH w/ 4 1/2" tbg to 13972'. Displaced csg w/ pkr fluid. Set pkr @ 13964'. ND BOP & NU WH. 1/29/18: Performed MIT test to 400# for 30 minutes, held OK. Richard Inge w/NMOCD witnessed and took chart with him. RIPWOL. | _line |
| Unit Letter H : 1980 feet from the North line and 990 feet from the East Section 27 Township 23S Range 28E NMPM County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3035 GL 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1/25/18: MIRU WS rig. ND WH & NU BOP. Released pkr & POOH w/ tbg. Changed out pkr. 1/28/18: RIH w/ 4 1/2" tbg to 13972'. Displaced csg w/ pkr fluid. Set pkr @ 13964'. ND BOP & NU WH. 1/29/18: Performed MIT test to 400# for 30 minutes, held OK. Richard Inge w/NMOCD witnessed and took chart with him. RIPWOL. | _line |
| Section 27 Township 23S Range 28E NMPM County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE COMMINGLE 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimator of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1/25/18: MIRU WS rig. ND WH & NU BOP. Released pkr & POOH w/ tbg. Changed out pkr. 1/28/18: RIH w/ 4 1/2" tbg to 13972'. Displaced csg w/ pkr fluid. Set pkr @ 13964'. ND BOP & NU WH. 1/29/18: Performed MIT test to 400# for 30 minutes, held OK. Richard Inge w/NMOCD witnessed and took chart with him. RIPWOL. | _line |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3035 GL 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB P AND A COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JOB OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimat of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1/25/18: MIRU WS rig. ND WH & NU BOP. Released pkr & POOH w/ tbg. Changed out pkr. 1/28/18: RIH w/ 4 1/2" tbg to 13972'. Displaced csg w/ pkr fluid. Set pkr @ 13964'. ND BOP & NU WH. 1/29/18: Performed MIT test to 400# for 30 minutes, held OK. Richard Inge w/NMOCD witnessed and took chart with him. RIPWOL. | A Comment |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK □ ALTERING CASING COMMENCE DRILLING OPNS.□ PAND A PULL OR ALTER CASING □ MULTIPLE COMPL □ CASING/CEMENT JOB □ COMMENCE COMMINGLE □ CLOSED-LOOP SYSTEM □ OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimat of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1/25/18: MIRU WS rig. ND WH & NU BOP. Released pkr & POOH w/ tbg. Changed out pkr. 1/28/18: RIH w/ 4 1/2" tbg to 13972'. Displaced csg w/ pkr fluid. Set pkr @ 13964'. ND BOP & NU WH. 1/29/18: Performed MIT test to 400# for 30 minutes, held OK. Richard Inge w/NMOCD witnessed and took chart with him. RIPWOL. | o de la Spanza |
| NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN COMMENCE DRILLING OPNS. PAND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimat of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1/25/18: MIRU WS rig. ND WH & NU BOP. Released pkr & POOH w/ tbg. Changed out pkr. 1/28/18: RIH w/ 4 1/2" tbg to 13972'. Displaced csg w/ pkr fluid. Set pkr @ 13964'. ND BOP & NU WH. 1/29/18: Performed MIT test to 400# for 30 minutes, held OK. Richard Inge w/NMOCD witnessed and took chart with him. Ripwoll. | |
| NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PAND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimat of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1/25/18: MIRU WS rig. ND WH & NU BOP. Released pkr & POOH w/ tbg. Changed out pkr. 1/28/18: RIH w/ 4 1/2" tbg to 13972'. Displaced csg w/ pkr fluid. Set pkr @ 13964'. ND BOP & NU WH. 1/29/18: Performed MIT test to 400# for 30 minutes, held OK. Richard Inge w/NMOCD witnessed and took chart with him. Richard PWOL. | |
| PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB COMMENCE COMMINGLE COMMINGLE COMMINGLE COMMINGLE COMMINGLE COMMINGLE COMPL CASING/CEMENT JOB COMMINGLE COMMINGLE COMMINGLE COMPLETE COMPL COMPLETE COMPL CASING/CEMENT JOB COMPLETE CASING/CEMENT JOB CASING/CEMENT J | |
| TEMPORARILY ABANDON | |
| PULL OR ALTER CASING | |
| DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimate of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1/25/18: MIRU WS rig. ND WH & NU BOP. Released pkr & POOH w/ tbg. Changed out pkr. 1/28/18: RIH w/ 4 1/2" tbg to 13972'. Displaced csg w/ pkr fluid. Set pkr @ 13964'. ND BOP & NU WH. 1/29/18: Performed MIT test to 400# for 30 minutes, held OK. Richard Inge w/NMOCD witnessed and took chart with him. RIPWOL. | L |
| CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimate of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1/25/18: MIRU WS rig. ND WH & NU BOP. Released pkr & POOH w/ tbg. Changed out pkr. 1/28/18: RIH w/ 4 1/2" tbg to 13972'. Displaced csg w/ pkr fluid. Set pkr @ 13964'. ND BOP & NU WH. 1/29/18: Performed MIT test to 400# for 30 minutes, held OK. Richard Inge w/NMOCD witnessed and took chart with him. RIPWOL. | |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1/25/18: MIRU WS rig. ND WH & NU BOP. Released pkr & POOH w/ tbg. Changed out pkr. 1/28/18: RIH w/ 4 1/2" tbg to 13972'. Displaced csg w/ pkr fluid. Set pkr @ 13964'. ND BOP & NU WH. 1/29/18: Performed MIT test to 400# for 30 minutes, held OK. Richard Inge w/NMOCD witnessed and took chart with him. RIPWOL. | |
| of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1/25/18: MIRU WS rig. ND WH & NU BOP. Released pkr & POOH w/ tbg. Changed out pkr. 1/28/18: RIH w/ 4 1/2" tbg to 13972'. Displaced csg w/ pkr fluid. Set pkr @ 13964'. ND BOP & NU WH. 1/29/18: Performed MIT test to 400# for 30 minutes, held OK. Richard Inge w/NMOCD witnessed and took chart with him. RIPWOL. | |
| 1/28/18: RIH w/ 4 1/2" tbg to 13972'. Displaced csg w/ pkr fluid. Set pkr @ 13964'. ND BOP & NU WH. 1/29/18: Performed MIT test to 400# for 30 minutes, held OK. Richard Inge w/NMOCD witnessed and took chart with him. RV PWOL. | |
| 1/28/18: RIH w/ 4 1/2" tbg to 13972'. Displaced csg w/ pkr fluid. Set pkr @ 13964'. ND BOP & NU WH. 1/29/18: Performed MIT test to 400# for 30 minutes, held OK. Richard Inge w/NMOCD witnessed and took chart with him. RV PWOL. | |
| 1/29/18: Performed MIT test to 400# for 30 minutes, held OK. Richard Inge w/NMOCD witnessed and took chart with him. RI PWOL. | |
| PWOL. | |
| | DMO WS |
| If you have any questions please call Zane Anderson, (5/5) 390-3929. | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| I hereby certify that the information above is true and complete to the best of my knowledge and belief. | |
| SIGNATURE Latter TITLE Regulatory DATE 2/22/18 | |
| Type or print name Jackie Lathan E-mail address: _jlathan@mewbourne.com PHONE: _575-393-59 | |
| For State Use Only | |
| APPROVED BY: Declare / Ras TITLE COMPLIANTS OFFICE DATE 3/9/18 Conditions of Approval (if any): | <u> </u> |