Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT


FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-effective in abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2					5. Lease Serial No. NMNM100558 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No.	
Name of Operator Contact: CRYSTAL FULTON RKI EXPLORATION & PROD LLC E-Mail: crystal.fulton@wpxenergy.com					9. API Well No. 30-015-44477	
3a. Address 3500 ONE WILLIAMS CENTE TULSA, OK 74172	3b. Phone No. (include area code) Ph: 539-573-0218			10. Field and Pool or Exploratory Area PURPLE SAGE;WOLFCAMP(GAS		
4. Location of Well (Footage, Sec., T. Sec 16 T26S R30E 250FNL 1)			11. County or Parish, State EDDY COUNTY, NM		
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OI	FNOTICE	, REPORT, OR OTH	ER DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
☑ Notice of Intent ☐ Subsequent Report	☐ Acidize ☐ Alter Casing ☐ Casing Repair		DeepenHydraulic FracturingNew Construction		tion (Start/Resume) nation plete	☐ Water Shut-Off ☐ Well Integrity ☑ Other
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	-			☐ Temporarily Abandon ☐ Water Disposal	
13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for fi	ally or recomplete horizontally, rk will be performed or provide l operations. If the operation re pandonment Notices must be fil	give subsurface the Bond No. or sults in a multipl	locations and measure of file with BLM/BIA of completion or reco	red and true v Required su mpletion in a	rertical depths of all pertine absequent reports must be a new interval, a Form 3160	ent markers and zones. Filed within 30 days 1-4 must be filed once
ATTN: CHRIS WALLS & JENNIFER SANCHEZ						
RKI EXPLORATION & PROD WELL.	UCTION, LLC REQUEST	S TO PERFO		••		MENTIONED
Attached is our planned procedure, a new wellbore diagram, and a CBL/CCL which has been approved by Chris Walls.						
Submit subsequentreport to BLM MAR 1 2 2018 RECEXTED						18
14. I hereby certify that the foregoing is Name(Printed/Typed) CRYSTAL	Electronic Submission #	RATION & PR	DD LLC, sent to to JENNIFER SANC	h¢∕ Carlsbac	28/2018 ()	
Signature (Electronic S	<u> </u>		Date 02/27/2		PPROVED	\star
	THIS SPACE FO	OR FEDERA	L OR STATE	PFFICE L	GER 2 2018	Man
Approved By Conditions of approval, if any, are attached. Approval of this notice does			Title	BINE!	ATTE LANGUAGE	
certify that the applicant holds legal or equivalent would entitle the applicant to condu	Office	1 / 8	KEZRAD FIETO OF 191			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.U. Section 1212, make it a statements or representations as	crime for any pe to any matter w	erson knowingly and ithin its jurisdiction.	wilffully to n	nake to any department or	agency of the United

WPXENERGY

Tucker Draw Fed Com 9-4-1H Wellbore Diagram

Wolfcamp A Eddy County, NM API #: 30-015-44477 Rig Release Date: 02/09/2018



Date Prepared:

Jennifer Harris 10/9/2017



RKI Exploration & Production, LLC Tucker Draw 9-4 Fed Com 1H

Drilling Program Eddy County, NM

February 19, 2018

9-5/8" x 7" Remedial Squeeze

Objective: The objective is to remediate the TOC behind the 7" casing to at least 200-ft above the 9-5/8" casing shoe.

API #: 30-015-44477

Procedure

- 1. Notify BLM at least 4 hours prior to upcoming cement job.
- 2. MIRU Par Five Equipment
- 3. Record pressure on 7" casing and 9-5/8" \times 7" annulus. Bleed off pressure on 9-5/8" \times 7" annulus if any.
- 4. Tie into 2-1/16" 5K inlet valve on wellhead to pump down 9-5/8" x 7" annulus.
- 5. Test cement lines to 3,000 psi.
- 6. Establish injection rates at 2, 3, and 4 bpm with 50 bbls of freshwater. Record pressures at each rate.
 - a. Do not exceed 2,000 psi while pumping cement job. Set pump kick out at 2,000 psi.
 - b. Discuss with drilling superintendent/engineer if additional pressure is needed.
- 7. Pump 369 sx, 126 bbls of 35/65 Poz C with additives, mixed @ 12.9 ppg & 1.91 ft³/sk
- 8. Displace cement with 3 bbls of freshwater
 - a. Treat freshwater with corrosion inhibitor to protect casing
- 9. Open other 2-1/16" 5K inlet valve to 9-5/8" x 7" annulus and monitor to see if well is on vacuum.
 - a. Close both valves and shut well in if well is on a vacuum while monitoring
- 10. Record pump rates and pressures. Send data to engineer to be entered into Openwells.