Form 3160-5 (June 2015)

UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

	Expires, Jane
5.	Lease Serial No.
	NMNM92748

SUNDRY	NMNM92748							
Do not use the abandoned we	6. If Indian, Allottee or Tribe Name							
SUBMIT IN	7. If Unit or CA/Ag	greement,	Name and/or No.					
I. Type of Well ☑ Oil Well ☐ Gas Well ☐ Oth	8. Well Name and No. SERRANO FEDERAL 2							
Name of Operator EOG Y RESOURCES, INC.	9. API Well No. 30-015-29401		-					
3a. Address 104 SOUTH FOURTH STREE ARTESIA, NM 88210	o. (include area code 48-4168	•	10. Field and Pool of DAGGER DR	or Explor AW, UF	atory Area P, NORTH			
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)		12 112-	18	11. County or Paris	h, Statc		
Sec 11 T19S R25E NWSW 19	18 MOCD	EDDY COUN	TY, NM					
12. CHECK THE AF	PPROPRIATE BOX(ES) T	O INDICA	TE NATURE C	F NOTICE,	REPORT, OR O	THER I	DATA .	_
TYPE OF SUBMISSION								
Notice of Intent ■ Notice of Intent Notice of Inten	☐ Acidize	☐ Dee	pen	□ Product	ion (Start/Resume)	Ω,	Water Shut-Off	
_	☐ Alter Casing	☐ Hyd	Iraulic Fracturing	□ Reclam	ation	ο,	Well Integrity	
☐ Subsequent Report	□ Casing Repair	☐ Nev	v Construction	☐ Recomp	olete		Other	
☐ Final Abandonment Notice	☐ Change Plans	Plu	g and Abandon	on				
	☐ Convert to Injection	☐ Plu	g Back	☐ Water I	Disposal	_		
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi This well has valuable up hole this well and recomplete up ho MiT, contingency plan is to plu that the included plugging proof this well in the event of a failed	operations. If the operation resuland onment Notices must be filed nal inspection. recompletion potential. Refile in 2019 or 2020. Only refig and abandon this well incedure be reviewed and Colored.	alts in a multip I only after all equesting a equesting 2	le completion or reco requirements, include oproval to Tempo year TA status. following failed N	ompletion in a siding reclamation orarily Aband If well fails	new interval, a Form 3 n, have been complete	160-4 mi d and the	ist be filed once operator has	
EOG Y Resources, Inc. plans	to temporarily abandon this	s well as fol	lows:	S	EE ATTACH	IED I	FOR	
 MIRU any safety equipment RIH with GR/JB to 7470 ft. Set a CIBP at 7450 ft with 3 		g over open	ONDITIONS	6 OF	APPROVA	L		
perforations.	·	-			NM OI	I CO	NSERVATIO	N
MIT within 4	5 days of	appro	va (,				DISTRICT	. u
14. I hereby certify that the foregoing is	Electronic Submission #44	14024 verifie SOURCES,	d by the BLM We NC., sent to the	II Informatior Carlsbad	System	DEC 1	2 2018	_
Name (Printed/Typed) TINA HUE	Title REGUL	ATORY SPI	ECIALIST	REC	EIVED			
Signature (Electronic S	Date 11/14/2	018						
	THIS SPACE FOR	R FEDERA	L OR STATE	OFFICE U	SÉ			_
Approved By	ole. am		Title 5	1167			11-29-18 Date	=
Conditions of approval, if any, are attached ertify the the applicant holds legal or equivalent yould entitle the applicant to conduct	itable title to those rights in the si		Office	60		'		– سر
Fitle 18 U.S.C. Section 1001 and Title 43 t States any false, fictitious or fraudulent st				willfully to ma	ke to any department of	or agency	of the United	

(Instructions on page 2)

Additional data for EC transaction #444024 that would not fit on the form

32. Additional remarks, continued

4. Tag TOC. Load hole with plugging mud. 5. Conduct MIT and chart for the BLM & NMOCD.

6. NU WH and shut well in.

If well fails MIT, contingency plan is to plug and abandon this well immediately following failed MIT as follows:

1. MIRU all safety equipment as needed. Add Alug: Stot 35 sx cmf from 1065 - 6885(T/up).
2. Spot a 30 sx Class H cement plug from 6070 ft - 6230 ft. This will place a plug across Wolfcamp

3. Spot a 25 sx Class C cement plug from 3580 ft - 3730 ft. This will place a plug across Bone

Spring top.
4. Spot a 25 sx Class C cement plug from 2320 ft - 2470 ft. This will place a plug across Glorieta

5. Perforate at 1200 ft. Attempt to establish circulation.
6. Spot a 72 sx Class C cement plug from 770 ft - 1200 ft. This will place a plug across 9-5/8 inch casing shoe and San Andres.
7. Spot a 10 sx Class C cement plug from 60 ft up to surface.
8. Cut off wellhead and install dry hole marker. Clean location.

Wellbore schematics attached.

WELL NAME: Serrano Fed #2 FIELD: **CASING PROGRAM** LOCATION: 1980' FSL & 660' FWL Sec. 11-19S-25E GL: 3,450' ZERO: KB: 9 5/8" 36# J-55 1,150' COMMENTS: API No.: 30-015-29401 7° 26# & 23# 8,120' **Before** 14 3/4"Hole ~ **TOPS** San Andres 820' ' 2,420'~ Glorieta 9 5/8" Csg @ 1,150 Cmt'd w/ 1200sx (Circ) Bone Spring 3,680' Wolfcamp 6,182' ~ Canyon 7,652' 7580 Cisco 7015 Penn 7300 8 3/4" Hole Perfs: 7,496' - 7,778' Perfs; 7827-7836 Soz' (11-25.97) Not to Scale

7" Csg @ 8,120' Cmt'd w/ 1025sx (Circ) 6

PBTD: 8,120'

11/2/18

JΕ

WELL NAME: Serrano Fed #2 FIELD:


LOCATION: 1980' FSL & 660' FWL Sec. 11-19S-25E

GL: 3,450' ZERO: KB:

COMMENTS: API No.: 30-015-29401

CASING PROGRAM

1,150'	
8,120'	



8 3/4" Hole

TA After

TOPS

 San Andres
 820'

 Glorieta
 2,420'

 Bone Spring
 3,680'

 Wolfcamp
 6,182'

 Canyon
 7,652'

CIBP w/ 35' Class "H" cmt @ 7,450' Perfs: 7,496' - 7,778'

PBTD: 8,120'

7" Csg @ 8,120' Cmt'd w/ 1025sx (Circ)

Not to Scale 11/2/18 JE

WELL NAME: Serrano Fed #2 FIELD: LOCATION: 1980' FSL & 660' FWL Sec. 11-19S-25E	CASING PROGRAM	
GL: 3,450' ZERO: KB:	9 5/8" 36# J-55 1,150'	\exists
COMMENTS: API No.: 30-015-29401		
	7" 26# & 23# 8,120'	
-		
	s "C" cmt plug @ 60' – Surface P&A Afte	ľ
14 3/4"Hole	TOPS	
9 5/8" Csg @ 1,150 Cmt'd w/ 1200sx (Circ)	S "C" cmt plug @ 770' – (/8" Csg Shoe & SA Top) San Andres 820 Glorieta 2,420 Bone Spring 3,680 Wolfcamp 6,183 Canyon 7,65	o, O,
8 3/4" Hole 25sx Class "C"	" cmt plug @ 3,580' – 3,730' (BS Top)	
30sx Class "H"	" cmt plug @ 6,070' – 6,230' (WC Top)	
CIBP w/ 35' Cli Perfs: 7,496' ~	class "H" cmt @ 7,450' - 7,778'	

7" Csg @ 8,120' Cmt'd w/ 1025sx (Circ)

PBTD: 8,120'

Not to Scale 11/2/18

JΕ

BUREAU OF LAND ANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands **Conditions of Approval**

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

A procedure to repair the casing so that a TA approval can be granted. 1.

2. A procedure to plug and abandon the well.

NOI PEA Approved 11.29.18

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.