

Submit 1 Copy To Appropriate District Office  
 District I - (575) 393-6161  
 1625 N. French Dr., Hobbs, NM 88240  
 District II - (575) 748-1283  
 811 S. First St., Artesia, NM 88210  
 District III - (505) 334-6178  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV - (505) 476-3460  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Revised July 18, 2013

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

WELL API NO.	30-015-36004
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No.	36900
7. Lease Name or Unit Agreement Name	RDX 16
8. Well Number	001
9. OGRID Number	246289
10. Pool name or Wildcat	BRUSHY DRAW; DELAWARE, EAST
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	3,056' GR

**SUNDRY NOTICES AND REPORTS ON WELLS**  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well  Gas Well  Other

2. Name of Operator: RKI EXPLORATION & PRODUCTION, LLC

3. Address of Operator: 3500 ONE WILLIAMS CENTER MD 35  
TULSA, OK 74172

4. Well Location  
 Unit Letter O : 990 feet from the SOUTH line and 2310 feet from the EAST line  
 Section 16 Township 26S Range 30E NMPM EDDY County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
CLOSED-LOOP SYSTEM <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

RKI EXPLORATION & PRODUCTION, LLC RESPECTFULLY REQUESTS TO P&A THE ABOVE MENTIONED WELL.

THE WBD AND PROCESS ARE ATTACHED.

*See Comments to Procedure*

RECEIVED

JAN 14 2019

*Notify OCD 24 hrs. prior to any work done.*

DISTRICT II-ARTESIA O.C.D.

**ENTERED**  
 1-16-19

Spud Date: 01/16/2008

Rig Release Date: 02/29/2008

*\* See Attached COAs must be Plugged by 1/15/20*

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Caitlin O'Hair TITLE Regulatory Tech II DATE 01/10/2019

Type or print name Caitlin O'Hair E-mail address: caitlin.ohair@wpenergy.com PHONE: 539-573-3527

**For State Use Only**

APPROVED BY: [Signature] TITLE STAFF Mgr DATE 1/15/19

Conditions of Approval (if any):

**WPXENERGY**

KB: 3068.0'

GL: 3056.0'

Datum: 12.0' above GL

Spud: 01/16/2008  
Completed: 02/05/2008

13 3/8" (17 1/2" hole) 54.5# J-55 to 892'  
cmt'd w- 705 sxs. to surface

9 5/8" (12 1/4" Hole) 36# K-55 to 3,519'  
cmt'd w- 1503 sxs. to surface

5 1/2" (7 7/8" Hole) 17# J-55 to 7,580'  
cmt'd w- 900 sxs. to 2,870' (per CBL)

DV Tool: 5,131'


PBTD: 7,536'

**RDX '16' #1  
Current WB**

Les Peeler 01/09/2019

API No: 30-015-36004

Sec. 16, 26 S, 30 E.  
Eddy Co. New Mexico  
Brushy Draw/Delaware Field  
Grid # 246289  
GPS: 32.037862 -103.884584



Delaware 3,495'

Delaware: 6,321' - 6,359'

TD @7,580'

**WPXENERGY**

KB: 3068.0'

GL: 3056.0'

Datum: 12.0' above GL

Spud: 01/16/2008  
Completed: 02/05/2008

**RDX '16' #1  
Proposed Plugged WB**

Les Peeler 01/09/2019


API No: 30-015-36004

Sec. 16, 26 S, 30 E.  
Eddy Co. New Mexico  
Brushy Draw/Delaware Field  
Grid # 246289  
GPS: 32.037862 -103.884584

13 3/8" (17 1/2" hole) 54.5# J-55 to 892'  
cmt'd w- 705 sxs. to surface

9 5/8" (12 1/4" Hole) 36# K-55 to 3,519'  
cmt'd w- 1503 sxs. to surface

5 1/2" (7 7/8" Hole) 17# J-55 to 7,580'  
cmt'd w- 900 sxs. to 2,870' (per CBL)



Delaware 3,495'

Delaware: 6,321' - 6,359'

DV Tool: 5,131'

Spud 02/05/2008

Set CBL @ 2,870' (per CBL)

PBTD: 7,536'

TD @7,580'

les@peeleroilfield.com

# WPXENERGY.

## RDX "16" #1 Plug and Abandon Procedure Brushy Draw Delaware East Field

Section 16 T-26S, R-30E  
Eddy Co., New Mexico  
GPS: 32.037862 -103.884584

API # 30-015-36004  
OGRIG # 246289

**Spud Date:** 01/16/2008  
**TD Date:** 02/05/2008

**Producing Formations:**  
Delaware: 6,321' – 6,359'

**KB Elev:** 3068'  
**GL Elev:** 3056'  
**TD:** 7,580'  
**PBTD:** 7,536'  
**Marker Joint:** N/A

### CASING SUMMARY:

Safety Factor = 80% of new applied to burst, collapse and tension parameters in table.

Size	Depth (ft)	Weight (#/ft)	Grade psi	Connection Type	Capacity (bbls/ft)	ID (in)	Drift (in)	Burst (psi)	Collapse (psi)	Tension (lbs)
13 3/8"	1,000'	54.5 #	J-55	n/a	.1571	n/a	n/a	n/a	n/a	n/a
9 5/8"	3,429'	36 #	K-55	n/a	.0609	n/a	n/a	n/a	n/a	n/a
5 1/2"	7,580'	17 #	J-55	n/a	.0238	n/a	n/a	n/a	n/a	n/a

Surface: 13 3/8": 0'- 892'- TOC @ surface w-705 sxs

Production: 9 5/8" 0'- 3,519'- TOC @ surface 1,503 sxs.

Production 5 1/2": 0'- 7,580' - TOC @ 2,870' (per CBL) w- 900 sxs,

### COMPLETION HISTORY TO DATE:

**OBJECTIVE:** Plug and abandon.

**WPX REQUIRES THAT HARD HATS, STEEL TOE BOOTS, FIRE RETARDANT CLOTHING, AND SAFETY GLASSES BE WORN ON LOCATION.**

**HOLD SAFETY MEETING PRIOR TO COMMENCING PERFORATING, WIRE LINE AND PUMPING OPERATIONS**

**NO IGNITION SOURCES WITHIN 100 FT OF THE WELLHEAD, FLOWBACK TANKS OR MANIFOLD.**

**PROCEDURE:**

- 1) Test safety anchors and replace as necessary.
- 2) MIRU Service Unit.
- 3) NDWH - NUBOP
- 4) Tally tbg. OOH
- 5) MI RU wireline unit. Run 5 1/2" GR/JB to 6,221'.
- 6) RIH w- 5 1/2" tbg. & CIBP & set @ 6,221' - PU 1 jt. Circulate 150 bbls. heavy mud. Press. test csg. to 500#. Spot 25 sxs. Class "C" cmt. on top to 5,975'. *- WOC & Tag*
- 7) POOH & LD tbg. to 5,181'
- 8) Spot 25 sxs. from 5,181' to 5,031' (Over DVT @ 5,131') *- WOC & Tag*
- 9) POOH & LD tbg. to 3,569'.
- 10) Spot 35 sxs. cmt. from 3,569 to 3,345 (50' below shoe @ 3,519'). *- Perf @ 3569 & Attempt to Set WOC & Tag*
- 11) Stand back 942' tbg. & LD Rest.
- 12) Perf @ 942'.
- 13) RIH w- Pkr & tbg. - set Pkr. - Establish pump rate. Squeeze 70 sx Class C Cement (14.8 ppg, 6.3 gps, 1.32 cfs yield) from 942' - 792' (50' below shoe @ 892')
- 14) **WOC & Tag - Tag @ 792'.**
- 15) LD tbg.
- 16) RU WL & Perforate @ 150'.
- 17) Squeeze 110 sx Class C Cement (14.8 ppg, 6.3 gps, 1.32 cfs yield) from 150' to surface.
- 18) RDMO Service Unit. RDMO Cementers.
- 19) MIRU Welder. Cut-off casing head. WO cap with well name and number, operator name, and date.
- 20) Pull safety anchors, dress, and reclaim surface location if necessary.

**WPX Contact List:**

<b>WPX</b>	<b>Title</b>	<b>Ofc.</b>	<b>Cell</b>
Justin Warren	Production Superintendent	575-885-7525	701-421-7324
Steve Bernhardt	Permian Production Engineer	539-573-3548	918-671-0683
Brad Ballinger	Permian Production Engineer	539-573-0135	303-928-0799
Bailey Nett	Permian Production Engineer	539-573-2547	505-386-8974
Brittani Vegher	Permian Production Engineer		918-600-8645
Josh Walker	Regulatory Specialist	539-573-0108	580-716-0330
Les Peeler	Plugging Consultant	405-659-5185	405-318-4726

**Emergency Contacts – New Mexico:**

Hospital: Carlsbad Medical Center (575) 887-4100  
2430 W. Pierce St., Carlsbad, NM 88220

Sheriff's Office: Lea County Sheriff Dept (575) 396-3611  
Eddy County Sheriff Dept (575) 887-7551

**Emergency Contacts – Texas:**

Hospital: Reeves County Hospital (432) 447-3551  
2323 Texas St, Pecos TX 79772

Sheriff's Office: Reeves County Sheriff Dept (432) 445-4901  
Loving County Sheriff Dept (432) 377-2411

## CONDITIONS FOR PLUGGING AND ABANDONMENT

### District II / Artesia N.M.

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, **Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work.**

1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs.
2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
3. Trucking companies being used to haul oilfield waste fluids to a disposal – commercial or private – shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
6. If the well is not plugged within 1
7. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
8. **Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.**
9. Produced water **will not** be used during any part of the plugging operation.
10. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
11. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
12. **Class 'C' cement will be used above 7500 feet.**
13. **Class 'H' cement will be used below 7500 feet.**
14. **A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged**
15. **All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing**

16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
17. **A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.**
18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, **(WOC 4 hrs and tag).**
19. No more than **3000'** is allowed **between cement plugs in cased hole and 2000' in open hole.**
20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
  - A) Fusselman
  - B) Devonian
  - C) Morrow
  - D) Wolfcamp
  - E) Bone Springs
  - F) Delaware
  - G) Any salt sections
  - H) Abo
  - I) Glorieta
  - J) Yates.
  - K) **Potash---** (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, **WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.**
21. **If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing**

#### **DRY HOLE MARKER REQUIRMENTS**

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

**1. Operator name 2. Lease and Well Number 3.API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County (SPECIAL CASES)-----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS**

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)