


•			OCD Artesia				
Form 3160-5 (June 2015)	UNITED STATES DEPARTMENT OF THE IN BUREAU OF LAND MANAG	INTERIOR			FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				l	5. Lease Serial No. NMNM77046		
				6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agree	ement, Name and/or No.	
1. Type of Well Gas Well Other				8. Well Name and No. NORTH PURE GOLD 9 FEDERAL 5			
2. Name of Operator Contact: MAX LUBITZ DEVON ENERGY E-Mail: max.lubitz@dvn.com					9. API Well No. 30-015-27914		
3a. Address 333 WEST SHERIDAN A OKLAHOMA CITY, OK 7	3b. Phone No. (include area code) Ph: 5805020193CONSERVATIO			10. Field and Pool or I LOS MEDRANC	Exploratory Area DS, DELAWARE		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		JAN 3 1 2019		11. County or Parish, State			
Sec 9 T23S R31E Mer NMP 1140FNL 990FWL				2013	EDDY COUNTY, NM		
12 CHECK TH	E APPROPRIATE BOX(ES)				EPORT. OR OTH	IER DATA	
				·			
TYPE OF SUBMISSION		TYPE OF ACTION					
Notice of Intent	C Acidize	Deepen Pro		-	tion (Start/Resume)	□ Water Shut-Off	
Subsequent Report	Alter Casing	Hydraulic Fracture		Reclamation		Well Integrity	
	Casing Repair	-			. –		
Final Abandonment Notic	Change Plans	 Plug and Abandon Tempo Plug Back Water 		rarily Abandon			
 Set CIBP at 7900- Tag Spot 40 sx CI C 4100-5 Perf at 3935 Pump 40 	8" production tubing assembly . Spot 25 sx Cl C 7900-7800. 1950. WOC & tag. (T Delawar 0 sx Cl C from 3935 -700'. WC sx Cl C from 475'-375'. WOC sx Cl C in/out to surface. Set dry hole marker.	(open perfs at 7 e 4154, shoe 39 DC & tag. (R-11	1P Solid plug t) 3600, SG		
(well inside R-111P boundary. Salt section noted @ 74		S'-3885'GC Frecord ! NINC		SEE ATTACHED FOR			
LAT / LONG 32.323 -10	Accepted	10-		CONDITIONS OF APPROVAL			
Below ground	level dry hol	a marke	c requi	red.			
14. I hereby certify that the forego	Electronic Submission #	VON ENERGY s	ent to the Carls	sbad			
Name (Printed/Typed) MAX LUBITZ							
Signature (Electr	ignature (Electronic Submission) Date			ate 01/08/2019			
	THIS SPACE F	OR FEDERAL	OR STATE		JSE	· · · · · · · · · · · · · · · · · · ·	
Approved By	nes a. An		Title S	AET.		1-25-19 Date	
Conditions of approval, if any, are a certify that the applicant holds legal which would entitle the applicant to	or equitable title to those rights in th	e subject lease	Office LFC	2			
Title 18 U.S.C. Section 1001 and Tit		a crime for any pers s to any matter with	on knowingly and in its jurisdiction.	willfully to n	nake to any department o	r agency of the United	
(Instructions on page 2) ** OPE	RATOR-SUBMITTED ** C	PERATOR-S	UBMITTED *	* OPERA	Engles-		



۰ ,

•





BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Below Ground Level Cap (Lesser Prairie-Chicken Habitat)</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). **The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses.** Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>

8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u> From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted