
SUNDRY	UREAU OF LAND MANA NOTICES AND REPO	UU	D Artesia 5. Lease Serial No. NMLC028775	January 31, 2018	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.		6. If Indian, Allottee			
SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well Oil Well Oil Well Oil Well Oil Well Oil Well			7. If Unit or CA/Ag 8910123980	 If Unit or CA/Agreement, Name and/or 1 8910123980 Well Name and No. RJ UNIT 119 	
2. Name of Operator COG OPERATING LLC Contact: ABIGAIL ANDERSON E-Mail: abbym@bcmandassociates.com			9. API Well No. 30-015-03146	9. API Well No. 30-015-03146-00-S1	
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701		3b. Phone No. (include area code) Ph: 432-580-7161	10. Field and Pool of GRAYBURG	r Exploratory Area	
 Location of Well (Footage, Sec., T., R., M., or Survey Description, Sec 27 T17S R29E SWSE Tract 1 660FSL 1980FEL)	11. County or Paris	n, State	
			EDDY COUN	EDDY COUNTY, NM	
12. CHECK THE AF	PROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, REPORT, OR OT	THER DATA	
TYPE OF SUBMISSION	· · · ·	TYPE OF	ACTION		
D Notice of Intent	☐ Acidize	Deepen	Production (Start/Resume)	U Water Shut-	
Notice of Intent	Alter Casing	Hydraulic Fracturing	Reclamation	🗖 Well Integri	
Subsequent Report	Casing Repair	□ New Construction	□ Recomplete	Other	
Final Abandonment Notice	 Change Plans Convert to Injection 	🛛 Plug and Abandon 🗖 Plug Back	Temporarily Abandon Water Disposal		
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fin 1. Set 7" CIBP @ 2800'. Spot 2 2. Set 7" CIBP @ 2400'. Spot 2 MLF.	operations. If the operation re andonment Notices must be fil nal inspection. 25 sx cmt on top. Circula 25 sx cmt on top. Pressu	sults in a multiple completion or reco ed only after all requirements, includ te hole w/ MLF. re test cso, to 500 psi, Circula:	mpletion in a new interval, a Form 3 ng reclamation, have been complete re hole w/	160-4 must be filed on d and the operator has	
 following completion of the involved testing has been completed. Final Ab determined that the site is ready for final. Set 7" CIBP @ 2800'. Spot 2 	operations. If the operation re andonment Notices must be fil nal inspection. 25 sx cmt on top. Circula 25 sx cmt on top. Pressu 5 cm 747. Sc 6 WOC & Tag. 245 urface.	sults in a multiple completion or reco ed only after all requirements, includ te hole w/ MLF. re test csg. to 500 psi. Circular ' Z Cmt to leg (Shock T/salt)	mpletion in a new interval, a Form 3 ng reclamation, have been complete re hole w/	160-4 must be filed on d and the operator has	
following completion of the involved testing has been completed. Final Ab determined that the site is ready for final 1. Set 7" CIBP @ 2800'. Spot 2 2. Set 7" CIBP @ 2400'. Spot 2 MLF. Has Place Pare 3. Perf & Sqz 55 sx @ 420- 824 4. Perf & Sqz 45 sx @ 60' to si 5. Cut off wellhead and weld o	operations. If the operation re bandonment Notices must be fil nal inspection. 25 sx cmt on top. Circula 25 sx cmt on top. Pressu F 2 747. Sc 9 WOC & Tag. 245 wiface. n Below Ground Dry Hole Accepted for rec	sults in a multiple completion or reco ed only after all requirements, including the hole w/ MLF. re test csg. to 500 psi. Circular C = C + C + C + C + C + C + C + C + C +	mpletion in a new interval, a Form 3 ng reclamation, have been complete re hole w/	160-4 must be filed on d and the operator has South	
following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi 1. Set 7" CIBP @ 2800'. Spot 2 2. Set 7" CIBP @ 2400'. Spot 2 MLF. Fidd Phase 3. Perf & Sqz 55 sx @ 420- 220 4. Perf & Sqz 45 sx @ 60' to si 5. Cut off wellhead and weld o	operations. If the operation re- bandonment Notices must be fil nal inspection. 25 sx cmt on top. Circula 25 sx cmt on top. Pressu 25 sx cmt on top. Pressu 25 sx cmt on top. Pressu 25 sx cmt on top. Circula 25 sx cmt on top. C	sults in a multiple completion or reco ed only after all requirements, including the hole w/ MLF. re test csg. to 500 psi. Circular C = C + C + C + C + C + C + C + C + C +	mpletion in a new interval, a Form 3 ng reclamation, have been complete the hole w/ DEEATTACHED FC DNDITIONS OF A	160-4 must be filed on d and the operator has Sa(+) DR PPROVAL RECEIVED AUG 2: 1 2019	
following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi 1. Set 7" CIBP @ 2800'. Spot 2 2. Set 7" CIBP @ 2400'. Spot 2 MLF. Fidd Phase 3. Perf & Sqz 55 sx @ 420- 220 4. Perf & Sqz 45 sx @ 60' to si 5. Cut off wellhead and weld o	operations. If the operation re- bandonment Notices must be fil nal inspection. 25 sx cmt on top. Circula 25 sx cmt on top. Pressu 25 sx cmt on top. Pressu 25 sx cmt on top. Pressu 4 WOC & Tag. 243 wiface. n Below Ground Dry Hold C C C S Accepted for rest Electronic Submission # For COG C tted to AFMSS for process NDERSON	sults in a multiple completion or reco ed only after all requirements, includ te hole w/ MLF. re test csg. to 500 psi. Circular CShoc & T/satt) e Marker. Marker. 463657 verified by the BLM Well PERATING LLC, sent to the Ca sing by DEBORAH MCKINNEY c	mpletion in a new interval, a Form 3 ng reclamation, have been complete the hole w/ DEEATTACHED FOR DISTE	160-4 must be filed on d and the operator has Salt) DR PPROVAL RECEIVED AUG 2 1 2019	
following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi 1. Set 7" CIBP @ 2800'. Spot 2 2. Set 7" CIBP @ 2400'. Spot 2 MLF. Fidd. Phase , Perf 3. Perf & Sqz 55 sx @ 420- 22 4. Perf & Sqz 45 sx @ 60' to si 5. Cut off wellhead and weld o 14. I hereby certify that the foregoing is Commi Name(<i>Printed/Typed</i>) ABIGAIL A	operations. If the operation re- bandonment Notices must be fil nal inspection. 25 sx cmt on top. Circula 25 sx cmt on top. Pressu 25 sx cmt on top. Pressu 25 sx cmt on top. Pressu 25 sx cmt on top. Circula 25 sx cmt on top. Circula 25 sx cmt on top. Circula 25 sx cmt on top. Circula 26 WOC & Tag. 24 9 WOC & Tag. 24	sults in a multiple completion or reco ed only after all requirements, includ te hole w/ MLF. re test csg. to 500 psi. Circular Choc & T/satt) e Marker.	mpletion in a new interval, a Form 3 ng reclamation, have been complete the hole w/ DE ATTACHED FO DNDITIONS OF A Information System rlsbad n 05/01/2019 (19DLM0457SE)	160-4 must be filed on d and the operator has Salt) DR PPROVAL RECEIVED AUG 2 1 2019	
following completion of the involved testing has been completed. Final Ab determined that the site is ready for fit. 1. Set 7" CIBP @ 2800'. Spot 1 2. Set 7" CIBP @ 2400'. Spot 1 MLF. His Place 3. Perf & Sqz 55 sx @ 420-324 4. Perf & Sqz 45 sx @ 60' to si 5. Cut off wellhead and weld o 14. 1 hereby certify that the foregoing is Commini Name (Printed/Typed) ABIGAIL A Signature (Electronic S)	operations. If the operation re- bandonment Notices must be fil nal inspection. 25 sx cmt on top. Circula 25 sx cmt on top. Pressu 25 sx cmt on top. Pressu 25 sx cmt on top. Pressu 25 sx cmt on top. Circula 25 sx cmt on top. Circula 25 sx cmt on top. Circula 25 sx cmt on top. Circula 26 WOC & Tag. 24 9 WOC & Tag. 24	sults in a multiple completion or reco ed only after all requirements, includ te hole w/ MLF. re test csg. to 500 psi. Circular Chock T/satt e Marker.	mpletion in a new interval, a Form 3 ng reclamation, have been complete the hole w/ DE ATTACHED FO DNDITIONS OF A Information System rlsbad n 05/01/2019 (19DLM0457SE)	160-4 must be filed on d and the operator has South DR PPROVAL RECEIVED AUG 2: 1 2019	
following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi 1. Set 7" CIBP @ 2800'. Spot 2 2. Set 7" CIBP @ 2400' Spot 2 MLF. Fidd. Phag. Perf 3. Perf & Sqz 55 sx @ 420- 22 4. Perf & Sqz 45 sx @ 60' to si 5. Cut off wellhead and weld o 14. I hereby certify that the foregoing is Name(<i>Printed/Typed</i>) ABIGAIL A	operations. If the operation re- bandonment Notices must be fil nal inspection. 25 sx cmt on top. Circula 25 sx cmt on top. Pressu 25 sx cmt on top. Pressu 25 sx cmt on top. Pressu 25 sx cmt on top. Pressu 26 WOC & Tag. 24 urface. n Below Ground Dry Hole Control	sults in a multiple completion or reco ed only after all requirements, includ te hole w/ MLF. re test csg. to 500 psi. Circular (Shock T/satt) e Marker. /22/19 Store Marker. /22/19 Second To Second Sing by DEBORAH MCKINNEY of Title AGENT Date 05/01/20 Date 05/01/20 Date Circular Title Circular	mpletion in a new interval, a Form 3 ng reclamation, have been complete the hole w/ DE ATTACHED FO DNDITIONS OF A Information System rlsbad n 05/01/2019 (19DLM0457SE)	160-4 must be filed on d and the operator has S=1+ DR PPROVAL RECEIVED AUG 2 1 2019 NCTHARTESIA	
following completion of the involved testing has been completed. Final Ab determined that the site is ready for fit 1. Set 7" CIBP @ 2800'. Spot 1 2. Set 7" CIBP @ 2400'. Spot 1 MLF. Hue. 3. Perf & Sqz 55 sx @ 420-324 4. Perf & Sqz 45 sx @ 60' to si 5. Cut off wellhead and weld o 14. 1 hereby certify that the foregoing is Comminion Name (Printed/Typed) ABIGAIL A Signature (Electronic S) Approved By Conditions of approval, if any, are attached certify that the applicant holds legal or equipiers	operations. If the operation re- bandonment Notices must be fil- nal inspection. 25 sx cmt on top. Circula 25 sx cmt on top. Pressu 25 sx cmt on top. Pressu 25 sx cmt on top. Pressu 26 WOC & Tag. 245 urface. n Below Ground Dry Hold Compared for rest Accepted for rest true and correct. Electronic Submission # For COG C tted to AFMSS for process NDERSON Ubmission) THIS SPACE FC Accepted for rest NDERSON	sults in a multiple completion or reco ed only after all requirements, includ te hole w/ MLF. re test csg. to 500 psi. Circular (Shock T/satt) e Marker. /22/19 Stord • MMOCD 463657 verified by the BLM Well PERATING LC, sent to the Ca sing by DEBORAH MCKINNEY of Title AGENT Date 05/01/20 Date 05/01/20 DR FEDERAL OR STATE (mpletion in a new interval, a Form 3 ng reclamation, have been complete the hole w/ CEATTACHED FO DNDITIONS OF A Information System risbad n 05/01/2019 (19DLM0457SE) DISTR 019 DFFICE USE	160-4 must be filed on d and the operator has Soci-t-) DR PPROVAL RECEIVED AUG 2 1 2019 NCTHARTESIAC	



4/25/2019

RJ Unit # 119 Wellbore diagram (2)

SH

COG Operating LLC

Lease & Well # RJ Unit #119 Spud: 3/5/47 Elevation - 3556' 1 Partie SEZ 35 SAC 60'-Surface [Top of cmt est 120' fs 8 5/8" csg @ 368, 50 sx cmt. (3) Ref : Sq2 55 5x @ 420 - 320. WOL TAS ___Top of cmt est @ 1,000' fs. 75 jts 2 3/8" ICC & IPC tbg Baker tandem tension pkr - 2349' 5 jts nickel ctd tbg -2' sub, nickel ctd-San Andres (3 7" CIBPE 2400' -/ 25-5x 7 jts nickel ctd tbg -2464-2506 Acidized w/750 gal 15% HCL, converted to injection well. (8/1973) **Squeezed off with 600 sx, 11/14/91. Baker lok-set pkr. - 2733' () 7' CIBPO 2800 U/ 25'5X 7" csg @ 2829'. Cmt w/100 sx San Andres OH 2768 - 2975'. Acidized 2000 gal HCL, re-acidized w/4,000 gal 15% HCL 2 3/8" ICC & IPC tbg @ 2948 PBTD- 2952' Hydromite plug 6" OH to 3014'

RJ Unit # 119 Wellbore diagram (2)

32.8000679

-104:0604553

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure'to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>minety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.