Form	3160-5
(June	2015)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

**OCD** Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

Expires: January	
Lease Serial No.	
NMLC065347	

SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter an	
bandoned well. Use form 3160-3 (APD) for such proposals	;.

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. SW93			
Type of Well					8. Well Name and No. WCPN GASCOM UT2 2			
2. Name of Operator Contact: RICKY VILLANUEVA CHEVRON USA INCORPORATED E-Mail: ryqg@chevron.com					9. API Well No. 30-015-00398-00-S1			
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706  3b. Phone No. (include area code) Ph: 432-687-7786					10. Field and Pool or Exploratory Area WHITE CITY-WOLFCAMP			
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description	)			11. County or Parish,	State	· · · · · · · · · · · · · · · · · · ·	
Sec 20 T24S R26E SWNE 2400FNL 2444FEL					EDDY COUNTY, NM			
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTI	HER I	DATA	
TYPE OF SUBMISSION			TYPE OF	ACTION				
	☐ Acidize	☐ Dee	oen	☐ Producti	on (Start/Resume)		Water Shut-Off	
Notice of Intent	Notice of Intent			raulic Fracturing    Reclamation			☐ Well Integrity	
☐ Subsequent Report	☐ Casing Repair		Construction	☐ Recomp	lete		Other	
☐ Final Abandonment Notice	☐ Change Plans	_	and Abandon		rily Abandon	_		
	☐ Convert to Injection	☐ Plug		☐ Water D	•			
determined that the site is ready for f  1. MI&RU. 2. Set CIBP @ 9460. Pressur 3. Spot 30 sx H cmt from 9466 4. Spot 100 sx H cmt from 828 5. Perf and squeeze 80 sx C c 6. Perf and squeeze 50 sx C c 7. Perf and squeeze 110 sx C 8. Perf and squeeze 170 sx C 9. Cut all casings & anchors & marker as per, NMOCD requir	e test @ 1000 psi for 10 i b' to 9256? (Perfs,Pennsy 33' to 7803?(Bone Spring cmt from 5290? to 5040? cmt from 2617? to 2461? cmt from 1720? to 1376? cmt from 530? to Surface remove 3? below grade	rlvanion) WO0, Wolfcamp) (Bone Spring (Cherry Cany (Lamar, Bell	Shoe) WOC-Ta on) WOC-Tag Canyon) WOC- ut to surface & w	g Tag eld on dry ho EE ATT	IONS OF A	)R PPR		
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #	486884 verifie	d by the BLM Wel	I Information	System	ART	CONSERVATION ESIA DISTRICT	
	For CHEVRON U itted to AFMSS for process ILLANUEVA			on 10/08/2019	(20DLM0018SE) TORNEY IN FACT	00	2 1 2019	
					٠,		CCETI IEE	
Signature (Electronic S	Submission)		Date 10/07/2	019		<u>.</u>	ECEIVED	
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE US	SE		<del></del>	
Approved By James	x a. Cimos		Title SF	KT			10-12-19 Date	
Conditions of approval of any, are attache ertify that the applicant holds legal or equivalent to conduct the applicant to conduct the conduction of the con	itable title to those rights in the		Office [F	2				
Fitle 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it a	crime for any pe	rson knowingly and	willfully to ma	ke to any department or	agency	of the United	

## White City Penn Gas Com Unit 2 #2 Wellbore Diagram

Created:         11/05/07 Updated:         By:         White City Penn Gas Com Unit 2           Lease:         Field:         White City Penn           Surf. Loc.:         2,400' FNL & 2,444' FEL           Bot. Loc.:         County:           Status:         Active Gas Well	C. A. Irle Yifan Li	Well #: API Surface Unit Ltr.: Bottom hole Unit Ltr.: Cost Code: Chevno:	2 Fd./St. #: LC065347 30-015-00398  Tshp/Rng: S-24 & E-26 G Section: 20  Tshp/Rng: Section: UCU970200 FC1142
Surface Casing   Size:	8" Well Head for 7"	Casing!	KB: Unknown DF: Unknown GL: 3,379 Ini. Spud: 05/09/60 Ini. Comp.: 08/30/60  Perf & squeeze 170 sx of Class C CMT f/ 530' to Surface (WB, Shoe)  Perf & squeeze 110 sx of Class C CMT f/ 1720' to 1376' (Lamar, Bell Canyon) WOC-Tag Perf & squeeze 50 sx of Class C CMT f/ 2617' to 2461' (Cherry Canyon) WOC-Tag  Perf & squeeze 80 sx of Class C CMT f/ 5290' to 5040' (Bone Spring, Shoe) WOC-Tag
Strawn   9,692	9560 9567 9570 9575 9820 9830		Spot 100 sx of Class H CMT f/ 8283' to 7803' (Bone Spring, Wolfcamp) Spot 30 sx of Class H CMT f/ 9400' to 9256' Pressure Test @ 1000 psi for 10 minutes (Pennsylvanian) Set CIBP @ 9400'  History  Drilling: Gas kick 9070. 9.3 to 11.3# mud. 830/60 Ini Comp: Perf 4 spf 10338-342, 367-371, 11112-116, 131-135, 334-338. RBP 11355, pkr 11271, acid 1000 gis MCA, RBP 11150, pkr 11068, acid 1000 gis MCA, RBP 11150, pkr 11050, pkr 10271, acid 1000 gis. swab. RBP 11150, pkr 11029, acid 2000 gis 15%, 30 8S, wtr. RBP 11355, pkr 11271, acid 2000 gis 15%, gas, tog part, fish is 16' tbg, SN, pkr, 74' tbg & RBP 8 11150, not ret. CIBP 10000, cmt 9940, perf 2 spf
Perforations 9050-85, 9661-66, 9826-49, 66-74, 78-84, 10033-040, 081-088, 129- 130, 338-342, 367-371, 374-378, 884-890, 973-980, 984-982, 11066-	9661 9670 96770 96773 96775 96776 9678 96900 96900 96900 96900 96900 96000 96000 96000 96000 96000 96000 96000 96000 9		9050-85, RBP 9105, pkr 9021. acid 1000 gls 15% MCA. com, flow, perf 4 jnif 9828-34, 40-42, 70-74, pkr 9112, 2.78 lbg ihru pkr 9911, BHA, J Snap Set pkr 9040, 2.38 to pkr 9042, acid lwr 1500 gls 15% MCA, flow. 126/80 Stim: L0 2.38, rerun 2.78, acid 18000 gls 15% MS 2.5 85, BHA. 120/71 Acid: 500 gls 15%, swab. 1/20/71 Acid: 500 gls 15%, swab. 1/20/71 Acid: 500 gls 15%, swab. 1/27/71 Acid: 500 gl
071, 074-078, 090-095, 112-116, 131-135, 334-338  **Tubing Detail** 10" 2 7/8" Sub, 8" 2 7/8" Sub, 6" 2 7/8" Sub, 29 7 Jts. 2 7/8" Sub, 6" 2 7/8" Sub, 297 Jts. 2 7/8" S.#L-80 Tubing, 2 7/8" X 3 1/2" XO, O/O w/2.25" F Profile, Weatherford Arrow Pak Packer @ 9,500", 8" 3 1/2" 9.3# L-80 Sub, 2.25" R Profile Nipple, WLEG @ 9520	PBTD: 11,263 TD: 11,419		9620-30, pkr 9500 wBP, run frac string, ret BP, acid 2000 gls (SW pad, 40# after) 48k# 30/50 econoprop, flow, set BP, ret frac string, run 2 7/8, ret BP, NOTE: Packer Release Requires Weatherford Plucking Tool!  **FISH Detail** 15° 2 36° 4.6# L-80 Tubing wBumper Spring @ Bottom, Oxforf Tool, Baker Model D Pkr wt/1.87* Profile Nipple, 10° 2 3/8° Tubing Sub, 1.822° R Seat Nipple w/No-Go

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.