Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia NOV 0 5 2019

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018


Lease Serial No. NMNM14118

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such in the subject of the such in the subject of the such in the subject of the subject o

6. If Indian, Allottee or Tribe Name

		-) Giğil		egian'r').		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.		
Type of Well Oil Well				8. Well Name and No. ALLISON CQ FEDERAL 9			
Name of Operator Contact: JEREMY HAASS EOG RESOURCES INCORPORATEDE-Mail: jeremy_haass@eogresources.co				9. API Well No. 30-015-24133			
3a. Address	3b. Phone No. (inclu	. (include area code)		10. Field and Pool or Exploratory Area			
104 SOUTH FOURTH STREET ARTESIA, NM 88210		Ph: 575-748-43 <i>°</i> 	575-748-4311		UNDESIGNATED CISCO		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
Sec 15 T19S R24E NWNW 99					EDDY COUNTY, NM		
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICATE N	ATURE O	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					· · · · · · · · · · · · · · · · · · ·	
Notice of Intent ■	☐ Acidize	Deepen		☐ Product	ion (Start/Resume)		
☐ Alter Casing		☐ Hydraulic Fracturing ☐ Recla		□ Reclama	ation	■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair ☐ Ne		struction	□ Recomp	olete	Other	
Final Abandonment Notice	□ Change Plans	Plug and A	Plug and Abandon		arily Abandon		
	☐ Convert to Injection	☐ Plug Back	Plug Back		Disposal		
following completion of the involved testing has been completed. Final Ab determined that the site is ready for final Ab determined that the site is ready for final Ab determined that the site is ready for final Ab determined that the site is ready for final Ab determined that the site is ready for final Ab determined that the site is ready for final Ab determined at 25 SX (362 ft) CLS (Wolfcamp. 4. Perforate at 3883 ft. Attempt C cement plug 3745 ft. Attempt C cement plug 3133 ft. Attempt	andonment Notices must be filinal inspection. as needed. NU BOP. PO ft-of-CLS H-on-top. C cement plug 4714 ft - 5 pt to establish Circulation ft. WOC & Tag Plug. Thi at to establish Circulation ft. WOC & Tag Plug. Thi pt to establish Circulation pt to establish Circulation ft. WOC & Tag Plug. Thi pt to establish Circulation pt to establish Circulation pt true and correct. Electronic Submission #	ed only after all required only after all required only after all required on the second of the seco	ernents, included a equipment of Plug. This res 38 SX (energy) ares 32 SX (energy) he BLM We	it. s will plug the (138 ft) CLS (118 ft) CLS	e Accepted for I	CFS ead NMOCD	
For EOG RESOURCES INCORFORATED, sent to the Carlsbad							
Name (Printed/Typed) JEREMY HAASS			KEGUL	ATORY SP	ECIALIS I		
Signature (Electronic S	Submission)	Date	10/18/2	2019			
	THIS SPACE FO	OR FEDERAL O	R STATE	OFFICE U	SE		
Approved By	a. am	⊘ Titl	. SX	167		1/-1-19 Date	
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to condu	uitable title to those rights in th	s not warrant or		to			
Fitle 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it a				ake to any department or	agency of the United	

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **






Additional data for EC transaction #488800 that would not fit on the form

32. Additional remarks, continued

C cement plug 1714 ft - 1832 ft. WOC & Tag Plug. This will plug the Glorieta

165

- 7. Perforate at 972 ft. Attempt to establish Circulation or spot I/O. Requires 25 SX (362 ft) CLS C cement plug 610 ft 972 ft. WOC & Tag Plug. This will plug the Shoe
- 8. Perforate at 136 ft. Attempt to establish Circulation or spot I/O. Requires 28 SX (104 ft) CLS C cement plug 32 ft 136 ft. WOC & Tag Plug. This will plug the San Anders Add, Ferf & 406 Soz ent 306 Shoe work Tag
- 9. Spot a 10 SX (145 ft) CLS C cement plug 0 ft 145 ft. WOC & Tag Plug. This will plug the Top. 10. Cut off wellhead and weld on dry hole marker. Clean location as per regulation.



API: 30-015-24133 Sec-TWN-RNG: D-15-19S-24E **ALLISON CQ FEDERAL #009** GL: 3691 FOOTAGES: 990 FNL 1300 FWL DESCRIPTION. KB: 12 Proposed COMMENTS CASING DETAIL # HOLE SIZE SIZE WGHT GRADE Top Bottom Sx Cmt Circ/TOC TOC Method 17 1/2 13 3/8 54.5 0 356 350 circ 12 1/4 0 В 8 5/8 24 922 500 Circ 7 7/8 4.5 10.5 & 11.6 0 9000 1475 4620 CBL FORMATION TOPS Formation Top San Anders 448 1782 Glorieta Tubb 3215 X 3833 Abo х 5 Wolfcamp 5026 6264 Cisco X 7366 Plugged Canyon Strawn 8043 Plugged 8399 Plugged Atoka 8662 Plugged Morrow 8875 Plugged THE PARTY Plugs 1 Set CIBP at 6352 ft with 35 ft of CLS H on top. Spot a 25 SX (362 ft) CLS C cement plug 4714 ft - 5076 ft. WOC & Tag Plug. This will plug the Wolfcamp. Perforate at 3883 ft. Attempt to establish Circulation or spot I/O. Requires 38 SX (138 ft) CLS C cement plug 3745 ft - 3883 ft, WOC 8 Tag Plug. This will plug the Abo Perfoate at 3265 ft. Attempt to establish Circulation or spot I/O, Requires 36 SX (132 ft) CLS C cement plug 3133 ft - 3265 ft. WOC & Tag Plug. This will plug the Tubb Perforate at 1832 ft. Attempt to establish Circulation or spot I/O. Requires 32 SX (118 ft) CLS C cement plug 1714 ft - 1832 ft. WOC 8 Perforate at 972 ft, Attempt to establish Circulation or spot I/O. Requires 25 SX (362 ft) CLS C cement plug 610 ft - 972 ft. WOC & Perforations 6 Tag Plug. This will plug the Shoe Perforate at 136 ft. Attempt to establish Circulation or spot I/O. Requires 28 SX (104 ft) CLS C cement plug 32 ft - 136 ft. WOC & Tag 6402 - 6462 Plug. This will plug the San Anders Spot a 10 SX (145 ft) CLS C cement plug 0 ft - 145 ft. WOC & Tag Plug. This will plug the Top. CIBP 7400' + 35 sx cmt 7494-7774 CIBP 8700' + 35 sx cmt 8733-8739 PBTD: MD TD: MD

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>minety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement</u>: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.