
	UNITED STATE		OCD Art	1	O	DRM APPROVED MB No. 1004-0137
	PARTMENT OF THE I				5 Longo Sorial Na	ires: October 31, 2021
SUNDRY	NOTICES AND REPO	RTS	IGTY-ARTE	SIAO.C	D. 6. If Indian, Allottee or	A 14768-B
Do not use this	form for proposals t	o arili or to	re-enter an			The Maine
	Use Form 3160-3 (A			•	7. If Unit of CA/Agree	ment, Name and/or No.
. Type of Well	TRIPLICATE - Other instru	ctions on page	2			
Oil Well Gas					8. Well Name and No.,	WILDERSPIN #3
2. Name of Operator SOUTHWEST ROYALTIES, INC.					9. API Well No. 30-015-25501	
3a. Address P.O. BOX 53570 3b. Phone No. MIDLAND, TEXAS 79710 (432) 207-30:			· / / / ·		0. Field and Pool or Exploratory Area FENTON; DELLLAWAREEE, NORTHWEST	
4. Location of Well (Footage, Sec., T.R.,M., or Survey Description) 1650' FNL & 660' FEL, H, SEC, 11, T-21S, R-27E			11. Country or Parish, EDDY COUNTY, N		11. Country or Parish, EDDY COUNTY, N	
	ECK THE APPROPRIATE B	DX(ES) TO IND	ICATE NATURE	OF NOTI	L	
TYPE OF SUBMISSION				PE OF AC		
Notice of Intent	Acidize	Deepe	n		uction (Start/Resume)	Water Shut-Off
	Alter Casing		ulic Fracturing	_	amation omplete	Well Integrity
Subsequent Report	Casing Repair		ind Abandon		porarily Abandon	Uner Other
Final Abandonment Notice	Convert to Injection	Plug I	Back	Wate	er Disposal	
completion of the involved operat completed. Final Abandonment N is ready for final inspection.) NOTICE OF INTENET TO PL	ions. If the operation results in otices must be filed only after UG AND ABANDON	a inultiple com all requirements ccepted for t	pletion or recomp	oletion in a nation, hav	new interval, a Form 3 e been completed and the SEE ATT	st be filed within 30 days following 160-4 must be filed once testing has been the operator has detennined that the site CACHED FOR IONS OF APPROV
completion of the involved operat completed. Final Abandonment N is ready for final inspection.) NOTICE OF INTENET TO PL 1. RU WELL SERVICE UNIT. 2. NU BOP. UNSEAT ANCHO 3. RU WIRELINE. SET CIBP 4. TIH W/ OPEN ENDED 2-7/ 5. WOC EOP 4 HBS TOG TO	ions. If the operation results in otices must be filed only after UG AND ABANDON POH LD RODS AND PUM IR, TOH W/ 2-7/8" TBG. @ 2000 '. 2.800 - 2 8" TBG. TAG CIBP. CIRCL IP OF CMT	n a multiple com all requirements ccepted for t P. P.	pletion or recomp including reclan fectoral NM (50 - 100 VI 10# GELLED	OCD CD BRINE. S	new interval, a Form 3: e been completed and th SEE ATT CONDIT re greater for port 35 SX CLASS (ACHED FOR IONS OF APPROV
completion of the involved operat completed. Final Abandonment N is ready for final inspection.) NOTICE OF INTENET TO PL 1. RU WELL SERVICE UNIT. 2. NU BOP. UNSEAT ANCHO 3. RU WIRELINE. SET CIBP 4. TIH W/ OPEN ENDED 2-7/ 5. WOC EOP 4 HBS TOG TO	ions. If the operation results in otices must be filed only after UG AND ABANDON POH LD RODS AND PUM OR, TOH W/ 2-7/8" TBG. @ 2600'. 2.800 - 2.2 B" TBG. TAG CIBP. CIRCL OP OF CMT. OLES AT 1800'. SQUEEZI CULATE CLASS C CMT T I. INSTALL BELOW GROU E EQUIPMENT INCLUDING FROM LOCATION AND R ORK USING A STEEL PIT.	A a multiple com all requirements Crepted for 1 P. SCATE HOLE V E 50 SXS CLAS O SURFACE. ND LEVEL DR 3 ELECTRIC P OAD. PREPAR	pletion or recomp including reclan fectoral NM (50 - 100 VI 10# GELLED	COR REG	new interval, a Form 3 e been completed and the SEE ATT CONDIT (CONDIT) (CONT) (160-4 must be filed once testing has been the operator has detennined that the site CACHED FOR IONS OF APPROV
completion of the involved operat completed. Final Abandonment N is ready for final inspection.) NOTICE OF INTENET TO PL 1. RU WELL SERVICE UNIT. 2. NU BOP. UNSEAT ANCHO 3. RU WIRELINE. SET CIBP 4. TIH W/ OPEN ENDED 2-7/ 5. WOC FOR 4 HRS. TAG TO 6. PERFORATE SQUEEZE H 7. PERFORATE SQUEEZE H 7. PERFORATE SQUEEZE H 7. PERFORATE AT 300°. CIR 8. ND BOP. CUT WELLHEAD 9. MOVE OUT ALL SURFACE 10. REMOOOOVE CALICHE ** NO SURFACE PIT. ALL WA 4. 1 hereby certify that the foregoing	ions. If the operation results in otices must be filed only after UG AND ABANDON POH LD RODS AND PUM OR, TOH W/ 2-7/8" TBG. @ 2600'. 2.800 - 2.2 B" TBG. TAG CIBP. CIRCL OP OF CMT. OLES AT 1800'. SQUEEZI CULATE CLASS C CMT T I. INSTALL BELOW GROU E EQUIPMENT INCLUDING FROM LOCATION AND R ORK USING A STEEL PIT.	A a multiple com all requirements Crepted for 1 P. SCATE HOLE V E 50 SXS CLAS O SURFACE. ND LEVEL DR 3 ELECTRIC P OAD. PREPAR	REGULA	COR REG	new interval, a Form 3 e been completed and the SEE ATT CONDIT (CONDIT) (CONT) (160-4 must be filed once testing has been the operator has detennined that the site CACHED FOR IONS OF APPROV COMT. 438. Tay Arrie & To 358. Tay (SLO EQUIREMENTS. 0 150 SQZ TO
completion of the involved operat completed. Final Abandonment N is ready for final inspection.) NOTICE OF INTENET TO PL 1. RU WELL SERVICE UNIT. 2. NU BOP. UNSEAT ANCHO 3. RU WIRELINE. SET CIBP 4. TIH W/ OPEN ENDED 2-7/ 5. WOC FOR 4 HRS. TAG TO 6. PERFORATE SQUEEZE H 7. PERFORATE SQUEEZE H 7. PERFORATE SQUEEZE H 7. PERFORATE AT 300°. CIR 8. ND BOP. CUT WELLHEAD 9. MOVE OUT ALL SURFACE 10. REMOOOOVE CALICHE *** NO SURFACE PIT. ALL WA 4. I hereby certify that the foregoing .INDSAY LIVESAY	ions. If the operation results in otices must be filed only after UG AND ABANDON POH LD RODS AND PUM PR, TOH W/ 2-7/8" TBG. 2000'. 2.800 - 2.2 B" TBG. TAG CIBP. CIRCL P OF CMT. OLES AT 1800'. SQUEEZI CULATE CLASS C CMT T . INSTALL BELOW GROU E EQUIPMENT INCLUDING FROM LOCATION AND R DRK USING A STEEL PIT.	a a multiple com all requirements cepted for 1 P. JLATE HOLE V E 50 SXS CLAS O SURFACE. ND LEVEL DR G ELECTRIC P OAD. PREPAR	REGULAT	OCD CCD BRINE.S C 4 HRS. C 4 HRS. C 4 HRS. C 7 HRS	new interval, a Form 3: e been completed and the SEE ATT CONDIT is port 35 SX CLASS (TAG CMT. SOZ ROWTH PER BLM R ALYST 09/13/2	160-4 must be filed once testing has been the operator has detennined that the site CACHED FOR IONS OF APPROV COMT. 438. Tay Arrie & To 358. Tay (SLO EQUIREMENTS. 0 150 SQZ TO
completion of the involved operat completed. Final Abandonment N is ready for final inspection.) NOTICE OF INTENET TO PL 1. RU WELL SERVICE UNIT. 2. NU BOP. UNSEAT ANCHO 3. RU WIRELINE. SET CIBP 4. TIH W/ OPEN ENDED 2-7/ 5. WOC FOR 4 HRS. TAG TO 6. PERFORATE SQUEEZE H 7. PERFORATE SQUEEZE H 7. PERFORATE SQUEEZE H 7. PERFORATE AT 300°. CIR 8. ND BOP. CUT WELLHEAD 9. MOVE OUT ALL SURFACE 10. REMOOOOVE CALICHE *** NO SURFACE PIT. ALL WA 4. I hereby certify that the foregoing .INDSAY LIVESAY	ions. If the operation results in otices must be filed only after UG AND ABANDON POH LD RODS AND PUM PR, TOH W/ 2-7/8" TBG. @ 2600'. 2.800 - 2.3 B" TBG, TAG CIBP. CIRCL OP OF CMT. OLES AT 1800'. SQUEEZI CULATE CLASS C CMT T INSTALL BELOW GROU EQUIPMENT INCLUDING FROM LOCATION AND R ORK USING A STEEL PIT.	a multiple com all requirements crepted for t P. JLATE HOLE V E 50 SXS CLAS O SURFACE. ND LEVEL DR G ELECTRIC P OAD. PREPAR	pletion or recomp including reclan including reclan including reclan including reclan including reclan including reclan including recland including recland	OCD CCD BRINE.S C 4 HRS. C 4 HRS. C 4 HRS. C 7 HRS	new interval, a Form 3 e been completed and the SEE ATT CONDIT is port 35 SX CLASS (TAG CMT. SOCZ TO SCOZ ROWTH PER BLM R ALYST 09/13/2 FICE USE	160-4 must be filed once testing has been the operator has detennined that the site CACHED FOR IONS OF APPROV COMT. 438. Tay Arrie & To 358. Tay (SLO EQUIREMENTS. 0 150 SQZ TO

SOUTHWEST ROYALTIES, INC. WILDERSPIN FEDERAL #3 30-015-25501



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3 <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement</u>: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water Minimum nine (9) pounds per gallon.

5 <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.