Submit 3 Copies To Appropriate District	State of N	lew Me	xico		Form C-1	03
Office District I	Energy, Minerals a		Revised June 10, 20	003		
1625 N. French Dr., Hobbs/ NM 88240	WELL API NO).				
District II /9 III	30-015-32862					
1301 W. Grand Ave., Artesia, NM 882100	ZUJUL GUNSERV			5. Indicate Ty	pe of Lease	
1000 Rio Brazos Rd Azies NM 87411FCE	VED 1220 South			STATE	FEE	
1301 W. Grand Ave., Artesia, NM 882 IVUL <u>District III</u> 1000 Rio Brazos Rd., Aztes, NM 874 HECE <u>District IV</u> 1220 S. St. Francis Dr. Sabe Fe. NM	IFSIA Santa Fe,	, NM 87	505	6. State Oil &	Gas Lease No.	
1220 5. 50. 11005 51., 500002 0, 1111	Con Co			NM4681		
87505	TES ANT PEDODTS ON	WEIIS	·····	7 Loose Nom	e or Unit Agreement Name	
SUNDER NOTIO	LES AND REPORTS ON	WELLS	IG BACK TO A	7. Lease Maine	e of Onit Agreement Name	5
DIFFERENT RESERVOIR. USE "APPLICA	ATION FOR PERMIT" (FORM	(C-101) FO	R SUCH	State 2		
PROPOSALS.)				8. Well Numb		
1. Type of Well:				8. Wen Numb		
Oil Well 🔲 Gas Well 🛛	Other			o		
2. Name of Operator				9. OGRID Nu	mber	
Pecos Production Company				215758		
3. Address of Operator				10. Pool name or Wildcat		
400 W. Illinois, Suite 1070, Midland	l, TX 79701			Undesignated Hackberry Morrow, North		
4. Well Location						
Unit LetterN:_	_660'feet from the _	South_	line and1	980'feet f	rom theWestlin	e
Section 2	Township 199	6 I	Range 30E	NMPM	Eddy County	
	11. Elevation (Show whe	ether DR,	RKB, RT, GR, etc.)			
12 Charles A	<u>3427' GR</u>	L'ante NT		D and an Oth		
	ppropriate Box to Inc	ncate N				
NOTICE OF INT		_			REPORT OF:	_
	PLUG AND ABANDON		REMEDIAL WORI	K L	ALTERING CASING	
	CHANGE PLANS	\boxtimes	COMMENCE DRI			
		-			ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB		J	
		_			-	
OTHER:			OTHER:			
 Describe proposed or completed of starting any proposed wor or recompletion. 						

- 1. Well location changed to 660' FSL & 1980' FWL of Sec. (See attached Form C-102)
- 2.
- 3.
- Well depth changed to 12,200'. (See attached revised well plan) Intermediate casing depth changed to 3200'. (See attached revised well plan) BOP rating changed from 3M to 5M. (See attached revised well plan & schematic attached) 4.

I hereby certify that the information above is true a	nd complete to the best of my ki	nowledge and belief.	
SIGNATURE Will Which	TITLEVP – Engr	& OperatinsDATE	7/21/03
	E-mail address: billh@pecospr	oduction.com , Telephone No.	432-620-8480
(This space for State for State from) W. Su APPPROVED BY	m Rutri	1 Superview	JUL-2-3 2003
APPPROVED BY	TITLE	DATE	
Conditions of approval, if any:			

DISTRICT I F.O. Bar 1953, Nothe, DISTRICT II F.O. Drymer BD, Artest DISTRICT III 1950 Bio Brance Rd	Mi 6884 1-1	an (197	202	122232	2.25		State	of Net d magazet	w Mes	KİCO Bışırtmıst			For Rovised Johnson	TR C-102 y 10, 1994
DISTRICT II P.O. Dremer 10, Artest		ATIS .	,	- OIL	Ĉ	ÖN	SER	VATI	ON	DIVIS	IC)N ^{Bubmit}	to Appropriate Dist State Lease For Lease	- 4 Copies
DISTRICT III 1990 No Brasos M	L. Antes, 0													- O Collidad
DISTRICT IV P.O. BOX 6005. SANTA		~ 0(CD - T	ABIESU	CAT	- ION	AND	ACREA	IGE I	EDICATI	ON	PLAT	Z AMENDED	REPORT
1	tumber	101			Pool	óđe		1						
30-015- Property Co			68	1999	<u>Z_</u>			erty Nem	10	gnated	Ha	<u>ckberry M</u>	orrow, Nort	
OGRID No.	•			· · · · · · · · · · · · · · · · · · ·				ATE 2					8 Bovetic	
215758		I		P	ECO	S P	RODU			IPANY			3427	-
C		1					_	ce Loc						
UL or lot No.	Rection 2	Townshi 19-	•	Rango 30-E	Lot	1dp		om the 60'	1	/South Ites OUTH	ľ	test from the 1980'	Bast/Went line WEST	Comply EDDY
		r			·····					From Sur				1
UL er lot No.	Section	Townshi	lp I	Rango	Lot	Ida	Feet fr	om the	North	South line		est from the	Kunt/West. Hns	County
Dedicated Acres	Joint a	r infill	Con	haolidation	Code	Ór	der Ho,		L		1			
320						<u> </u>	· · · · · ·					<u></u>		
NO ALLO	WABLE V											TS HAVE BE S DIVISION	SEN CONSOLIDA	TED
LOT 4			LOT			-	OT 2		. 1	LOT 1		OPERATO	DR CERTIFICAT	TON
			Pe	ecos Pr	1			ipany					y sertify the the inj n is true and compl	
[[1			Stat	e 2 	Lea	ise	1					stadge and belief.	
												11-	a. n. A	
40.40	AC	.	40.	JR AC			10.38 AC			40.36 AC		Bignature	4 Marin	
											٦	William Frinted Nem	R. Huck	
{					1 1 ·				•				gr. & Opera	tions
												7-21-03		
					1			1				Date		
			<u></u>		1							SURVEYO	R CERTIFICAT	TON
	1				1		•	1					y that the well lead as plotted from field	1
					1			1				oningi euroege supervisen. er	made by the or	undor my
	ļ											correct to th	s best of my bolle	r.
	1				1			1				Ju	ne 11, 2003	
	↓				 							Signature 2	11, 2003	A.W.B
								•				0 2	N MEL SOL	2
			_									Konald	Asulon 2	21/03
	1980'		Ĩ		•			1				1 20	11.0755	a line
			-660		32	20 A	cres					Curtificate a	AAN ELESION	DM . 3830 12041
		a	1	e a salar - a - a	l								NOT CONTRACT	

.

BLOWOUT PREVENTOR ARRANGEMENT

II "SHAFFER TYPE LWS, 5000 psi WP
II "CAMERON SPHERICAL, 5000 psi WP
I20 GALLON, 5 STATION KOOMEY ACCUMULATOR
5000 psi WP CHOKE MANIFOLD



•

Pecos Production Company Revised Drilling Well Plan

Well Name:	State 2 No. 8						
Location:	660' FSL & 1980' FWL, Section 2, Twp 19-S, Rge 30-E, Eddy Co, NM Well is believed to be outside the OCD R-111-P Area. Shallow horizons (Yates – San Andres) contain H2S. Limited Exposure radius. 100 PPM ROE = 11.71ft. 500 PPM ROE = 5.71 ft Use appropriate warning signs, monitors, and train drilling personel.						
Objective:	8,800' Bone Spring, 12,200' Morrow						
Rig Specs:	-	12,000 – 13,000' depth b łookload (16.6# dp): g Hookload:	racket. 250,000 lb. 210,000 lb.				
BOP's:	Surface Hole: Intermediate: Production:	None 13-5/8", 3M Double Ra 11", 5M Double Ram v					

EST FORMATION TOPS

Yates	2,290	1 st BS Sand	8,490
Queen	2,713	2 nd BS Sand	8,600
SanAndres	3,460	Wolfcamp	9,700
Delaware	5,023	Strawn	10,700
Bone Spring	6,000	Morrow`	11,600

LOCATION

Build 300' x 200' caliche pad w/ 150×150 double horseshoe reserve. Use material from reserve for pad and road surface. Keep reserve pit below grade to facilitate reclamation to OCD guidelines. Install 6' x 6' x 6' cellar. Drill and grout in 40 ft of 20 " conductor pipe.

SURFACE HOLE

Drill 17-1/2" surface hole to \pm - 680'. Use fresh water – native mud. Circulate steel pits to control washout. Run and cement 13-3/8" casing. Centralize every other collar. Install Texas Pattern Guide shoe and insert float. Displace w/ fresh water.

SURFACE CASING

Size	Wgt	Grd	Cplg	Depth	Col SF	Burst SF	Tens SF
13-3/8"	48#	H-40	STC	680	2.43	1.15*	9.80
MAOD	1000	•					

MASP - 1500 psi.

CEMENT

Lead: 385 sx Class C w/ 4% gel, ¼# Celloflake, 2% CaCl. 13.4 ppg. 1.77 cf/sk.

Tail: 200 sx Class C w/ ¼# celloflake, 2% CaCl. 14.8 ppg. 1.34 cf/sk.

INTERMEDIATE HOLE

WOC 4 hrs. Cut off conductor and 13-3/8" casing. Weld on 13-3/8" SO x 13-5/8", 3M Bradenhead. Install and test 13-5/8", 3M double-ram BOP's w/ Annular. Test casing to 1000 psi. Drill out shoe and drill 11" hole to 3200'. Circulate brine to control washout in salt section. Lower waterloss to 20 cc at 3200 ft to stabilize hole for casing job. Run and cement 8-5/8" casing. Centralize shoe joint and every 4th collar back to 1000'. Install cement nose guide shoe and float collar. Set 75 % csg weight on slips after bumping plug.

INTERMEDIATE CASING

Size	Wgt	Grd	Cplg	Sect L.	Depth	Col SF	Burst SF	Tens SF
8-5/8"	32	J-55	STC	3200	3200	1.52	1.31	3.63
D C A CITA	0000	•						

MASP – 3000 psi.

CEMENT

Lead: 550 sx 50:50 Poz:C w/ 5% salt, 10% gel. 11.6 ppg. 2.61 cf/sk. 1900' fill x 100% excess. Tail: 200 sx Class C w/ 1% CaCl. 14.8 ppg. 1.34 cf/sk. 500' fill x 100% excess.

PRODUCTION HOLE

Rig down 13-5/8" stack. Install 13-5/8" $3M \ge 11$ ", 3M B-section and test seal to 3000 psi. Install 11", 5M double-ram BOP's w/ annular and rotating head. Test BOP's and casing to 2500 psi. Drill out shoe and test formation to 12 ppg EMW. Drill 7-7/8" hole to 12,200 ft. Drill out 8-5/8" casing with cut brine. Control seepage w/ fibrous LCM sweeps. At 9500', add brine for 9.5 ppg weight. Lower WL to 10 cc w/ white starch at 10,500', maintain adequate viscosity to clean hole with XCD polymer. MW of 9.5 – 10.0 ppg should be adequate for Strawn and Morrow sections. At TD, condition hole and log. If productive – condition hole for casing, change BOP rams and run 5-1/2 " production casing to TD. Run float shoe and float collar, DV tool at +/-7500'. Centralize casing through zones of interest.

PRODUCTION CASING

Size	Wgt	Grd	Cplg	Sect. L	Depth	Col. SF	Burst SF	Tens SF*
5-1/2"	17#	L-80	LTC	3200	3200	3.80	1.54	1.62
5-1/2"	17#	J-55	LTC	4300	7500	1.15	1.10	1.61
5-1/2"	17#	N-80	LTC	3300	10800	1.12	NA	4.35
5-1/2"	17#	HCN	LTC	1400	12200	1.35	NA	NA

CEMENT

1 st stage Lead:	325 sx 35:65:6 "H" w/ 1.1% FL-52. 12.4 ppg, 2.0 cf/sk 2500' fill w/ 50% excess
Tail:	380 sx 61:15:11 "H":poz:cse w/ .7% FL-25, .4% FL-52, .5% SMS. 2200 ft fill w/ 50% excess.
2 nd stage Lead:	400 sx 50:50 poz "H" w/ 3% salt, .5% FL-52. 3300' fill w/ 50% excess
Tail	200 sx Class C Neat. 1100' fill w/ 50% excess.

COMPLETION

Set 75% casing weight on slips. Remove BOP's and install 11", 3M x 7-16", 3M tubinghead. Test seals to 3000 psi. RDMO rotary tools.