		ew Mexico	Form C-103
Office <u>District I</u>	Energy, Minerals an	nd Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-015-05411
1301 W. Grand Ave., Artesia, NM 88210		ATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410		St. Francis Dr.	STATE FEE
District IV	Santa Fe,	NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			
87505 SUNDRY NO	TICES AND REPORTS ON	WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROP	POSALS TO DRILL OR TO DEEPER	N OR PLUG BACK TO A	Lea D
DIFFERENT RESERVOIR. USE "APPI PROPOSALS.)	LICATION FOR PERMIT" (FORM (C-101) FOR SUCH	8. Well Number 1
1. Type of Well: Oil Well	Gas Well Other In	jection PECELVET	
2. Name of Operator		• •	9. OGRID Number
Forest Oil Corporation		JUN 2 7 2006	8041
3. Address of Operator		WUUMANTEO	10. Pool name or Wildcat
3504 NW County Road		·	Grayburg Jackson 7RVS QN GB SA
4. Well Location			
Unit Letter B :	660 feet from the Nor		feet from the <u>East</u> line
Section 26	Township 175		NMPM Eddy County
	i '	her DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application	3849' DF		
Pit type Depth to Ground		st fresh water well Dist	ance from nearest surface water
V	il Below-Grade Tank: Volun		nstruction Material
12. Check	Appropriate Box to Indi	cate Nature of Notice,	Report or Other Data
NOTICE OF I	INTENTION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK		☐ REMEDIAL WOR	·
		COMMENCE DRI	LLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL	☐ CASING/CEMEN	T JOB
	-		
OTHER: Temporary Abandor		OTHER:	d aivo nominant datos, includina actimated dato
13. Describe proposed or con	npleted operations. (Clearly s	tate all pertinent details, and	d give pertinent dates, including estimated date
13. Describe proposed or con of starting any proposed	npleted operations. (Clearly s	tate all pertinent details, and	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
13. Describe proposed or con	npleted operations. (Clearly s	tate all pertinent details, and	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
13. Describe proposed or con of starting any proposed	npleted operations. (Clearly s	tate all pertinent details, and	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
13. Describe proposed or con of starting any proposed or recompletion.	npleted operations. (Clearly s work). SEE RULE 1103. For	tate all pertinent details, and Multiple Completions: At	tach wellbore diagram of proposed completion
13. Describe proposed or composed or starting any proposed or recompletion. The annulus will be press	npleted operations. (Clearly s work). SEE RULE 1103. For sured to 500 PSI to check its in	tate all pertinent details, and Multiple Completions: At multiple Completions At materials. If it is ok, a pulling	tach wellbore diagram of proposed completion g unit will be rigged up. The packer
13. Describe proposed or con of starting any proposed or recompletion. The annulus will be press will be released and pulle	npleted operations. (Clearly s work). SEE RULE 1103. For sured to 500 PSI to check its ired out of the hole, laying down	tate all pertinent details, and Multiple Completions: At multiple Completions: At materials. If it is ok, a pulling tubing and packer. A CIB	tach wellbore diagram of proposed completion g unit will be rigged up. The packer P will be set where packer was
13. Describe proposed or completion. The annulus will be press will be released and pulle set. The Artesia OCD off	inpleted operations. (Clearly s work). SEE RULE 1103. For sured to 500 PSI to check its in ad out of the hole, laying down fice will be notified before sta	tate all pertinent details, and Multiple Completions: At multiple Completions: At materials. If it is ok, a pulling tubing and packer. A CIB	tach wellbore diagram of proposed completion g unit will be rigged up. The packer
13. Describe proposed or con of starting any proposed or recompletion. The annulus will be press will be released and pulle	inpleted operations. (Clearly s work). SEE RULE 1103. For sured to 500 PSI to check its in ad out of the hole, laying down fice will be notified before sta	tate all pertinent details, and Multiple Completions: At multiple Completions: At materials. If it is ok, a pulling tubing and packer. A CIB	tach wellbore diagram of proposed completion g unit will be rigged up. The packer P will be set where packer was
13. Describe proposed or composed or starting any proposed or recompletion. The annulus will be press will be released and pulle set. The Artesia OCD off PSI and tested again with	inpleted operations. (Clearly s work). SEE RULE 1103. For sured to 500 PSI to check its in ad out of the hole, laying down fice will be notified before sta	tate all pertinent details, and Multiple Completions: At multiple Completions: At multiple Completions: At multiple title and packer. A CIB at the form of work and casing test.	tach wellbore diagram of proposed completion g unit will be rigged up. The packer P will be set where packer was
13. Describe proposed or composed or starting any proposed or recompletion. The annulus will be press will be released and pulle set. The Artesia OCD off PSI and tested again with	npleted operations. (Clearly s work). SEE RULE 1103. For sured to 500 PSI to check its intended out of the hole, laying down fice will be notified before state a 30 minute chart.	tate all pertinent details, and Multiple Completions: At multiple Completions: At multiple Completions: At multiple title and packer. A CIB at the form of work and casing test.	tach wellbore diagram of proposed completion g unit will be rigged up. The packer P will be set where packer was
13. Describe proposed or composed or starting any proposed or recompletion. The annulus will be press will be released and pulle set. The Artesia OCD off PSI and tested again with Estimated date of starting	sured to 500 PSI to check its in the dout of the hole, laying down fice will be notified before state a 30 minute chart.	tate all pertinent details, and Multiple Completions: At Multiple Completions: At Integrity. If it is ok, a pulling a tubing and packer. A CIB art of work and casing test.	tach wellbore diagram of proposed completion g unit will be rigged up. The packer P will be set where packer was
13. Describe proposed or composed or starting any proposed or recompletion. The annulus will be press will be released and pulle set. The Artesia OCD off PSI and tested again with Estimated date of starting	sured to 500 PSI to check its in a 30 minute chart. g proposed work will be as soon ust be within 100' of Top	tate all pertinent details, and Multiple Completions: At multiple Completions: At many many many many many many many many	tach wellbore diagram of proposed completion g unit will be rigged up. The packer P will be set where packer was The casing will be pressured to 500
13. Describe proposed or composed or starting any proposed or recompletion. The annulus will be press will be released and pulle set. The Artesia OCD off PSI and tested again with Estimated date of starting	sured to 500 PSI to check its in a 30 minute chart. g proposed work will be as soon ust be within 100' of Top	tate all pertinent details, and Multiple Completions: At multiple Completions: At many many many many many many many many	g unit will be rigged up. The packer P will be set where packer was The casing will be pressured to 500
13. Describe proposed or composed or starting any proposed or recompletion. The annulus will be press will be released and pulle set. The Artesia OCD off PSI and tested again with Estimated date of starting	sured to 500 PSI to check its in a 30 minute chart. g proposed work will be as soon ust be within 100' of Top	tate all pertinent details, and Multiple Completions: At multiple Completions: At many many many many many many many many	tach wellbore diagram of proposed completion g unit will be rigged up. The packer P will be set where packer was The casing will be pressured to 500
13. Describe proposed or composed of starting any proposed or recompletion. The annulus will be press will be released and pulle set. The Artesia OCD off PSI and tested again with Estimated date of starting CIBP multiple CIBP	sured to 500 PSI to check its in the dout of the hole, laying down fice will be notified before state a 30 minute chart. It proposed work will be as soon the state of the within 100' of Top ions.	tate all pertinent details, and Multiple Completions: At Multiple Completions: At a pulling at tubing and packer. A CIB at the of work and casing test.	tach wellbore diagram of proposed completion g unit will be rigged up. The packer P will be set where packer was The casing will be pressured to 500 Notify OCD 24 hrs. prior to only work done.
13. Describe proposed or composed or starting any proposed or recompletion. The annulus will be press will be released and pulle set. The Artesia OCD off PSI and tested again with Estimated date of starting CIBP may Perforate	inpleted operations. (Clearly's work). SEE RULE 1103. For sured to 500 PSI to check its in a dout of the hole, laying down fice will be notified before star a 30 minute chart. It is proposed work will be as soon ust be within 100' of Top ions.	tate all pertinent details, and Multiple Completions: At Multiple Completions: At many many many many many many many many	y unit will be rigged up. The packer P will be set where packer was The casing will be pressured to 500 Notify OCD 24 hrs. prior to only work done.
13. Describe proposed or composed or starting any proposed or recompletion. The annulus will be press will be released and pulle set. The Artesia OCD off PSI and tested again with Estimated date of starting CIBP may Perforate	inpleted operations. (Clearly's work). SEE RULE 1103. For sured to 500 PSI to check its in a dout of the hole, laying down fice will be notified before star a 30 minute chart. It is proposed work will be as soon ust be within 100' of Top ions.	tate all pertinent details, and Multiple Completions: At Multiple Completions: At many many many many many many many many	tach wellbore diagram of proposed completion g unit will be rigged up. The packer P will be set where packer was The casing will be pressured to 500 Notify OCD 24 hrs. prior to only work done.
13. Describe proposed or composed or starting any proposed or recompletion. The annulus will be press will be released and pulle set. The Artesia OCD off PSI and tested again with Estimated date of starting CIBP may Perforate	npleted operations. (Clearly swork). SEE RULE 1103. For sured to 500 PSI to check its index out of the hole, laying down fice will be notified before state a 30 minute chart. The proposed work will be as soon to be within 100° of Top ions. The proposed work and complete or closed according to NMOCD guide.	tate all pertinent details, and Multiple Completions: At Multiple Completions: At many many many many many many many many	y unit will be rigged up. The packer P will be set where packer was The casing will be pressured to 500 Notify OCD 24 hrs. prior to only work done.
13. Describe proposed or composed or starting any proposed or recompletion. The annulus will be press will be released and pulle set. The Artesia OCD off PSI and tested again with Estimated date of starting CIBP may Perforate I hereby certify that the information grade tank has been/will be constructed SIGNATURE	sured to 500 PSI to check its in a dout of the hole, laying down fice will be notified before stars a 30 minute chart. The proposed work will be as soon that the within 100' of Topmons. The proposed according to NMOCD guarantees and complete or closed according to NMOCD guarantees.	tate all pertinent details, and Multiple Completions: At Multiple Completions: At many many many many many many many many	young work done. The and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE June 26, 2006
13. Describe proposed or composed or starting any proposed or recompletion. The annulus will be press will be released and pulle set. The Artesia OCD off PSI and tested again with Estimated date of starting CIBP may Perforate Perforation. I hereby certify that the information of the property of the	sured to 500 PSI to check its in a dout of the hole, laying down fice will be notified before stars a 30 minute chart. The proposed work will be as soon that the within 100' of Topmons. The proposed according to NMOCD guarantees and complete or closed according to NMOCD guarantees.	tate all pertinent details, and Multiple Completions: At Multiple Completions: At many many many many many many many many	tach wellbore diagram of proposed completion g unit will be rigged up. The packer P will be set where packer was The casing will be pressured to 500 Notify OCD 24 hrs. prior ony work done. the and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
13. Describe proposed or composed or starting any proposed or recompletion. The annulus will be press will be released and pulle set. The Artesia OCD off PSI and tested again with Estimated date of starting CIBP may Perforate I hereby certify that the information grade tank has been/will be constructed SIGNATURE	sured to 500 PSI to check its in a dout of the hole, laying down fice will be notified before stars a 30 minute chart. The proposed work will be as soon that the within 100' of Topmons. The proposed according to NMOCD guarantees and complete or closed according to NMOCD guarantees.	tate all pertinent details, and Multiple Completions: At Multiple Completions: At many many many many many many many many	younit will be rigged up. The packer P will be set where packer was The casing will be pressured to 500 Notify OCD 24 hrs. Prior to any work done. The and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan . DATE June 26, 2006 Telephone No. (505) 392-9797
13. Describe proposed or composed or starting any proposed or recompletion. The annulus will be press will be released and pulle set. The Artesia OCD off PSI and tested again with Estimated date of starting CIBP may Perforate Perforation. I hereby certify that the information of the property of the	sured to 500 PSI to check its in a dout of the hole, laying dowr fice will be notified before state a 30 minute chart. The proposed work will be as soon as the within 100' of Top ions. The proposed according to NMOCD guidence or closed according to NMOCD guidence.	tate all pertinent details, and Multiple Completions: At Multiple Completions: At many many many many many many many many	younit will be rigged up. The packer P will be set where packer was The casing will be pressured to 500 Notify OCD 24 hrs. Prior to any work done. The and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan . DATE June 26, 2006 Telephone No. (505) 392-9797
13. Describe proposed or composition of starting any proposed or recompletion. The annulus will be press will be released and pulle set. The Artesia OCD off PSI and tested again with Estimated date of starting CIBP may Perforate Perforation. I hereby certify that the information of the property of t	sured to 500 PSI to check its in a dout of the hole, laying dowr fice will be notified before state a 30 minute chart. The proposed work will be as soon as the within 100' of Top ions. The proposed according to NMOCD guidence or closed according to NMOCD guidence.	tate all pertinent details, and Multiple Completions: At Multiple Completions: At many many many many many many many many	younit will be rigged up. The packer P will be set where packer was The casing will be pressured to 500 Notify OCD 24 hrs. Prior to any work done. The and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan . DATE June 26, 2006 Telephone No. (505) 392-9797 The packer P will be rigged up. The packer P will be rigged up. The packer P was a set of the packer P will be rigged up. The packer P will be rigged up. The packer P was a set of the packer P will be rigged up. The packer P will be rigge