Form 3160-5 (April 2004)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	<u>, , , , , , , , , , , , , , , , , , , </u>	ed .	\
( , (	Month - V FEB 2 V	SIESIA.	eh)
\	000	/	/

FORM APPROVED OMB No. 1004-0135 Expires March 31, 2007

Lease Serial No.		
IM-34452		

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or re enter an					5. Lease Serial No. NM-34452		
abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well  X Oil Well Gas Well Other					8. Well Name and No.		
2. Name of Operator			····	· ·	Northwestern 9. API Well No.	Shores XR Federal Com #1	
Yates Petroleum Corporation  3a. Address  3b. Phone No. (include area code)						600	
3a. Address 3b. Phone No. (include area code) 105 S. 4th Str., Artesia, NM 88210 505-748-1471					10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec.,T.,R.,M., OR Survey Des	cription)	<u> </u>			Atoka; Glor	ieta-Yeso	
	2005 (11 11 5 11)	A(A)=\			11. County or Pa		
660'FNL & 1980'FEL of Section 36-T18S-F	<del></del>		PE OF NO		Eddy County, New Mexico		
TYPE OF SUBMISSION	(E3) 10 INDICA		TYPE OF A		- CKI, OK C	THER DATA	
TITE OF SODIVISSION			TILON	7			
Acidize		Deepen		Production (S	tart/Resume)	Water Shut-Off	
X Notice of Intent Alter C	asing	Fracture Treat	<u></u>	Reclamation		Well Integrity	
Subsequent Report Casing	Repair	New Construc	tion	Recomplete		Other	
Change	Plans X	Plug and Abar	idon	Temporarily /	Abandon		
Final Abandonment Notice Conver	t to Injection	Plug Back		Water Dispos	al		
Attach the Bond under which the work will be performed or provide following completion of the involved operations. If the operation is testing has been completed. Final Abandonment Notices shall be determined that the site is ready for final inspection.)  Yates Petroleum Corporation plans to plug 1. Rig up all safety equipment as needed. 2. Set a 5-1/2" CIBP at 2914' with 35' cemes 3. Spot a 25 sx Class "C" cement plug with This will leave a 100' plug across the interest of the surface casing shoe. 4. Perforate the 5-1/2" casing at 601'. Pure the surface casing shoe. 5. Perforate the 5-1/2" casing at 150'. Tie displace. This will leave plug from the side. Remove all surface equipment and weld.	results in a multiple comple filed only after all required and abandon the No casing recovered to the casing additives from the armediate casing a 50 sx cemes on the 5-1/2" casurface to 150'.	etion or recomprements, includir nis well as very will be 1275'-137 g shoe. ent plug ar sing and e	follows: follows: attempte follows: displace stablish ci	d. POOH 2-1/2 hour	with tubing and tag p This will lea	and TAC at +/-3000'.  lug, reset if necessary.  ve a 100' plug across	
14. I hereby certify that the foregoing is true and correct	ise steer pits arr	T TO Garti.	μισ				
Name <i>(Printed/Typed)</i> Tina Hu <b>∉</b> rta		Title	Regulator	v Complia	nce Superv	isor	
11:		Date			· · ·		
Signature Date February 20, 2007  THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
			T			ato.	
Approved by  Conditions of approval, if any, are attached. Approval of this	s notice does not warr		Title	····	Da	ale .	

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willbully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction



