OCD-ARTESIA UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED
OM B No. 1004-0137
Expires: March 31, 2007

5.	Lease Serial No.
ı	NIM 564 26

SUNDRY	NOTICES AND REPORTS	ON WELLS	NM 504-20	
Do not use thi abandoned wel	6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIF	7. If Unit or CA/Agreement, Name and/or No.			
2. Name of Operator SOUTHWEST 3a Address 6 DESTA DRIVE, STE 2100, MI 4. Location of Well (Footage, Sec., T.,	3b. Phone 432 688 R, M, or Survey Description)	No (inclanded code) -3267 2 2007 OCD - NATIONAL NAM	8. Well Name and No. ALSCOTT FEDERAL #2 9. API Well No. 30 015 22142 10. Field and Pool, or Exploratory Area N TURKEY TRACK (MORROW) 11. County or Parish, State	
660' FSL & 1980' FEL, SEC 30,	1188, R29E, UNIT O		EDDY COUNTY, NM	
12. CHECK APP	ROPRIATE BOX(ES) TO INDICATE	E NATURE OF NOTICE, I	REPORT, OR OTHER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION		
If the proposal is to deepen direction Attach the Bond under which the	Change Plans Convert to Injection Plug Bac Operation (clearly state all pertinent details, in onally or recomplete horizontally, give subsurvork will be performed or provide the Bond N	nstruction Recomplete Abandon Temporarily A k Water Disposal cluding estimated starting date of a face locations and measured and tr lo. on file with BLM/BIA. Requir	Well Integrity Other bandon	
Perfs 10,610' - 10,946' (CIBP Schematic attached. RU P&A contractor & eqpm	nt'd w/1400' sx circ mt'd w/700 sx; TOC @ 8250' (TS) @ 10,570' w/35' cmt) (CIBP @ 10,410' t. Set CIBP @ 9500' and top w/35' cmt. c of 5-1/2" to 50' above 5-1/2" csg. 2968'.		UR	
14. I hereby certify that the foregoi Name (Printed/Typed) DAWN M. HOWAR		Title OPERATIONS ASSIS	STANT	
Signature		Date 0	4/19/2007	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by Conditions of approval, if any, are attac	hed. Approval of this notice does not warra	Title	USE NED APPROVED	
	equitable title to those rights in the subject le		1 1 APR 27 2001	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. (Instructions on page 2)

SOUTHWEST ROYALTIES PROJECT AlsoH No2 ut 0, Sec 30, T185, 29E 1930 FEL & 660 F54 Eday Co, NM 171/2" Elev: 34616R hole NM 0924 API No 30-015 - 22/42 13 3/8 40# W/350X 60 dira 3018 934 24\$32# W/1400 SX (files bosurf) -11" pole pole **Accepted** for record **NMOCD** 700 C 8250' Survey 9506-71, 9574-78, 9614-21,) Cisco -9651-53, 19604-14. CIBP C 10570' W/35x com 10,610-14. perts 10,883-92 4 Shots Morrow -5/2"/7/20 -922-24 4 s Lots Ni Turkey Track 11,27018 235-46 10 shots W/ 7005X 11332 TD

PG-10

SUNDRY NOTICE SPECIAL STIPULATIONS

- 1. Approval is granted to plug this well with the following modifications:
- 2. BLM records indicate that three CIBP's were set in this well in February 2002 @ 11,050', 10120' and 9500' respectively, with 35' of cement bailed on top of each CIBP. This work was witnessed by a BLM Inspector. Apparently the CIBP reported as being set @ 10570' on 6/21/97 was drilled out without a sundry being filed to request or report that work. If you can verify this information, the setting of a CIBP @ 9500' in the proposed procedure should be replaced with tagging the cement on top of the CIBP currently @ 9500', then running a CIT or pumping 48 sacks of class H cement on top of the cement @ the PBTD.
- 3. When 5.5" casing is cut and pulled set stub plug size according to the criteria below. If the casing is pulled to down below 6595', add a 40 sack cement plug @ 6595', for the top of the Bone Spring. If the casing is pulled above 6595', perf and squeeze 40 sacks of cement @ 6595' leaving 16 sacks inside of the casing. If the casing is pulled below 8595' the plug must come above this depth or a plug must be added between that plug and the one @ 6595' to reduce the distance between these plugs to less than 2000'.
- 4. Add a 26 sack plug @ 895' for the top of the Delaware.
- 5. Add a 26 sack plug @ 445' for the surface casing shoe.

Accepted for record NMOCD

- 6. The surface plug must be at least 100'.
- 7. The plugs @ the 5.5" casing stub, 3068' and 455' must be tagged.
- 8. The balance of the procedure is approved as submitted

***All plugs below the surface plug must be at least 100' and 25 sacks of cement plus an additional 10% for each 1000 feet of depth.

Plugging procedures must conform to 43 CFR 3162.6.d and Onshore Order No. 2.III.G or NMOCD orders if they are more stringent.

ALL OF THE WORK AUTHORIZED HERE MUST BE COMPLETED WITHIN 90 DAYS.

Engineering can be reached at 505-706-2779 for variances.

F Wright 4/27/07

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, NM 88220

Interim Reclamation Procedures for Permanently Abandoned Federal Wells

- 1. After Subsequent Report of Abandonment, Form 3160-5, is filed and approved by the BLM the surface protection specialist (SPS) will conduct a surface inspection of the abandonment. The SPS will establish the reclamation requirements the operator will need to complete. **DO NOT START RECLAMATION UNTIL THE SPS HAS INSPECTED THE LOCATION.**
- 2. The reclamation requirements will be given to an environmental protection specialist (EPS). The EPS will issue the operator a Notice of Written Order outlining the reclamation requirements. **DO NOT START**RECLAMATION UNTIL A NOTICE OF WRITTEN ORDER FOR RECLAMATION HAS BEEN RECEIVED. The EPS will be responsible for all further abandonment work and inspections.
- 3. Notification: CONTACT THE EPS 3 DAYS PRIOR TO RECLAMATION WORK. This notification gives the EPS an opportunity to discuss by phone or on location the reclamation requirements, any special concerns and the timeframes. It also allows the EPS an opportunity to witness various aspects of the reclamation work to determine if an adequate seedbed has been prepared and all reclamation requirements have been completed. CONTACT THE EPS AT LEAST 3 DAYS PRIOR TO SEEDING. This allows the EPS to witness the seeding operation to make sure the location is seeded properly and with the appropriate seed mixture. DO NOT START RECLAMATION UNTIL THE EPS HAS BEEN NOTIFIED.
- 4. After reclamation work has been completed, submit the I & E copy of the Notice of Written Order to the BLM. It will need to be signed by a company representative and dated. Also submit one original and five copies of the Final Abandonment Notice, Form 3160-5. The report should state that all reclamation work has been completed, and the location is ready for a final abandonment inspection.
- 5. The BLM will continue to monitor the location to ensure the location vegetates successfully, and salts from the reserve pit do not leach to the surface. The location will be monitored until such time as vegetation (20%) is established evenly across the location (including the reserve pit and access road). Once EPS determines that vegetation (20%) is evenly spread across the location, final abandonment will be authorized.

If there are any questions please feel free to contact any of the following:

Accepted for record NMOCD

Jim Amos Supervisory Environmental Protection Specialist (505) 234-5909

Barry Hunt Surface Protection Specialist (505) 234-5965

Todd Suter Surface Protection Specialist (505) 234-5987

Trishia Bad Bear Natural Resource Specialist – Lea County (505) 393-3612 Cody Layton Natural Resource Specialist (505) 234-5959

Paul Evans Environmental Protection Specialist (505) 234-5977

Terry Gregston Environmental Protection Specialist (505) 234-5958

10/18/2006