Submit 3 Copies To Appropriate District Office		New Me		Form C-103 Revised June 10, 2003		
1625 N. French Dr., Hobbs, NM 88240						
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION				30-015-00176 5. Indicate Type	of Lease	
District III	1220 South St. Francis Dr.			STATE	FEE 🛛	
1000 Rio Brazos Rd, Aztec, NM 87410 District IV Santa Fe, NM 87505				6. State Oil & G	<del></del>	
1220 S. St. Francis Dr , Santa Fe, NM 87505						
	CES AND REPORTS O	N WELLS	S	7. Lease Name of	or Unit Agreement Na	ne
(DO NOT USE THIS FORM FOR PROPOS				Atoka San Andı	res Unit	
DIFFERENT RESERVOIR. USE "APPLICATION PROPOSALS")	ATION FOR PERMIT" (FOR	(M C-101) F	JK SUCH	8. Well Number		
1. Type of Well:				o. Wen Number		
Oil Wall Cos Wall 🔯	Other—Water Injection	n Well		113		
2. Name of Operator			a 6 3001	9. OGRID Num	ber	
Devon Energy Production Company	, LP	UEC	505	6137		****
3. Address of Operator		05	LAKTESI	10. Pool name o		
20 North Broadway, Suite 1500, Ok	lahoma City, Oklahoma	1 731 <u>02</u> C1	<u> </u>	Atoka San Andı	res	
4. Well Location						
2. Name of Operator Devon Energy Production Company, LP  3. Address of Operator 20 North Broadway, Suite 1500, Oklahoma City, Oklahoma 73102CD-Air Suite Sun Andres  4. Well Location  Unit Letter J : 1645' feet from the South line and 2310' feet from the East line						
Section 11	Township 18	S R	ange 26E	Edd	y County	
	11. Elevation (Show w. 3316' GL: 3322' KB	hether DR	, RKB, RT, GR, etc.)			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK	PLUG AND ABANDON	<b>1</b>	REMEDIAL WORK		ALTERING CASING	
						_
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRIL	_LING OPNS.□	PLUG AND ABANDONMENT	$\boxtimes$
PULL OR ALTER CASING	MULTIPLE		CASING TEST AN	ID 🗆		
	COMPLETION		CEMENT JOB			
OTHER:			OTHER:			
13. Describe proposed or comple						
of starting any proposed wor or recompletion.	k). SEE RULE 1103. I	For Multip	le Completions: Att	ach wellbore diagi	am of proposed compl	letion
or recompletion.						
1. MIRU PA rig on 12/2/07. POOH	w/ 2-3/8" IPC tubing. I	Dump bail	35' cement on top of	f existing CIBP at	1,576'.	
2. Circulate wellbore with 9.5 ppg salt gel mud.						
3. Spot 25 Sx cement in 5-1/2" casing plug at 1,275'. Tagged TOC @ 1,046'. (8-5/8" casing shoe at 1,225')						
4. Spot 60' surface plug.						
<ul><li>5. Cut wellhead off 3' below ground level, set P&amp;A marker, clean location.</li><li>6. Wellbore plugged &amp; abandoned - 12/20/07.</li></ul>						
o. Wellbore plugged & abandoned – I	2/20/07.					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
<b>A</b>						
SIGNATURE Rownie Stack TITLE: Engineering Technician DATE 12/20/0					E/2/20/07	
Type or print name Ronnie Slack E-mail address: Ronnie.Slack@dvn.com Telephone No. 405-552-4615						
(This space for State use)						
ADDDD OVED BY	b				DATE 1/- 1-	ر،
APPPROVED BY May Conditions of approval, if any:	mi	mle <u>Ca</u>	nglin off	<u> </u>	DATE 1/2/20	108
Conditions of approval, if any.					, ,	

Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under forms. www.emnrd.state.us/ocd Elevation: 3316' GL; 3322' KB API#: 30-015-00176 **PLUGGED & ABANDONED** 12/20/07 location. 9.5# mud 11" Hole 8-5/8", 29#, @ 1,225 Cmt'd w/700 Sx. TOC at surface 9.5# mud **SAN ANDRES** 1,654' - 1,672 (4 spf)

Plug & Abandonment

- 1. Spot 60' surface plug.
- 2. Cut wellhead off, set dry hole marker, clean
- 3. Wellbore plugged 12/20/07

Plug & Abandonment

- 1. Spot 25 Sx cement at 1,275'.
- 2. Tagged TOC @ 1,046'.

7-7/8" Hole 5-1/2", 15#, @ 1,797' Cmt'd w/350 Sx. TOC at surface Plug & Abandonment

- 1. Dump 35' cement on existing CIBP at 1,576'.
- 2. Circulate wellbore w/9.5# salt gel mud

CIBP @ 1,576' (3/18/82)

1,788' PBTD

1,797' TD