	TED STATES	OCD-ARTES	SIA		рркотеd . 1004-0137	
(April 2004) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			Ļ	Expires March 31, 2007		
				5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS				NM NM 103570 6. If Indian, Allottee or Tribe Name		
abandoned well. Use For						
SUBMIT IN TRIPLICATE -	Other instructions on re			7. If Unit or CA/Agr	eement, Name and/or No.	
1. Type of Well	A A	~ 082008		8. Well Name and N	0	
Oil Well X Gas Well Other OCD_ARTESIA 2. Name of Operator Ocdama Ocdama Ocdama				SAND BOX 1921- FEDERAL		
PARALLEL PETROLEUM CORPORATION				9. API Well No.		
3a. Address 3b. Phone No. (include area code) 1004 N BIG SERING, SUITE 400, MIDLAND, TX 79701 432-685-6563			·	30-015-35588		
1004 N BIG SPRING, SUITE 400, MIDLAND, TX 79701 432-685-6563 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 432-685-6563				10. Field and Pool, or Exploratory Area FOUR MILE DRAW, WOLFCAMP, SW		
SL: 742 FSL & 300 FEL, SEC 23, T1					.,	
BHL: 742 FSL & 660 FEL, SEC 24, T19S, R21E				11. County or Parish, State		
12. CHECK APPROPRIATE	E BOX(ES) TO INDICATE	E NATURE OF NOT			DATA	
TYPE OF SUBMISSION			OF ACTION			
X Notice of Intent	Acidize	Deepen	Production ((Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation		Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete		Other EXTENSION OF	
	Change Plans	Plug and Abandon	Temporarily	Altern de la		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Dispo		PROVED DRILLING	
If the proposal is to deepen directionally or recon Attach the Bond under which the work will be p following completion of the involved operations. testing has been completed. Final Abandonment determined that the final site is ready for final insp REQUEST THE APPROVED PERMIT FOR	erformed or provide the Bond No If the operation results in a mult Notices shall be filed only after ection.)	o. on file with BLM/BIA tiple completion or recom all requirements, includir	. Required sum pletion in a ne	bsequent reports sha w interval, a Form 3	Il be filed within 30 days 160-4 shall be filed once	
SEE ATTACHED FOR ENDING CONDITIONS OF APPROVAL				NTH PERIOD		
 I hereby certify that the foregoing is true and correc Name (Printed/Typed) 	х Т	Litle				
/KAYE MC CORMICK		SR PROD &	REG TECH	I		
pur McCornick Da		Date 03-12-2008				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
	Peterson	FIELD MA	ANAGEI	R Date		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.						
Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Sect States any false, fictitious or fraudulent statements or re	tion 1212, makes it a crime for an epresentations as to any matter with	y person knowingly and vithin its jurisdiction.	willfully to mai epted for re	ke to any department	or agency of the United	

PECOS DISTRICT CONDITIONS OF APPROVAL

OPERATOR'S NAME:	Parallel Petroleum Corporation
LEASE NO.:	NM103570
WELL NAME & NO.:	Sand Box 1921-24 Federal #1
SURFACE HOLE FOOTAGE:	742' FSL & 300' FEL Section 23
BOTTOM HOLE FOOTAGE	742' FSL & 660' FEL Section 24
LOCATION:	T19S., R21E., NMPM
COUNTY:	Eddy County, New Mexico

I. DRILLING

J.

A. DRILLING OPERATIONS REQUIREMENTS

The BLM is to be notified a minimum of **4 hours** in advance for a representative to witness:

- a. Spudding well
- b. Setting and/or Cementing of all casing strings
- c. BOP/BOPE tests

Eddy County

Call the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (575) 361-2822

- 1. Although there are no measured amounts of Hydrogen Sulfide reported in this Section, minor amounts have been measured in Section 7 at less than 10 ppm in STV's. If Hydrogen Sulfide is encountered, please report measured amounts and formations to the BLM.
- 2. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.
- 3. Floor controls are required for 3M or Greater systems. These controls will be on the rig floor, unobstructed, readily accessible to the driller and will be operational at all times during drilling and/or completion activities. Rig floor is defined as the area immediately around the rotary table; the area immediately above the substructure on which the draw works are located, this does not include the dog house or stairway area.

B. CASING

2

Note: All casing shall meet or exceed API standards for new casing. Onshore Order #2. III. B. 1. a (Any casing substitutions must have prior approval)

Centralizers required on surface casing per Onshore Order 2.III.B.1.f.

Medium cave/karst.

Possible lost circulation in the San Andres, Glorieta, and Wolfcamp formations. Possible high pressure gas kicks in the Wolfcamp formations.

- 1. The <u>8-5/8 inch</u> surface casing shall be set at <u>1500 feet</u> and cemented to the surface.
 - a. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with surface log readout will be used or a cement bond log shall be run to verify the top of the cement.
 - b. Wait on cement (WOC) time for a primary cement job will be a minimum 18 hours for a water basin, 24 hours in the potash area, or 500 pounds compressive strength, whichever is greater. (This is to include the lead cement).
 - c. Provide compressive strengths including hours to reach required 500 pounds compressive strength prior to cementing.
 - d. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compressive strength, whichever is greater.
 - e. If cement falls back, remedial action will be done prior to drilling out that string.
- 2. The minimum required fill of cement behind the <u>5-1/2 inch</u> production casing is:

Cement should tie-back at least 200 feet into previous casing string. **Operator shall provide method of verification.**

3. If hardband drill pipe is rotated inside casing, returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.

C. PRESSURE CONTROL

- 1. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 2. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be <u>3000 (3M)</u> psi.
- 3. The appropriate BLM office shall be notified a minimum of **4 hours** in advance for a representative to witness the tests.
 - a. The tests shall be done by an independent service company.
 - b. The results of the test shall be reported to the appropriate BLM office.
 - c. All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
 - d. The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug.
 - e. BOP/BOPE must be tested by an independent service company within 500 feet of the top of the <u>Wolfcamp</u> formation, if the time between the setting of the intermediate casing and reaching this depth exceeds 20 days. This test does not exclude the test prior to drilling out the casing shoe as per Onshore Order No. 2.

ę

D. DRILLING MUD

Mud system monitoring equipment, with derrick floor indicators and visual and audio alarms, shall be operating before drilling into the **Wolfcamp** formation, and shall be used until production casing is run and cemented.

E. DRILL STEM TEST

If drill stem tests are performed, Onshore Order 2.III.D shall be followed.

JDW 3/31/08

1910 4/4/08