Submit 3 Copies To Appropriate District	State of	New Me	exico			Form C-103
Office District I	Energy, Minerals	and Natu	ral Resources			May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	23 7			WELL API NO.		
District II	QIL CONSERV	/ A TION	DIVISION	, 30	0-005-63882	
1301 W. Grand Ave., Artesia, NM 88210				5. Indicate Type of Lease		
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr.				STATE	☐ FEE	
District IV	Santa Fe	e, NM 87	7505	6. State Oil & C	Gas Lease No	ο.
1220 S. St. Francis Dr., Santa Fe, NM 87505	i					
SUNDRY NOTI	ICES AND REPORTS OF	N WELLS		7. Lease Name o	r Unit Agree	ment Name:
(DO NOT USE THIS FORM FOR PROPOS				Riva Ridge 1426		
DIFFERENT RESERVOIR. USE "APPLIC	CATION FOR PERMIT" (FORM	1 C-101) FO	R SUCH			
PROPOSALS.)	C. Wall D. Odana			8. Well No. 1		
	Gas Well Other x	<u>apk</u>	<u>2 1 2008</u>			
2. Name of Operator	.•	200	ADTECIA	9. OGRID Numb	er	ļ
Parallel Petroleum Corpo	oration	Chris	-ARTESIA	10 70 1	33711 4	
3. Address of Operator	. 400 Mill J TW 505	0.1		10. Pool name or		
1004 N. Big Spring St. Ste	e. 400, Midiand, 1 X /9/	01		Wild	cat; Wolfca	mp
4. Well Location	500 C4 C	6 41	1: 1 00		.1 ***	. 1:
	760 feet from the				rom the Wes	
Section 16	Township 14		ange 26 E	NMPM	County	Chaves
	11. Elevation (Show who	ether DK,	RKB, RT, GR, etc.)			
Pit or Below-grade Tank Applicat			_			
			fresh water well			vater
	mil Below-Grade Tank:			ols; Construction Mat		
12. Check A	appropriate Box to Inc	licate Na	ature of Notice, 1	Report or Other	· Data	
NOTIOE OF 11						_
NOTICE OF IN		_		SEQUENT R		
PERFORM REMEDIAL WORK			REMEDIAL WORK		ALTERING	
TEMPORARILY ABANDON		Ц.	COMMENCE DRII		P AND A	
PULL OR ALTER CASING	MULTIPLE	Ц	CASING/CEMENT	JOB \square		
	COMPLETION					
	COMPLETION					•
	COMPLETION	П	OTHER:			
OTHER:		to all north	OTHER:		in aluding on	timated data of
OTHER: 13. Describe proposed or complete	d operations. (Clearly sta		inent details, and gi			
OTHER: 13. Describe proposed or complete starting any proposed work). S	d operations. (Clearly sta		inent details, and gi			
OTHER: 13. Describe proposed or complete starting any proposed work). S recompletion.	d operations. (Clearly sta SEE RULE 1103. For Mu		inent details, and gi			
OTHER: 13. Describe proposed or complete starting any proposed work). S recompletion. 4/07/08 MIRU plugging equipment	d operations. (Clearly sta SEE RULE 1103. For Mu	ltiple Con	inent details, and gi apletions: Attach w	rellbore diagram of		
OTHER: 13. Describe proposed or complete starting any proposed work). S recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 100	ed operations. (Clearly state SEE RULE 1103. For Mu nt. 0 bbls. of brine. NU BOI	ltiple Com P. Start in	inent details, and gi inpletions: Attach w in hole with work so	ellbore diagram of	f proposed co	ompletion or
OTHER: 13. Describe proposed or complete starting any proposed work). S recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 100 4/09/08 RIH w/ workstring to 552	od operations. (Clearly states of the RULE 1103. For Munt. Obbls. of brine. NU BOIO. Pump 70 bbls of mud	ltiple Com P. Start in laiden flu	inent details, and gi apletions: Attach w hole with work st id. Spot 50 sx. cei	tring. SDFN. nent @ 5520. Pul	f proposed co	ent, WOC 4
OTHER: 13. Describe proposed or complete starting any proposed work). Some recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 10/04/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47	od operations. (Clearly states of the RULE 1103. For Munt. Obbls. of brine. NU BOIO. Pump 70 bbls of mud	ltiple Com P. Start in laiden flu	inent details, and gi apletions: Attach w hole with work st id. Spot 50 sx. cei	tring. SDFN. nent @ 5520. Pul	f proposed co	ent, WOC 4
OTHER: 13. Describe proposed or complete starting any proposed work). Some recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 10/04/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night.	od operations. (Clearly states of the Clear	P. Start in laiden flu ud. Spot 2	inent details, and gi appletions: Attach we had hole with work so aid. Spot 50 sx. cen 25 sx. cement @ 47	tring. SDFN. ment @ 5520. Pull	f proposed co	ent, WOC 4
OTHER: 13. Describe proposed or complete starting any proposed work). S recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 100 4/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night. 4/10/08 RIH w/ tbg. and tag plug @ 5000'.	ed operations. (Clearly state of the Clearly state	P. Start in laiden flu ud. Spot 2	inent details, and ginpletions: Attach we hole with work stud. Spot 50 sx. cei 25 sx. cement @ 47 laiden fluid. POH	rellbore diagram of tring. SDFN. ment @ 5520. Pull '00'. Pull out of ce I to 3250'. Spot 2	f proposed collisions of cements of cements. Close 5 sx @ 3250	ent, WOC 4 e well in for . WOC 4 hrs.
OTHER: 13. Describe proposed or complete starting any proposed work). S recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 100 4/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night. 4/10/08 RIH w/ tbg. and tag plug @ 17 Tag plug @ 2978'. POH to 1500'.	ed operations. (Clearly state of the Clearly state	P. Start in laiden flu ud. Spot 2	inent details, and ginpletions: Attach we hole with work stud. Spot 50 sx. cei 25 sx. cement @ 47 laiden fluid. POH	rellbore diagram of tring. SDFN. ment @ 5520. Pull '00'. Pull out of ce I to 3250'. Spot 2	f proposed collisions of cements of cements. Close 5 sx @ 3250	ent, WOC 4 e well in for . WOC 4 hrs.
OTHER: 13. Describe proposed or complete starting any proposed work). S recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 100 4/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night. 4/10/08 RIH w/ tbg. and tag plug G Tag plug @ 2978'. POH to 1500'. surface. SDFN.	ed operations. (Clearly state of the control of the	P. Start in laiden flu ud. Spot 2 e w/ mud l OC 4 hrs.	inent details, and ginpletions: Attach was hole with work stud. Spot 50 sx. ceizs sx. cement @ 47 laiden fluid. POHTag plug @ 1240'.	rellbore diagram of tring. SDFN. ment @ 5520. Pull '00'. Pull out of ce I to 3250'. Spot 2	f proposed collisions of cements of cements. Close 5 sx @ 3250	ent, WOC 4 e well in for . WOC 4 hrs.
OTHER: 13. Describe proposed or complete starting any proposed work). S recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 100 4/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night. 4/10/08 RIH w/ tbg. and tag plug @ 17 Tag plug @ 2978'. POH to 1500'.	ed operations. (Clearly state of the control of the	P. Start in laiden flu ud. Spot 2 e w/ mud l OC 4 hrs.	inent details, and ginpletions: Attach was hole with work stud. Spot 50 sx. ceizs sx. cement @ 47 laiden fluid. POHTag plug @ 1240'.	tring. SDFN. ment @ 5520. Pull 700'. Pull out of ce I to 3250'. Spot 2. POH to 200'. Cir	f proposed collision of cement. Close 5 sx @ 3250 rculate 30 sx	ent, WOC 4 e well in for . WOC 4 hrs.
OTHER: 13. Describe proposed or complete starting any proposed work). S recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 100 4/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night. 4/10/08 RIH w/ tbg. and tag plug @ 17 ag plug @ 2978'. POH to 1500'. surface. SDFN. 4/11/08 Cut off Well head. Weld of Approved for plug @ 1500 proved for plug @ 2978'.	d operations. (Clearly state of the control of the	P. Start in laiden fluud. Spot 2 e w/ mud l OC 4 hrs.	inent details, and ginpletions: Attach was hole with work stud. Spot 50 sx. ceizs sx. cement @ 47 laiden fluid. POHTag plug @ 1240'.	rellbore diagram of tring. SDFN. ment @ 5520. Pull '00'. Pull out of ce I to 3250'. Spot 2	f proposed collision of cement. Close 5 sx @ 3250 rculate 30 sx	ent, WOC 4 e well in for . WOC 4 hrs.
OTHER: 13. Describe proposed or complete starting any proposed work). S recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 100 4/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night. 4/10/08 RIH w/ tbg. and tag plug @ Tag plug @ 2978'. POH to 1500'. surface. SDFN. 4/11/08 Cut off Well head. Weld of Approved for ple Liability under the starting and proposed for ple starting and proposed for	nd operations. (Clearly state of the state o	P. Start in laiden fluud. Spot 2 e w/ mud lo DC 4 hrs.	inent details, and ginpletions: Attach was hole with work stud. Spot 50 sx. ceizs sx. cement @ 47 laiden fluid. POHTag plug @ 1240'.	tring. SDFN. ment @ 5520. Pull 700'. Pull out of ce I to 3250'. Spot 2. POH to 200'. Cir	f proposed collision of cement. Close 5 sx @ 3250 rculate 30 sx	ent, WOC 4 e well in for . WOC 4 hrs.
OTHER: 13. Describe proposed or complete starting any proposed work). S recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 10/04/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night. 4/10/08 RIH w/ tbg. and tag plug (Tag plug @ 2978'. POH to 1500'. surface. SDFN. 4/11/08 Cut off Well head. Weld of C-103 (Subset)	d operations. (Clearly state of the control of the	P. Start in laiden fluud. Spot 2 e w/ mud lo DC 4 hrs.	inent details, and ginpletions: Attach was hole with work stud. Spot 50 sx. ceizs sx. cement @ 47 laiden fluid. POHTag plug @ 1240'.	rellbore diagram of tring. SDFN. ment @ 5520. Pull '00'. Pull out of ce I to 3250'. Spot 2 POH to 200'. Cir ACCEPTED FO	f proposed collision of cements Close sx @ 3250 reulate 30 sx	ent, WOC 4 e well in for . WOC 4 hrs.
OTHER: 13. Describe proposed or complete starting any proposed work). S recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 10/04/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night. 4/10/08 RIH w/ tbg. and tag plug (Tag plug @ 2978'. POH to 1500'. surface. SDFN. 4/11/08 Cut off Well head. Weld of C-103 (Subse which may be for	od operations. (Clearly state of the control of the	P. Start in laiden fluud. Spot 2 e w/ mud lo DC 4 hrs.	inent details, and ginpletions: Attach was hole with work stud. Spot 50 sx. ceizs sx. cement @ 47 laiden fluid. POHTag plug @ 1240'.	tring. SDFN. ment @ 5520. Pull 700'. Pull out of ce I to 3250'. Spot 2. POH to 200'. Cir	f proposed collision of cements Close sx @ 3250 reulate 30 sx	ent, WOC 4 e well in for . WOC 4 hrs.
OTHER: 13. Describe proposed or complete starting any proposed work). S recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 10/04/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night. 4/10/08 RIH w/ tbg. and tag plug (Tag plug @ 2978'. POH to 1500'. surface. SDFN. 4/11/08 Cut off Well head. Weld of C-103 (Subse which may be for	nd operations. (Clearly state of the control of the	P. Start in laiden fluud. Spot 2 e w/ mud lo DC 4 hrs.	inent details, and ginpletions: Attach was hole with work staid. Spot 50 sx. ceres 25 sx. cement @ 47 laiden fluid. POH Tag plug @ 1240'.	tring. SDFN. ment @ 5520. Pull '00'. Pull out of ce I to 3250'. Spot 2. POH to 200'. Cir ACCEPTED FO	f proposed colling of proposed colling of cement. Close 5 sx @ 3250 reulate 30 sx DR RECOR	ent, WOC 4 e well in for . WOC 4 hrs cement to
OTHER: 13. Describe proposed or complete starting any proposed work). S recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 10/04/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night. 4/10/08 RIH w/ tbg. and tag plug (Tag plug @ 2978'. POH to 1500'. surface. SDFN. 4/11/08 Cut off Well head. Weld of C-103 (Subse which may be for	od operations. (Clearly state of the control of the	P. Start in laiden fluud. Spot 2 e w/ mud lo DC 4 hrs.	inent details, and ginpletions: Attach we have with work so tid. Spot 50 sx. cere 25 sx. cement @ 47 laiden fluid. POH Tag plug @ 1240'.	tring. SDFN. ment @ 5520. Pull '00'. Pull out of ce I to 3250'. Spot 2. POH to 200'. Cir ACCEPTED FO APR 2.2 Gerry Guye, Deputy	f proposed colling of proposed colling of cement. Close 5 sx @ 3250 rculate 30 sx DR RECOR.	ent, WOC 4 e well in for . WOC 4 hrs cement to
OTHER: 13. Describe proposed or complete starting any proposed work). S recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 10/04/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night. 4/10/08 RIH w/ tbg. and tag plug @ 12978'. POH to 1500'. surface. SDFN. 4/11/08 Cut off Well head. Weld of C-103 (Subse which may be forms, www.cm.)	d operations. (Clearly state of the control of the	P. Start in laiden fluud. Spot 2 ew/ mud DC 4 hrs.	inent details, and ginpletions: Attach was hole with work staid. Spot 50 sx. ceres 25 sx. cement @ 47 laiden fluid. POH Tag plug @ 1240'.	tring. SDFN. ment @ 5520. Pull '00'. Pull out of ce I to 3250'. Spot 2. POH to 200'. Cir ACCEPTED FO APR 2.2 Gerry Guye, Deputy	f proposed colling for the following of the following for the foll	ent, WOC 4 e well in for . WOC 4 hrs cement to
OTHER: 13. Describe proposed or complete starting any proposed work). So recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 10/04/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night. 4/10/08 RIH w/ tbg. and tag plug a Tag plug @ 2978'. POH to 1500'. surface. SDFN. 4/11/08 Cut off Well head. Weld of Colod (Subse which may be for Forms, www.cm).	d operations. (Clearly state of Clearly	P. Start in laiden fluud. Spot 2 e w/ mud DC 4 hrs.	inent details, and ginpletions: Attach was hole with work staid. Spot 50 sx. ceres 25 sx. cement @ 47 laiden fluid. POH Tag plug @ 1240'. ove off.	tring. SDFN. ment @ 5520. Pull '00'. Pull out of ce I to 3250'. Spot 2. POH to 200'. Cir ACCEPTED FO APR 2.2 Gerry Guye, Deputy IMOCD-Districe ief. I further certify the	f proposed colling from the following from the foll	ent, WOC 4 e well in for . WOC 4 hrs cement to
OTHER: 13. Describe proposed or complete starting any proposed work). S recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 10/04/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night. 4/10/08 RIH w/ tbg. and tag plug @ 12978'. POH to 1500'. surface. SDFN. 4/11/08 Cut off Well head. Weld of C-103 (Subse which may be forms, www.cm.)	d operations. (Clearly state of Clearly	P. Start in laiden fluud. Spot 2 e w/ mud DC 4 hrs.	inent details, and ginpletions: Attach was hole with work staid. Spot 50 sx. ceres 25 sx. cement @ 47 laiden fluid. POH Tag plug @ 1240'. ove off.	tring. SDFN. ment @ 5520. Pull '00'. Pull out of ce I to 3250'. Spot 2. POH to 200'. Cir ACCEPTED FO APR 2.2 Gerry Guye, Deputy IMOCD-Districe ief. I further certify the	f proposed colling from the following from the foll	ent, WOC 4 e well in for . WOC 4 hrs cement to
OTHER: 13. Describe proposed or complete starting any proposed work). S recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 100 4/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night. 4/10/08 RIH w/ tbg. and tag plug Tag plug @ 2978'. POH to 1500'. surface. SDFN. 4/11/08 Cut off Well head. Weld of C.103 (Subse which may be for Forms, www.cm.) I hereby certify that the information aboth has been/will be constructed or closed a	d operations. (Clearly state of Clearly	P. Start in laiden fluud. Spot 2 e w/ mud laiden fluud. Spot 3 e w	inent details, and ginpletions: Attach was hole with work staid. Spot 50 sx. ceres 25 sx. cement @ 47 laiden fluid. POH Tag plug @ 1240'. ove off.	tring. SDFN. ment @ 5520. Pull 100'. Pull out of ce I to 3250'. Spot 2. POH to 200'. Cir ACCEPTED FO APR 2.2 Gerry Guye, Deputy MOCD-District ef. I further certify the content of the certify the certification of the certifica	f proposed colling of proposed colling of cement. Close 5 sx @ 3250 cculate 30 sx DR RECOR. 2008 7 Field Inspect 11 ARTES hat any pit or live OCD-app	ent, WOC 4 e well in for . WOC 4 hrs cement to
OTHER: 13. Describe proposed or complete starting any proposed work). So recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 10/04/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night. 4/10/08 RIH w/ tbg. and tag plug a Tag plug @ 2978'. POH to 1500'. surface. SDFN. 4/11/08 Cut off Well head. Weld of Colod (Subse which may be for Forms, www.cm).	d operations. (Clearly state of Clearly	P. Start in laiden fluud. Spot 2 e w/ mud laiden fluud. Spot 3 e w	inent details, and ginpletions: Attach was hole with work staid. Spot 50 sx. ceres 25 sx. cement @ 47 laiden fluid. POH Tag plug @ 1240'. ove off.	tring. SDFN. ment @ 5520. Pull 100'. Pull out of ce I to 3250'. Spot 2. POH to 200'. Cir ACCEPTED FO APR 2.2 Gerry Guye, Deputy MOCD-District ef. I further certify the content of the certify the certification of the certifica	f proposed colling of proposed colling of cement. Close 5 sx @ 3250 cculate 30 sx DR RECOR. 2008 7 Field Inspect 11 ARTES hat any pit or live OCD-app	ent, WOC 4 e well in for . WOC 4 hrs cement to
OTHER: 13. Describe proposed or complete starting any proposed work). So recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 10/04/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night. 4/10/08 RIH w/ tbg. and tag plug @ 12978'. POH to 1500'. surface. SDFN. 4/11/08 Cut off Well head. Weld of Approved for plug and Liability under the of C-10/3 (Subsequence) which may be forms, www.cm.	d operations. (Clearly state of the control of the	P. Start in laiden fluud. Spot 2 e w/ mud DC 4 hrs. g down me	inent details, and ginpletions: Attach was hole with work staid. Spot 50 sx. cere. S sx. cement @ 47 laiden fluid. POH Tag plug @ 1240'. ove off.	tring. SDFN. ment @ 5520. Pull '00'. Pull out of ce I to 3250'. Spot 2 POH to 200'. Cir ACCEPTED FO APR 2.2 Gerry Guye, Deputy MOCD-District lef. I further certify the an (attached) alternation.	f proposed colling for the following of the following for the foll	ent, WOC 4 e well in for . WOC 4 hrs cement to
OTHER: 13. Describe proposed or complete starting any proposed work). So recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 10/04/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night. 4/10/08 RIH w/ tbg. and tag plug @ 12978'. POH to 1500'. surface. SDFN. 4/11/08 Cut off Well head. Weld of Approved for ple Liability under the of C-10/3 (Subse which may be for Forms, www.cm.) I hereby certify that the information about has been/will be constructed or closed a SIGNATURE Type or print name	d operations. (Clearly state of the control of the	P. Start in laiden fluud. Spot 2 e w/ mud laiden fluud. Spot 3 e w	inent details, and ginpletions: Attach was hole with work staid. Spot 50 sx. cere. S sx. cement @ 47 laiden fluid. POH Tag plug @ 1240'. ove off.	tring. SDFN. ment @ 5520. Pull '00'. Pull out of ce I to 3250'. Spot 2 POH to 200'. Cir ACCEPTED FO APR 2.2 Gerry Guye, Deputy MOCD-District lef. I further certify the an (attached) alternation.	f proposed colling of proposed colling of cement. Close 5 sx @ 3250 cculate 30 sx DR RECOR. 2008 7 Field Inspect 11 ARTES hat any pit or live OCD-app	ent, WOC 4 e well in for . WOC 4 hrs cement to
OTHER: 13. Describe proposed or complete starting any proposed work). So recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 10/04/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night. 4/10/08 RIH w/ tbg. and tag plug @ 12978'. POH to 1500'. surface. SDFN. 4/11/08 Cut off Well head. Weld of Approved for plug and Liability under the of C-10/3 (Subsequence) which may be forms, www.cm.	d operations. (Clearly state of the control of the	P. Start in laiden fluud. Spot 2 e w/ mud DC 4 hrs. g down me	inent details, and ginpletions: Attach was hole with work staid. Spot 50 sx. cere. S sx. cement @ 47 laiden fluid. POH Tag plug @ 1240'. ove off.	tring. SDFN. ment @ 5520. Pull '00'. Pull out of ce I to 3250'. Spot 2 POH to 200'. Cir ACCEPTED FO APR 2.2 Gerry Guye, Deputy MOCD-District lef. I further certify the an (attached) alternation.	f proposed colling for the following of the following for the foll	ent, WOC 4 e well in for . WOC 4 hrs cement to
OTHER: 13. Describe proposed or complete starting any proposed work). So recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 10/04/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night. 4/10/08 RIH w/ tbg. and tag plug Tag plug @ 2978'. POH to 1500'. surface. SDFN. 4/11/08 Cut off Well head. Weld of Colod (Subse which may be for Forms, www.cm) I hereby certify that the information aboth has been/will be constructed or closed a SIGNATURE Type or print name For State Use Only	d operations. (Clearly state of the control of the	P. Start in laiden fluud. Spot 2 e w/ mud la down modern fluud. Spot 2 e w/ mud la down modern flues a general	inent details, and ginpletions: Attach was hole with work staid. Spot 50 sx. cere. S sx. cement @ 47 laiden fluid. POH Tag plug @ 1240'. ove off.	tring. SDFN. ment @ 5520. Pull '00'. Pull out of ce I to 3250'. Spot 2 POH to 200'. Cir ACCEPTED FO APR 2.2 Gerry Guye, Deputy MOCD-District lef. I further certify the an (attached) alternation.	f proposed colling for the following of the following for the foll	ent, WOC 4 e well in for . WOC 4 hrs cement to
OTHER: 13. Describe proposed or complete starting any proposed work). So recompletion. 4/07/08 MIRU plugging equipmer 4/08/08 Bled down well. Pump 10/04/09/08 RIH w/ workstring to 552 hrs. Tag plug @ 5000'. POH to 47 night. 4/10/08 RIH w/ tbg. and tag plug @ 12978'. POH to 1500'. surface. SDFN. 4/11/08 Cut off Well head. Weld of Approved for ple Liability under the of C-10/3 (Subse which may be for Forms, www.cm.) I hereby certify that the information about has been/will be constructed or closed a SIGNATURE Type or print name	d operations. (Clearly state of the control of the	P. Start in laiden fluud. Spot 2 e w/ mud DC 4 hrs. g down me	inent details, and ginpletions: Attach was hole with work staid. Spot 50 sx. cere. S sx. cement @ 47 laiden fluid. POH Tag plug @ 1240'. ove off.	tring. SDFN. ment @ 5520. Pull '00'. Pull out of ce I to 3250'. Spot 2 POH to 200'. Cir ACCEPTED FO APR 2.2 Gerry Guye, Deputy MOCD-District lef. I further certify the an (attached) alternation.	f proposed colling for the following of the following for the foll	ent, WOC 4 e well in for . WOC 4 hrs cement to