
Subtitit 3 Copies To Appropriate District	State of Nev	w Mexico		Form C-103
Office District I	Energy, Minerals and	Natural Resources	WELL API NO.	May 27, 2004
1625 N French Dr, Hobbs, NM 88240 District 11	OIL CONCEDUAT	TION DIVISION	30-015-33977	
1301 W Grand Ave, Artesia, NM 88210 District III	OIL CONSERVAT 1220 South St.		5. Indicate Type of Lease	
1000 Rio Brazos Rd, Aztec, NM 87410	Santa Fe, N		STATE 6. State Oil & Gas Lease	FÉE
District IV 1220 S St Francis Dr, Santa Fe, NM	Sullu I o, II.		V-7113	
87505 SUNDRY NOTI	CES AND REPORTS ON W	/ELLS	7. Lease Name or Unit A	greement Name
(DO NOT USE THIS FORM FOR PROPOS	SALS TO DRILL OR TO DEEPEN	OR PLUG BACK TO A		
DIFFERENT RESERVOIR USE "APPLIC PROPOSALS)	<u></u>	ivi) FOR SUCH	Gila State 8. Well Number 1	
	Gas Well 🛛 Other	MAY 2 1 2008	9. OGRID Number	
2. Name of Operator Mack Ener	gy Corporation	AND ADTERNIO		3837
3. Address of Operator	<u> </u>	OUU-ARIESIA	I 0. Pool name or Wildca	t
	960 Artesia, NM 88211-09	960	Penasco Draw;Permo Per	nn
4. Well Location	1980 feet from the	North line and	660 feet from the	East line
17	1980 feet from the		rect from the	E.J.J.
Section	1 1. Elevation (Show whethe			
The state of the s	,	3800'		
Pit or Below-grade Tank Application o				
			Distance from nearest surface water	· <u></u>
Pit Liner Thickness: mɪl	Below-Grade Tank: Volume	,	Construction Material	
12. Check A	ppropriate Box to Indica	ate Nature of Notic	e, Report or Other Data	
NOTICE OF IN	TENTION TO:	SL	JBSEQUENT REPORT	ΦF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON		<u>=</u>	RING CASING
TEMPORARILY ABANDON	CHANGE PLANS	=	ORILLING OPNS. P AND	A L
PULL OR ALTER CASING L	MULTIPLE COMPL	_ CASING/CEME	ENT JOB	
OTHER		OTHER:		
 Describe proposed or comp of starting any proposed we or recompletion. 			and give pertinent dates, inclu Attach wellbore diagram of pr	
Notify OCD 24 hours prior to start	ing plugging operations			
1) Set 50sx cmt at 6215'-6065', Ta	3			
2) Set 25sx cmt plug at 5000' -485	· · · · · · · · · · · · · · · · · · ·			
3) Set 25sx cmt plug at 3700'-3550	` ,		A82.440	
4) Set 40sx cmt plug at 1270'-1150 5) Perforate at 100' and circulate to			MOTHY OCD	24 hrs notes
6) Install P & A Marker.	Surface.		Notify OCD To any wo	Yk done
Note: Circ. well with salt gel mud		Brine with 25 pounds	*	wy (10116)
of gel per barrel after the bottom p No pit will be used all contents con		auled to an approved f	acility	
The part was de disea an contents con	numed in steel tanks and na	and to an approved i	ucinty.	
	We a			
I hereby certify that the information a grade tank has been/will be constructed or	bove is true and complete to the closed according to NMOCD guid	the best of my knowledg delines 🔲, a general permit	ge and belief. I further certify the or an (attached) alternative OC	nat any pit or below- D-approved plan
SIGNATURE Jerry W.		TLE Production Clerk		5/20/08
Type or print name Jerry W. Sherre For State Use Only	II E-mai	iil address: <u>jerrys@</u> mac	kenergycorp.com Telephor	No. <u>(575)748-1288</u>
APPROVED BY: Conditions of Approval (if any):	TIT	TLE Corplin of	DATE.	5/23/08

1 7

Mack Energy Corporation

Gila State #1 30-015-33977



- 1) Set 50sx cmt at 6215'-6065', Tag
- 2) Set 25sx cmt plug at 5000' -4850' (Wolfcamp)
- 3) Set 25sx cmt plug at 3700'-3550' (Abo)
- 4) Set 40sx cmt plug at 1270'-1150' (tag)
- 5) Perforate at 100' and circulate to surface.
- 6) Install P & A Marker.

Note: Circ. well with salt gel mud consisting of at least 9.5# Brine with 25 pounds of gel per barrel after the bottom plug is set.