
Subtitit 3 Copies To Appropriate District State	State of New Mexico		Form C-103
Office District I Energy, Miner	Energy, Minerals and Natural Resources		May 27, 2004
1625 N French Dr , Hobbs, NM 88240 District [1]	WELL API NO. 30-015-33978		
1301 W Grand Ave, Artesia, NM 88210 OIL CONSE	10 OIL CONSERVATION DIVISION 5		
District III 1220 South St. Francis Dr.			EE 🗌
District IV Santa	i Fe, NM 87505	6. State Oil & Gas Lease N	0.
1220 S St Francis Dr , Santa Fe, NM 87505		V-7113	
SUNDRY NOTICES AND REPORTS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (I	DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agr San Juan State Com	eement Name
PROPOSALS)	MAY 2 1 2008	8. Well Number 1	
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator Mark France Comments on the second of	OCD-ARTESIA	9. OGRID Number	227
Mack Energy Corporation 3. Address of Operator	000 - 100 00 000	I 0. Pool name or Wildcat	537
P. O. Box 960 Artesia, NM 88	211-0960	Penasco Draw;Permo Penn	
4. Well Location			
Unit Letter P 660 feet from	the South line and	feet from the	East
Section Township	18S	NMPM County	Eddy
I 1. Elevation (Show	whether DR, RKB, RT, GR, etc		
3764' GR Pit or Below-grade Tank Application or Closure			
	n nearest fresh water well Di	stance from nearest surface water	
Pit typeDepth GroundwaterDistance from nearest fresh water wellDistance from nearest surface water Pit Liner Thickness:mil Below-Grade Tank: Volumebb1s; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
12. Check Appropriate Box it	marcate nature of notice	, Report or Other Data	
NOTICE OF <u>IN</u> TENTION TO: SUBSEQUENT <u>REPORT OF:</u>			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JOB			
PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEME	11 JOB	
OTHER:	OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
Notify OCD 24 hours prior to starting plugging operations			
1) Set 30sx cmt plug from 6210' to 6030' (tag) 2) Set 25sx cmt plug at 5000' (Wolfcamp)			
3) Set 25sx cmt plug @ 3700' (Abo)			
4) RIH w/ cmt bond log and find TOC (est TOC 1100'), cut 7" 23# J-55 csg. and POH.			
5) 8 th and when from 12601 to 501 above against and affi	•		
5) Set cmt plug from 1260' to 50' above casing cut-off	point. (tag)		
6) Set 30sx cmt plug from 90' to surface.	point. (tag)	Moths OCD	24 hrs. prio
	point. (tag)		24 hrs. prio
6) Set 30sx cmt plug from 90' to surface.7) Install P & A Marker.		To any w	24 hrs. prio ork done.
6) Set 30sx cmt plug from 90' to surface.		To any w	
 6) Set 30sx cmt plug from 90' to surface. 7) Install P & A Marker. Note: 1) Circ. well with salt gel mud consisting of at le of gel per barrel after the bottom plug is set. 2) If TOC is greater than 900' do not cut and pull, inste 	east 9.5# Brine with 25 pounds	To any w	
 6) Set 30sx cmt plug from 90' to surface. 7) Install P & A Marker. Note: 1) Circ. well with salt gel mud consisting of at le of gel per barrel after the bottom plug is set. 2) If TOC is greater than 900' do not cut and pull, instal 1260'-1110' (tag) and perf 7" csg. at 90' and circ cmt to the surface of the surfac	east 9.5# Brine with 25 pounds ead set a 25sx cmt plug from o surface.	To any w	
 6) Set 30sx cmt plug from 90' to surface. 7) Install P & A Marker. Note: 1) Circ. well with salt gel mud consisting of at le of gel per barrel after the bottom plug is set. 2) If TOC is greater than 900' do not cut and pull, inste 	east 9.5# Brine with 25 pounds ead set a 25sx cmt plug from o surface.	To any w	
 6) Set 30sx cmt plug from 90' to surface. 7) Install P & A Marker. Note: 1) Circ. well with salt gel mud consisting of at least of gel per barrel after the bottom plug is set. 2) If TOC is greater than 900' do not cut and pull, instal 1260'-1110' (tag) and perf 7" csg. at 90' and circ cmt to No pit will be used all contents contained in steel tanks 	east 9.5# Brine with 25 pounds ead set a 25sx cmt plug from o surface. and hauled to an approved fac	To any we	ork done.
 6) Set 30sx cmt plug from 90' to surface. 7) Install P & A Marker. Note: 1) Circ. well with salt gel mud consisting of at le of gel per barrel after the bottom plug is set. 2) If TOC is greater than 900' do not cut and pull, instal 1260'-1110' (tag) and perf 7" csg. at 90' and circ cmt to the surface of the surfac	east 9.5# Brine with 25 pounds ead set a 25sx cmt plug from o surface. and hauled to an approved facelete to the best of my knowledge	To any we sility.	ork done.
6) Set 30sx cmt plug from 90' to surface. 7) Install P & A Marker. Note: 1) Circ. well with salt gel mud consisting of at le of gel per barrel after the bottom plug is set. 2) If TOC is greater than 900' do not cut and pull, instal 1260'-1110' (tag) and perf 7" csg. at 90' and circ cmt to No pit will be used all contents contained in steel tanks. I hereby certify that the information above is true and compared tank has been/will be constructed or closed according to NMC SIGNATURE	east 9.5# Brine with 25 pounds ead set a 25sx cmt plug from o surface. and hauled to an approved facelete to the best of my knowledge	To any we sility.	any pit or belowapproved plan
6) Set 30sx cmt plug from 90' to surface. 7) Install P & A Marker. Note: 1) Circ. well with salt gel mud consisting of at le of gel per barrel after the bottom plug is set. 2) If TOC is greater than 900' do not cut and pull, instal 1260'-1110' (tag) and perf 7" csg. at 90' and circ cmt to No pit will be used all contents contained in steel tanks. I hereby certify that the information above is true and compared tank has been/will be constructed or closed according to NMC SIGNATURE	east 9.5# Brine with 25 pounds ead set a 25sx cmt plug from o surface. and hauled to an approved factoric to the best of my knowledge DCD guidelines , a general permit	ility. and belief. I further certify that or an (attached) alternative OCD-	any pit or below-approved plan []
6) Set 30sx cmt plug from 90' to surface. 7) Install P & A Marker. Note: 1) Circ. well with salt gel mud consisting of at le of gel per barrel after the bottom plug is set. 2) If TOC is greater than 900' do not cut and pull, instal 1260'-1110' (tag) and perf 7" csg. at 90' and circ cmt to No pit will be used all contents contained in steel tanks. I hereby certify that the information above is true and compared tank has been/will be constructed or closed according to NMO.	east 9.5# Brine with 25 pounds ead set a 25sx cmt plug from o surface. and hauled to an approved factoric to the best of my knowledge DCD guidelines , a general permit	ility. and belief. I further certify that or an (attached) alternative OCD-	any pit or belowapproved plan
6) Set 30sx cmt plug from 90' to surface. 7) Install P & A Marker. Note: 1) Circ. well with salt gel mud consisting of at le of gel per barrel after the bottom plug is set. 2) If TOC is greater than 900' do not cut and pull, instal 1260'-1110' (tag) and perf 7" csg. at 90' and circ cmt to No pit will be used all contents contained in steel tanks. I hereby certify that the information above is true and comparade tank has been/will be constructed or closed according to NMC SIGNATURE Type or print name Jerry W. Sherrell	east 9.5# Brine with 25 pounds ead set a 25sx cmt plug from o surface. and hauled to an approved factoric to the best of my knowledge DCD guidelines , a general permit	ility. and belief. I further certify that or an (attached) alternative OCD-	any pit or below-approved plan []

Mack Energy Corporation

San Jaun State Com #1 30-015-33978



- 1) Set 30sx cmt plug from 6210' to 6030' (tag)
- 2) Set 25sx cmt plug at 5000' (Wolfcamp)
- 3) Set 25sx cmt plug @ 3700' (Abo)
- 4) RIH w/ cmt bond log and find TOC (est TOC 1100"), cut 7" 23# J-55 csg. and POH.
- 5); Set cmt plug from 1260' to 50' above casing cut-off point. (tag)
- 6) Set 30sx cmt plug from 90' to surface.
- 7) Install P & A Marker.

- Note: , 1) Circ. well with salt gel mud consisting of at least 9.5# Brine with 25 pounds of gel per barrel after the bottom plug is set.
 - 2) If TOC is greater than 900' do not cut and pull, instead set a 25sx cmt plug from 1260'-1110' (tag) and perf 7" csg. at 90' and circ cmt to surface.