
Submit 3 Copies To Appropriate District Office	State of New Me		SFP 23 2009	Form C-103 June 19, 2008
District I 1625 N French Dr , Hobbs, NM 88240	Energy, Minerals and Natur	rai Resources	WELL API NO.	June 19, 2008
District II 1301 W Grand Ave, Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-22893 5. Indicate Type of Lea	ase
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410 District IV	1220 South St. Francis Dr. Santa Fe, NM 87505		STATE State Oil & Gas Lea	FEE
1220 S. St. Francis Dr., Santa Fe, NM 87505	,		B-1111	SC 110.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)			7. Lease Name or Unit Lucas Store KT State	Agreement Name
1. Type of Well: Oil Well Gas Well Other			8. Well Number 1	
2. Name of Operator Yates Petroleum Corporation			9. OGRID Number 025575	
3. Address of Operator 105 South Fourth Street, Artesia, NM 88210			10. Pool name or Wild Wildcat; Abo	cat
4. Well Location Unit Letter G: 1980 feet from the North line and 1980 feet from the East line				
Section 22	Township 17S Ran		NMPM Eddy	County
	11. Elevation (Show whether DR, 3592)		tc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE	TENTION TO: PLUG AND ABANDON ⊠ CHANGE PLANS □ MULTIPLE COMPL □	REMEDIAL WO	BSEQUENT REPORD ORK ALTE ORILLING OPNS. D. P. AN ENT JOE NOTIFY OCD. TO GNY WO	ERING CASING DE LOS DELOS DE LOS DE LOS DE LOS DE LOS DE LOS DE LOS DELOS DE LOS DELOS DE LOS DELOS DE LOS DELOS
OTHER:		OTHER:	•	
of starting any proposed we	oleted operations. (Clearly state all pork). SEE RULE 1103. For Multiple			
1. MIRU all H2S safety equipment 2. Perforate 4 squeeze holes at 5620 the Abo top. WOC and tag plug, res 3. Perforate 4 squeeze holes at 3804 the Glorieta top. WOC and tag plug 4. Perforate 4 squeeze holes at 2150 the intermediate casing shoe. WOC 5. Perforate 4 squeeze holes at 450 This will leave a plug across the sur 6. Perforate 4 squeeze holes at 150 This will leave a solid cement plug 7. Remove all surface equipment ar	4'. Squeeze with 50 sx Class "C" cer g, reset if necessary. 0'. Squeeze with 50 sx Class "C" cer	be attempted. ment and displacement and	e it down to 3704'. This wi e it down to 2050'. This wi ass "C" cement and displace try.	Il leave a plug across Il leave a plug across e it down to 350'.
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE TITLE Regulatory Compliance Supervisor DATE September 21, 2009				
Type or print name For State Use Only	rta E-mail address: tınah@		d providing work	575-748-4168
APPROVED BY: Conditions of Approval (if any):	ohe TITLE	is complete by	DATE	10/7/09



DC/Hill