

ict I
.25 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

001 05 2009

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

x Initial Report ☐ Final Report

Name of Company Basic Energy Services 246368	Contact David Alvarado
Address P.O. Box 10460 MIDLAND TX. 79702	Telephone No. 575.746.9663
Facility Name MYRTLE MYRA SWD CCI	Facility Type

Surface Owner STATE	Mineral Owner	Lease No. 3001521515
---------------------	---------------	----------------------

30-015-21515

LOCATION OF RELEASE

Unit Letter C	Section 21	Township 21S	Range 27E	Feet from the 660	North/South Line NORTH	Feet from the 1980	East/West Line WEST	County EDDY
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release PRODUCED WATER WITH IRON SULFATE	Volume of Release 600 BBLS	Volume Recovered 590 BBLS
Source of Release SUCTION SIDE OF PUMP FROM TANK	Date and Hour of Occurrence 10-2-09 UNDETERMAN TIME	Date and Hour of Discovery 10-2-09 7:30 AM.
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? JERRY HANAWAY, DAVID ALVARADO, ROGER MASSEY, LYN SOCLWELL	
By Whom? RICHARD PENA	Date and Hour 10-2-09 7:30 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse. NONE	

If a Watercourse was Impacted, Describe Fully.*

NO WATERCOURSE IMPACTED.

Describe Cause of Problem and Remedial Action Taken.*


4" Clamp broke on suction side of fluid end and separated when charge pump turned on..

Vacuum Truck was used to recover 590 bbls. and placed back in the storage tanks. Will have a blade scrape up material send to CRI.


Describe Area Affected and Cleanup Action Taken.*

South side and west side of location was affected. Before we can blade location gas lines are to be flagged.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 
Printed Name: David H. Alvarado

OIL CONSERVATION DIVISION

Approved by District Supervisor: 

Remediation Actions to be completed as
Final C-141 submitted with confirmation
analyses/documentation on or before
Expiration Date.

Title: S.E.N.M. DISTRICT MANAGER

Approval Date: 10-26-09

Expiration Date: 12-31-09

E-mail Address: david.alvarado@basicenergyservices.com

Conditions:

SEE ATTACHED
STIPULATIONS

Attached ☒

2RP-358

USE 0930036710
n 093003677
3EB093037000