

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
811 South First, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, New Mexico 87505

WELL API NO. 30-015-01599
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1111
7. Lease Name or Unit Agreement Name Red Lake Sand Unit
8. Well No. 6
9. Pool name or Wildcat Red Lake; Queen-Grayburg-SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3631' GR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS).	
1. Type Of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	RECEIVED JAN 12 2004 OCD-ARTESIA
2. Name of Operator Mack Energy Corporation	
3. Address of Operator P.O. Box 960, Artesia, NM 88211-0960	
4. Well Location Unit Letter <u>E</u> : <u>1650</u> Feet From The <u>North</u> Line and <u>330</u> Feet From The <u>West</u> Line Section <u>28</u> Township <u>17S</u> Range <u>28E</u> NMPM <u>Eddy</u> County	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Mack Energy Corporation proposes to plug and abandon well as follows:

1. Notify OCD 24 hours prior to starting plugging operations.
2. Set 100' cement plug from 1734-1634'. WOC and tag.
3. Circulate hole with mud gel.
4. Perforate @ 165' squeeze 100' cement above and below 8 5/8 casing. WOC and tag.
6. Perforate @ 60' circulate cement to surface. - Both csq. strings - inside & out w/ent. - WOC-24 HRS TAG
7. Install dry hole marker.

* Perf csq. @ 480' - Place 100' of cnt. inside & outside of csq
380' - 480'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry W. Sherrell TITLE Production Clerk DATE 1/12/2004

TYPE OR PRINT NAME Jerry W. Sherrell TELEPHONE NO. _____

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep ID DATE JAN 23 2004

CONDITIONS OF APPROVAL, IF ANY:

STATE

MACK ENERGY CORPORATION
RED LAKE SAND UNIT #6
Sec 28 T17S R28E 1650FNL 330FWL

'8 5/8"-28#

1. Notify BLM 24 hrs. prior to any work done.
2. Set 100' cmt plug 1734-1634' and tag.
3. Circ hole with mud gel.
4. Perf @ 165' squeeze 100' cmt plug 50' above & below 8 5/8" and tag.
5. Perf @ 60' circ cmt to surface
6. Install Dry Hole Marker

8 5/8"-28# Set @ 115' w/50sks

7" -20# Set @ 1684' w/100sks

OPEN HOLE 1684'-1995'