



BOPCO, LP  
NMLC-070220: Big Eddy Unit #10  
API: 30-015-10785  
Eddy County, New Mexico

RE: Plug back and Recomplete NOI – Conditions of Approval

**Contact the appropriate BLM office at least 24 hours prior to the commencing of any recompletion operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.**

There is to be no surface disturbance beyond the existing pad. A closed loop system is to be used. H2S monitoring and protection equipment is to be on site.

3M BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.

Before perforating the Delaware, the well must be plugged back as follows:

1. Dump bail 35' or pump 25sx of Class H cement on top of CIBP at 11,330'. (Perfs)
2. Spot a 200' plug (minimum 25sx) of Class H from 10502'-10302'. (Wolfcamp)
3. Perforate and squeeze a 180' plug (minimum 25sx) from 7085'-6905'. WOC and tag at 6905' or shallower. (Bone Springs)

Submit subsequent report and completion report once work is completed.

**A commercial well determination will need to be submitted after production has been established for at least six months.**

DHW 030310