orm 9-331	1						ureau No. 4	
May 1963)	DEPARTM		INTERIO	(Other instructions on verse side)	0	LASE DEFIGNAT	ION AND BE	RIAL-10
	GI	L_OGICAL SU	RVEY	·		M 87 Indian, allo'	TTEE OR TR	IBB NAME
CUNI	NOTIO	CES AND REF	ORTS ON	1 WELLS				
(Do not use this i					_			
					7. U	7. UNIT AGREEMENT NAME		
		Dry Hole						
WELL WELL I 2. NAME OF OPERATOR	OTHER					ARM OR LEASE		
Read & Stevens	s. Inc. A	gent for Mus	grave & Th	nomas		ams Ranc	<u>h</u>	<u></u>
OF INDRESS OF OPERATOR		-					-	-
P. O. Box 1518, Roswell, New Mexico 88201 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*					<u>10.</u>	10. FIELD AND POOL, OR WILDCAT		
4. LOCATION OF WELL (R See also space 17 belo	eport location C.	early and in accordan			l v	vildcat		
At surface					11.	BBC., T., R., M., BURVEY OR	OR BLK. AN	D
	' FN & WL					· ·	5	2
660	FIN & HL					Section 7	7-145-2	9E
14. PERMIT NO.		15. ELEVATIONS (She		T, GR, etc.)			N	
		3638.				Chaves		
16.	Check Ap	propriate Box To	Indicate Na	ture of Notice, Report,	or Other	Data		
	NOTICE OF INTEN		1	BU	BEEQUENT	REPORT OF:		
	[]			WATER SHUT-OFF		REPAIR	ING WELL	
TEST WATER SHUT-O	·····	PULL OB ALTER CASING		FRACTURE TREATMENT		-	ING CABING	X
FRACTURE TREAT	<u> </u>]	ABANDON*		SHOOTING OR ACIDIZING		ABANDO	ONMENT [®]	
SHOOT OB ACIDIZE	[]	CHANGE PLANS		(Other)(Norg: Report r	esults of m	ultiple comple	etion on W	-[] ell
				A	completiou	I Webort and w		
nent to this work.)		whing in hol	e tagged	details, and give pertinent ons and measured and true	dates, inclu vertical dep rilled	uding estimate ptbs for all m Out to 2	254'.	tarting a zones per
10/21/80, ra Per instruct Job complete	n 2 7/8" t ions from on 10/22,	tubing in hol	e, tagged		dates, incluventical dep rilled m 254'	out to 2 to surfa	25 4'. ace.	
10/21/80, ra	n 2 7/8" t ions from on 10/22,	tubing in hol	e, tagged	details, and give pertinent ons and measured and true fill @ 200'. Do 00 sx. cement from	dates, incluventical dep rilled m 254'	out to 2 to surfa notify v	25 4'. ace.	
10/21/80, ra Per instruct Job complete	n 2 7/8" t ions from on 10/22,	tubing in hol	e, tagged	details, and give pertinent ons and measured and true fill @ 200'. Do 00 sx. cement from	dates, incluventical dep rilled m 254'	out to 2 to surfa notify v	254'. ace. when	
10/21/80, ra Per instruct Job complete	n 2 7/8" t ions from on 10/22,	tubing in hol	e, tagged	details, and give pertinent ons and measured and true fill @ 200'. Do 00 sx. cement from	dates, incluventical dep rilled m 254'	out to 2 to surfa notify v	254'. ace. when	
10/21/80, ra Per instruct Job complete	n 2 7/8" t ions from on 10/22,	tubing in hol	e, tagged	details, and give pertinent ons and measured and true fill @ 200'. Do 00 sx. cement from	dates, incluventical dep rilled m 254'	out to 2 to surfa notify v	254'. ace. when	
10/21/80, ra Per instruct Job complete	n 2 7/8" t ions from on 10/22,	tubing in hol	e, tagged	details, and give pertinent ons and measured and true fill @ 200'. Do 00 sx. cement from	dates, incluventical dep rilled m 254'	out to 2 to surfa notify v	254'. ace. when	
10/21/80, ra Per instruct Job complete	n 2 7/8" t ions from on 10/22,	tubing in hol	e, tagged	details, and give pertinent ons and measured and true fill @ 200'. Do 00 sx. cement from	dates, incluventical dep rilled m 254'	out to 2 to surfa notify v	254'. ace. when	
10/21/80, ra Per instruct Job complete	n 2 7/8" t ions from on 10/22,	tubing in hol	e, tagged	details, and give pertinent ons and measured and true fill @ 200'. Do 00 sx. cement from	dates, incluventical dep rilled m 254'	out to 2 to surfa notify v	254'. ace. when	
10/21/80, ra Per instruct Job complete	n 2 7/8" t ions from on 10/22, spection.	tubing in hol the U.S.G.S. /80. Prep to	e, tagged , circ. 9 o install	details, and give pertinent ons and measured and true fill @ 200'. Do 00 sx. cement from	dates, incluventical dep rilled m 254'	uding estimate ptbs for all m out to 2 to surfa notify v	254'. ace. when	
10/21/80, ra Per instruct Job complete ready for in	n 2 7/8" t ions from on 10/22, spection.	tubing in hol the U.S.G.S. /80. Prep to	e, tagged , circ. 9 o install	details, and give pertinent ons and measured and true i fill @ 200'. Do 00 sx. cement from dry hole marker.	dates, incluventical dep rilled m 254'	out to 2 to surfa notify v	254'. ace. when 1980	
10/21/80, ra Per instruct Job complete ready for in	n 2 7/8" t ions from on 10/22, spection.	tubing in hol the U.S.G.S. /80. Prep to	e, tagged , circ. 9 o install	details, and give pertinent ons and measured and true i fill @ 200'. Do 00 sx. cement from dry hole marker.	dates, incluventical dep rilled m 254'	out to 2 to surfa notify v	254'. ace. when 1980	
10/21/80, ra Per instruct Job complete ready for in	at the foregoing	is true and correct	e, tagged , circ. 9 o install	details, and give pertinent ons and measured and true i fill @ 200'. Do 00 sx. cement from dry hole marker.	dates, incluventical dep rilled m 254'	uding estimate ptbs for all m out to 2 to surfa notify v	254'. ace. when 1980	

*See Instructions on Reverse Side

-