Submit 3 Copies to Appropriate District Office State of New Mexico rais and Natural Resources Department

LOCATION CLEAN AND READY FOR INSPECTION.

OSÉPH J. KELLY

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TYPE OR PRINT NAI

(This space for State Use)

APPROVED BY

CONDITIONS OF APPROV

CISI	
γ°	

Form C-103 Revised 1-1-39

4/9/99

505-623-3190

TELEPHONE NO.

OIL CONSERVATION DIVISION DISTRICT I 2040 South Pacheco WELL API NO. P.O. Box 1980, Hobbs, NM 88241-1980 Santa Fe, New Mexico 87505 30-005-60413 DISTRICT II 5. Indicate Type of Lease 811 S. First Street, Artesia, NM 88210 STATE X FEE DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 L-24 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: OIL GAS DEXTER STATE WELL WELL OTHER Name of Operator ; 8 Well No **ELK OIL COMPANY** 9. Pool Name or Wildcat 3. Address of Operator POST OFFICE BOX 310, ROSWELL, NEW MEXICO 88202-0310 DEXTER SAN ANDRES 4. Well Location NORTH WEST Line Feet From The Unit Letter Line and Feet From The 12 SOUTH 26 EAST CHAVES 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3528.1' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PTUG AND ABANDON ALTERING CASING REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103 PLUG AND ABANDON WELL AS FOLLOWS: 06/20/97: SPOT 40 SXS @ 1188' - 1068' TAGGED. 06/23/97: PERFORATE @ 365' - SQUEEZED 90 SXS TAGGED @ 130'. 06/24/97: SPOT 20 SXS @ 130' TO SURFACE. INSTALL DRY HOLE MARKER. CIRCULATE HOLE WITH 10# MUD.

PRESIDENT

Till Res

TITLE