	1000 per		Capy to S	
	OCC COPY	4		
Form 9-331 (May 1963)	UNITED STATES	SUBMIT IN TRIPLICATE*	Form approved. Budget Bureau No. 42R1424.	
(May 1900)	DEPARTMENT OF THE INTER	RIOR (Other instructions on re- verse side)	5. LEASE DESIGNATION AND SERIAL NO.	
	GEOLOGICAL SURVEY		NM 0558973	
CLD			6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
	NDRY NOTICES AND REPORTS is form for proposals to drill or to deepen or plug Use "APPLICATION FOR PERMIT_" for such			
			7. UNIT AGREEMENT NAME	
OIL GAS WELL WELL	X OTHER DRY	RECEIVED		
2. NAME OF OPERATOR		8. FARM OR LEASE NAME		
	e and B. N. Muncy, Jr.	Lillie Federal		
3. ADDRESS OF OPERATO			9. WELL NO.	
P 0 Box 196			5	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements). See also space 17 below.)			10. FIELD AND POOL, OR WILDCAT	
A surface		ARTESIA, OFFICE	Wildcat	
0 FSL and 1980 FWL Section 20, T 14S, R 28E			11. SEC., T., R., M., OR BLK. AND SUBVEY OR ABEA	
14. PERMIT NO.	15. ELEVATIONS (Show whether 3534.05 GI	,	Section 20, T 14S, R 28E 12. COUNTY OF PARISH 13. STATE Chaves NM	
в.	Check Appropriate Box To Indicate	Nature of Notice, Report, or C	Other Data	
	NOTICE OF INTENTION TO :	SUBSEQU	UENT REPORT OF:	
TEST WATER SHUT-	OFF PULL OF ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	
TEST WATER SHUT- FRACTURE TREAT	OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	
TEST WATER SHUT- Fracture treat Shoot ob acidize			-	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING	
FRACTURE TREAT Shoot or acidize	MULTIPLE COMPLETE	FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (NOTE: Report results	ALTERING CASING ABANDONMENT [•] Plug Book X.	
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED (MULTIPLE COMPLETE ABANDON [•] CHANGE PLANS Plug back OR COMPLETED OPERATIONS (Clearly state all pertin If well is directionally drilled, give subsurface lo	FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (NOTE: Report results Completion or Recomplement details, and give pertipent dates,	ALTERING CASING ABANDONMENT [®] Plug Book X. s of multiple completion on Well letion Report and Log form.) , including estimated date of starting any	
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE TROPOSED O proposed work. nent to this work. Propose to p	MULTIPLE COMPLETE ABANDON [•] CHANGE PLANS Plug back OR COMPLETED OPERATIONS (Clearly state all pertin If well is directionally drilled, give subsurface lo	FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (NOTE: Report results Completion or Recombinent details, and give pertinent dates, cations and measured and true vertices 50 sacks cement plug f	ALTERING CASING ABANDONMENT [®] Plug Book X. s of multiple completion on Well letion Report and Log form.) , including estimated date of starting any al depths for all markers and zones perti- from 8425 [°] - 8575; 50 sack	
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED O proposed work. 1 nent to this work. Propose to p cement plug	MULTIPLE COMPLETE ABANDON. CHANGE PLANS Plug back OR COMPLETED OPERATIONS (Clearly state all pertin If well is directionally drilled, give subsurface lo D8737 plug back to 2980' by setting	FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (NOTE: Report results Completion or Recompl tent details, and give pertinent dates, cations and measured and true vertice 50 sacks cement plug from 6300'	ALTERING CASING ABANDONMENT [•] Plug Book X. s of multiple completion on Well letton Report and Log form.) , including estimated date of starting any al depths for all markers and zones perti- from 8425 [•] - 8575; 50 sack - 6450 [•] , 50 sack cement p	
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED O proposed work. 1 nent to this work. Propose to p cement plug from 5100'-4	MULTIPLE COMPLETE ABANDON. CHANGE PLANS Plug back OR COMPLETE DOPERATIONS (Clearly state all pertin If well is directionally drilled, give subsurface low TD 8737 plug back to 2980' by setting from 7200' - 7350', 50 sack of	FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (NOTE: Report results Completion or Recompletion completion or Recompletions and measured and true vertices 50 sacks cement plug from 6300° cement plug from 6300° om 4350° -4500°, 35 sack	ALTERING CASING ABANDONMENT [®] Plug Book X. s of multiple completion on Well letton Report and Log form.) , including estimated date of starting any al depths for all markers and zones perti- from 8425 [°] - 8575; 50 sack - 6450 [°] , 50 sack cement p	

RECEIVED MAR 17 1978 U.S. GEULUGICAL SURVEY ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct			
SIGNED Alleng	TITLE Operator	DATE	3/14/78
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY :	TITLE ACTING DISTRICT ENGINEER	DATE	MAR 2 0 1978

*See Instructions on Reverse Side