Submit 3 Copies To Appropriate District State of New Mex	
District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 South First, Artesis, NM 88210 OIL CONSERVATION	WELL API NO . 30-005-60520
	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV South Pach	505 STATE C FEE C
2040 South Pacheco, Santa Echility 87505ESIA	6. State Oil & Gas Lease No. K-2114
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO PROPOSALS.)	IG BACK TO A R SUCH LER 16
1. Type of Well: Oil Well 🖾 Gas Well 🗔 Other	
2. Name of Operator	8. Well No.
Fred F. Pool, III / 3. Address of Operator	9
P.O. Box 132 Roswell, NM 88202	9. Pool name or Wildcat Chisum San Andres, East
4. Well Location	
Unit Letter K : 2200 feet from the south	line and 1650 feet from the west line
Section 16 Township 11S Rar	
10. Elevation (Show whether DR 3676 GR	, RKB, RT, GR, etc.)
11. Check Appropriate Box to Indicate Na	ture of Notice, Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. C PLUG AND
PULL OR ALTER CASING UMULTIPLE COMPLETION	CASING TEST AND
COMPLETION OTHER: 12. Describe proposed or completed operations. (Clearly state all pertion of starting any proposed work). SEE RULE 1103. For Multiple Co	CASING TEST AND ABANDONMENT CEMENT JOB CEMENT JOB CEMER: Casing Integrity Test Casing Cas
COMPLETION OTHER: 12. Describe proposed or completed operations. (Clearly state all pertion of starting any proposed work). SEE RULE 1103. For Multiple Construction or recompilation. 11/17/01 Rig up wireline truck and 1)	CASING TEST AND ABANDONMENT CEMENT JOB CEMENT JOB CEMER: Casing Integrity Test Casing Cas
COMPLETION OTHER: 12. Describe proposed or completed operations. (Clearly state all pertions of starting any proposed work). SEE RULE 1103. For Multiple Co or recompilation. 11/17/01 Rig up wireline truck and 1) 2) Set CIBP at 1990 feet. (Fill	ABANDONMENT ABANDON ABANDO
COMPLETION OTHER: 12. Describe proposed or completed operations. (Clearly state all pertions of starting any proposed work). SEE RULE 1103. For Multiple Co or recompilation. 11/17/01 Rig up wireline truck and 1) 2) Set CIBP at 1990 feet. (F 11/20/01 Loaded casing with 16 bbls.	ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Casing Integrity Test inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion Run 8 5/8", 24# Gauge ring to 2040 fee- luid level was at 275' from surface. H20 with packer fluid and pressure test surfaces with no pressure drop.
COMPLETION OTHER: Image: Completed operations Clearly state all pertions 12. Describe proposed or completed operations. (Clearly state all pertions of starting any proposed work). SEE RULE 1103. For Multiple Completion. 11/17/01 11/17/01 Rig up wireline truck and 1) 2) 2) Set CIBP at 1990 feet. (F 11/20/01 Loaded casing with 16 bbls. casing to 500 psi for 38 min TA status is hereby requested. Plug state	ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Casing Integrity Test inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion Run 8 5/8", 24# Gauge ring to 2040 fee- luid level was at 275' from surface. H20 with packer fluid and pressure test surfaces with no pressure drop.
OTHER: Image: Complete operation of starting any proposed or completed operations. (Clearly state all pertion of starting any proposed work). SEE RULE 1103. For Multiple Completion. 11/17/01 Rig up wireline truck and 1) 2) Set CIBP at 1990 feet. (F 11/20/01 Loaded casing with 16 bbls. casing to 500 psi for 38 min TA status is hereby requested. Plug stare enclosed.	ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Casing Integrity Test inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion Run 8 5/8", 24# Gauge ring to 2040 fee- luid level was at 275' from surface. H20 with packer fluid and pressure test surfaces with no pressure drop.
OTHER: Image: Completed operations 12. Describe proposed or completed operations. (Clearly state all pertion of starting any proposed work). SEE RULE 1103. For Multiple Completion. 11/17/01 Rig up wireline truck and 1) 2) Set CIBP at 1990 feet. (F 11/20/01 Loaded casing with 16 bbls. casing to 500 psi for 38 min TA status is hereby requested. Plug state are enclosed.	ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Casing Integrity Test inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion Run 8 5/8", 24# Gauge ring to 2040 fee- luid level was at 275' from surface. H20 with packer fluid and pressure test sutes with no pressure drop. Setting record and pressure test chart
OTHER: Image: Complete operation of starting any proposed work). SEE RULE 1103. For Multiple Complete or recompilation. 11/17/01 Rig up wireline truck and 1) 2) Set CIBP at 1990 feet. (F 11/20/01 Loaded casing with 16 bbls. casing to 500 psi for 38 min TA status is hereby requested. Plug stare enclosed. Temporary Abandoned Status approved 11 + 20 - 0 + Thereby certify that the information above is true and complete to the best SIGNATURE	ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Casing Integrity Test inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion Run 8 5/8", 24# Gauge ring to 2040 fee- luid level was at 275' from surface. H20 with packer fluid and pressure test sutes with no pressure drop. Setting record and pressure test chart
OTHER: Image: Complete operation of starting any proposed work). SEE RULE 1103. For Multiple Complete of starting any proposed work). SEE RULE 1103. For Multiple Complete or recompilation. 11/17/01 Rig up wireline truck and 1) 2) Set CIBP at 1990 feet. (F 11/20/01 Loaded casing with 16 bbls. casing to 500 psi for 38 min TA status is hereby requested. Plug stare enclosed. Temporary Abandoned Status approved und 11 20 - 64 Imporary Abandoned Status approved und 11 20 - 64	ABANDONMENT
OTHER: Image: Completed operations 12. Describe proposed or completed operations. (Clearly state all pertion of starting any proposed work). SEE RULE 1103. For Multiple Completion. 11/17/01 Rig up wireline truck and 1) 2) Set CIBP at 1990 feet. (F 11/20/01 Loaded casing with 16 bbls. casing to 500 psi for 38 min TA status is hereby requested. Plug state all pertion of the status approved with 11.20 - 64 I hereby certify that the information above is true and complete to the best status approved with 1.20 - 64 I hereby certify that the information above is true and complete to the best status approved with 1.20 - 64 Type or print name Fred F. Pool, III Type or print name Fred F. Pool, III	ABANDONMENT ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Casing Integrity Test inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion Run 8 5/8", 24# Gauge ring to 2040 feet Pluid level was at 275' from surface. H20 with packer fluid and pressure test sutes with no pressure drop. Setting record and pressure test chart est of my knowledge and belief. Deperator DATE //23/01