schemat Copies To Approximate District State of New Mexicio CNS Form C-103 Description Energy, Minerals and Natural Resources WILL A PLNO. Different Areas, Massion COLL CONSERVATION DIVISION WILL A PLNO. Different Areas, Massion COLL CONSERVATION DIVISION WILL A PLNO. Different Areas, Massion COLL CONSERVATION DIVISION WILL A PLNO. Different Areas, Massion State of New Mexico WILL A PLNO. CODE MORT SCIENCE State of New Mexico State of New Mexico OWN Disc Transference State of New Mexico State of New Mexico OWN Disc Transference State of New Mexico Twin Lakes San Andres Unit Disc Transference State of New Mexico Twin Lakes San Andres Unit Disc Transference Twin Lakes San Andres Unit Twin Lakes San Andres Unit Disc Transference Gas Well Other Injection Dist Transference Twin Lakes, San Andres Unit Twin Lakes, San Andres Unit Dist Transference State of Press County Twin Lakes, San Andres Unit Dist Transference State of Press County Twin Lakes, San Andres (Assoc) Dist Unit Letter, N : 560 Feet from			11	
Direct In an in- Statistic Conserved in the indicate indication indicates in the indicate indindicate indicate indicate indicate indindin	Office Energy Minerals and Natur		Form C-103 Revised March 25, 1999	
Sint Sam Jern, Area, 68 38210 Soll CONSERVATION DIVISION Santa Fer, Area, 68 38210 Job South Pacheco Demotion Santa Fe, NM 87505 Santa Fe, NM 87505 STATE Demotion Santa Fe, NM 87505 Support Ga Support Other Support Ga Support National Support Ga Support National Support Ga Support National Support Ga Support National Support Support Nationalo	1625 N. French Dr., Hobbs, NM 88240	WELL API	NO.	
1000 The Brands A. Ank/SM 07410 3' Santa Fc, NM 87505 SILLE / LES 2005 Sum Packeo, sant Fe, NM 87505 6. State OL & Che Lease No. 2005 Sum Packeo, sant Fe, NM 87505 6. State OL & Che Lease No. 2005 Sum Packeo, sant Fe, NM 87505 7. Lease Name or Unit Agreement Name: TYPE OF VISE THIS FOR PROFENSION DERLE OR TO EPERPIN OR FLIG PACK TO A DIFFERENT RESPONDE US: STAPLICATION FOR TERMIT d'OWN CLOY FOR SUCH 7. Lease Name or Unit Agreement Name: TYPE OF VISE THIS FOR PORTAGE 0 ther Injection 7. Well No. 01 Well Cas Well Other Injection 7. Well No. 01 Well Cas Copp. 8. Pool name or Wildcat 7. Well No. 10. Unitiana Ste 100; Molland, Tx 79701 Twin Lakes; San Andres (Assec) 49 4. Well Louisiana Ste 100; Molland, Tx 79701 Twin Lakes; San Andres County 397.7 CR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE CF (JUTENTION TO : SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PULL OR ALTER CASING MULTIPLE CASING TEST AND AAMPOONLE ALTERING CASING 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated	District II 811 South First, Artesia, 88210 RECEIVED OIL CONSERVATION	DIVISION 5. Indicate	Type of Lease	
Definition Sum Proteon, Stath E: NM 97805 Sum Proteon, Stath E: NM 97805 SUNDRY NOTICES AND REPORTS ON WELLS. To more than prove for experiences and process and proceses and proceses and process and proceses and process and	1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87	505 <u>51A</u>		
OD NOT USE THIS POSITION DOR PROFESSION TO DRILL OR TO DEPEND OR PLUG BACK TO A DEPERSON TRESENVOIR. USE "APPLICATION FOR USENIT" (FORM C-101) FOR SUCH Twin Lakes San Andres Unit PROFESSION CONSTRUCTION FOR PRANT FORM C-101) FOR SUCH Twin Lakes San Andres Unit PROFESSION Case Well Other Injection OI Well Case Well Other Injection 10 Name of Operator S. Pool name or Wilded 11 Check Operator S. Pool name or Wilded 12 Name of Operator S. Pool name or Wilded 13 Address of Operator S. Pool name or Wilded 14 Well Location Init Lakes, San Andres (Assoc) 13 Township S. Range 28 10 Elevation (Show whether DR, KKB, RT, GR, etc.) 3997.2 GR 11 Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF, INTENTION TO: 11 Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF, INTENTION TO: 12 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date 12 Describe proposed or completed operations. (Clearly state all pertinent details, and give periment dates, includ	2040 South Pacheco, Santa Fe, NM 87505	0. State O		
DIFFRENCY IDESTAVIDE. USE: ^APPLICATION FOR PERMIT' (FORM C-101) FOR SOCH Twin Lakes San Andres Unit POOTOSALS. Gas Well Other Injection 7. Well No. Oil Well Gas Well Other Injection 7. Well No. 2. Name of Operator 7. Well No. 49 3. Address of Operator 8. Pool name or Wildcat 104 10 W. Louisan Ste 410, Midland, Tx 79701 Twin Lakes, San Andres (Assoc) 4. Well Location 10. Elevantor South Ine and1650 feet from the	SUNDRY NOTICES AND REPORTS ON WELLS		ame or Unit Agreement Name:	
1. Type of Well: Oil Well: Oil Well: Cas Well D Gas Well Other Injection 7. Well No. 2. Name of Operator Concho Oil & Gas Corp. 7. Well No. 3. Address of Operator 8. Pool name or Wildcat 10 W. Louisiana Ste 010; Midland, Tx 79701 Twin Lakes; San Andres (Assoc) 4. Well Location Well Control Unit Letter_N: 560 Feet from the South line and 1650 feet from the West line Section 31 Township 8S Range 28E NOTICE OF, INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON PULL OR ALTER CASING MULTIPLE COMPLETION COMMENCE DRILLING OPNS. OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompliation. Concho Oil & Gas Corp. respectfully requests approval to acidize the TLSAU No. 49 according to the following procedure: 1. Dig workover pit. MIRU pulling unit. POID W //bg. 3. Adter and test to gat 0300 A. Sg gat 72 420 and 2 drums TC 405.	DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FC	R SUCH Twin Lake	s San Andres Unit	
2. Name of Operator 7. Well No. Concho Oli & Gas Corp. 49 3. Address of Operator 8. Pool name or Wildcat 10 W. Louisiana Ste 410; Midland, Tx 79701 Twin Lakes; San Andres (Assoc) 4. Well Location Unit Letter_N : 560 Feet from the South line and 1650 feet from the West line Section 31 Township 8S Range 28E NMPM Chaves County 10. Elevation (Mow whether DR, RKB, RT, GR, etc.) 397.2 GR 397.2 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PULL OR ALTER CASING MULTIPLE CASING TEST AND BANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND DTHER: DTHER: DTHER: 12. Discribe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Concho Oli & Gas Corp. respectfully requests approval to acidize the TLSAU No. 49 according to the following procedure: Dip Workove pit. MRUP pulling unit. 2. POOH & LD rods. Install BOP. Tag TD & TOOH w/ tbg.	1. Type of Well:			
Control of the Cody. 8. Pool name or Wildeat 110 W. Louisiana Ste 410; Midland, Tx. 79701 Twin Lakes; San Andres (Assoc) 4. Well Location Twin Lakes; San Andres (Assoc) Unit Letter N : 560 Feet from the		7. Well N		
3. Mattes of episods Twin Lakes; San Andres (Assoc) 10. W. Louisiana Ste 410, Midland, Tx 79701 Twin Lakes; San Andres (Assoc) 4. Well Location Unit Letter N : 560 Feet from the South line and 1650 feet from the West line Section 31 Township 88 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3997.2 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF, INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND OTHER: OTHER: OTHER: OTHER: OCONCh Oil & Gas Corp. respectfully requests approval to acidize the TLSAU No. 49 according to the following procedure: 1. Dig workover pit. MIRU pulling unit. 2. POOH & LD rods. Instail BOP. Tag TD & TOOH w/ tbg. 3. Set for 00 alse Gas Corp. respectfully requests approval to acidize the TLSAU No. 49 according to the following procedure: 1. Dig workover pit. MIRU pulling unit. 2. <td< td=""><td></td><td>8 Pool no</td><td></td></td<>		8 Pool no		
4. Well Location Unit Letter_N: 560 Feet from the				
Section 31 Township 8S Range 28E NMPM Chaves County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3997.2 GR 3997.2 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF, INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON PULL OR ALTER CASING MULTIPLE COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND ABANDONMENT OTHER: OTHER: OTHER: Internet details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Concho Oil & Gas Corp. respectfully requests approval to acidize the TLSAU No. 49 according to the following procedure: Dig workover pit. MIRU pulling unit. 2. POOH & LD rods. Install BOP. Tag TD & TOOH wi bg. Stating and pool gas 15% Pentol 300 and flush to top perf w/ prod wtr. 3. Style kit big in hole to 5000 psi Stas flow back load Acidize w/ 2000 gals 15% Pentol 300 and flush to top perf w/				
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3997.2 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PERFORM REMEDIAL WORK PLUG AND ABANDON GUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ALTERING CASING PLUG AND ALTERING CASING PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB 0THER: OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Concho Oil & Gas Corp. respectfully requests approval to acidize the TLSAU No. 49 according to the following procedure: 1. Dig workover pit. MIRU pulling unit. 2. POOH & LD rods. Install BOP. Tag TD & TOOH w/ tbg. 3. Run bit & bailer and clean out 50' of rathole below bottom perf (if necessary). 4. PU pir and test tog in hole to 5000 psi 5. Set pir 100' above top perf and test csg to 300#. 6. Pump 500 gals 15% Pentol 300 and flu	Unit Letter N : 560 Feet from the South line and 1650 feet from the West line			
3997.2 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF, INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON PULL OR ALTER CASING MULTIPLE COMPLETION COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recomplation. Concho Oil & Gas Corp. respectfully requests approval to acidize the TLSAU No. 49 according to the following procedure: 1. Dig workover pit. MIRU pulling unit. 2. POOH & LD rods. Install BOP. Tag TD & TOOH w/ tbg. 3. Run bit & bailer and clean out 50° of rathobe below bottom perf (if necessary). 4. PU ptr and test csg to 300#. 6. Pump 500 gals Xylene, 10 bbls prod water w/ 5 gals TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr. 7. SI 12 hrs minimum. 8. Swab flow back load. 9. Acidize w 2000 gals 15% Pentol 3		8	PM Chaves County	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF, INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND PLUC GAND ABANDONMENT OTHER: OTHER: CASING TEST AND 12. Describe proposed or completed operations. (Clearly state all pertiment details, and give pertiment dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Concho Oil & Gas Corp. respectfully requests approval to acidize the TLSAU No. 49 according to the following procedure: 1. Dig workover pit. MIRU pulling unit. 2. POOH & LD rods. Install BOP. Tag TD & TOOH w/ tbg. 3. Run bit & bailer and clean out 50' of rathobe below bottom perf (if necessary). 4. PU pkr and test tbg in hole to 5000 psi 5. Set pir 100' above top perf and test cag to 300#. 6. Pump 500 gals Xylene, 10 bibs prod water w/ 5 gals TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr. 7. Sl 12 hrs minimum. 8. Swab Edow back load. 9. Acidize w/ 2000 gals 15% Pentol 300 and flush to top perf w/ prod wtr. 10. Flow & s	議論》 #28 編 21 # 2011年1月1日 12 11 11 11 11 11 11 11 11 11 11 11 11			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND PLUG AND ABANDONMENT OTHER: Image: Completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Concho Oil & Gas Corp. respectfully requests approval to acidize the TLSAU No. 49 according to the following procedure: Dig workover pit. MIRU pulling unit. POOH & LD rods. Install BOP. Tag TD & TOOH w/ tbg. Run bit & bailer and clean out 50' of rathole below bottom perf (if necessary). 4. PU pkr and test cbg to 300#. 6. Pump 500 gals Xylene, 10 bbls prod water w/ 5 gals TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr. 7. SI 12 hrs minimum. 8. Swab & flow back load. 9. Acidize w/ 2000 gals 15% Pentol 300 and flush to top perf w/ prod wtr. 10. Flow & sub ack all load wtr. 11. POOH w/ pkr. 12. Return well to production. 13. After	做你你的小姐提供我们都在了一点""这个正式你有什么?""你们,你们就是因为我们就能能			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Concho Oil & Gas Corp. respectfully requests approval to acidize the TLSAU No. 49 according to the following procedure: 1. Dig workover pit. MIRU pulling unit. 2. POOH & LD rods. Install BOP. Tag TD & TOOH w/ tbg. 3. Run bit & bailer and clean out 50' of rathole below bottom perf (if necessary). 4. PU pra and test tog in hole to 5000 psi 5. Set pkr 100' above top perf and test csg to 300#. 6. Pump 500 gals Xylene, 10 bbls prod water w/ 5 gals TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr. 10. Flow & swab back all load wtr. 11. POOH w kpr. 12. Return well to production. 13. Ather two days gqueeze w/ TH 756 (according to recommendations). Thereby certify that the information above is true and complete to the best of my knowledge and belief. <	NOTICE OF, INTENTION TO: SUBSEQUENT REPORT OF:			
PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB ABANDONMENT OTHER: OTHER: Image: Complete operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Concho Oil & Gas Corp. respectfully requests approval to acidize the TLSAU No. 49 according to the following procedure: Image: Concho Oil & Gas Corp. respectfully requests approval to acidize the TLSAU No. 49 according to the following procedure: 1. Dig workover pit. MIRU pulling unit. POOH & LD rods. Install BOP. Tag TD & TOOH w/ tbg. 3. Run bit & bailer and clean out 50' of rathole below bottom perf (if necessary). 4. PU pkr and test tbg in hole to 5000 psi 5. Set pkr 100' above top perf and test csg to 300#. 6. Pump 500 gals Xylene, 10 bbls prod water w/ 5 gals TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr. 7. S1 12 hrs minimum. 8. Swab & flow back load. 9. Acidize w/ 2000 gals 15% Pentol 300 and flush to top perf w/ prod wtr. 10. Flow & swab back all load wtr. 11. POOH w/ ptr. 12. Return well to production. 13. After two days squeeze w/ TH 756 (according to recommendations). <td>PERFORM REMEDIAL WORK PLUG AND ABANDON</td> <td>REMEDIAL WORK</td> <td></td>	PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK		
OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Concho Oil & Gas Corp. respectfully requests approval to acidize the TLSAU No. 49 according to the following procedure: 1. Dig workover pit. MIRU pulling unit. 2. POOH & LD rods. Install BOP. Tag TD & TOOH w/ tbg. 3. Run bit & bailer and clean out 50' of rathole below bottom perf (if necessary). 4. PU pkr and test tbg in hole to 5000 psi 5. Set pkr 100' above top perf and test csg to 300#. 6. Pump 500 gals Xylene, 10 bbls prod water w/ 5 gals TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr. 7. S1 12 hrs minimum. 8. Swab & flow back load. 9. Acidize w/ 2000 gals 15% Pentol 300 and flush to top perf w/ prod wtr. 10. Flow & swab back all load wtr. 11. POOH w/rt. 12. Return well to production. 13. After two days gqueeze w/ TH 756 (according to recommendations). 14. Flow & swab squeeze w/ TH 756 (according to recommendations). 15. Stef wodays gqueeze w/ TH 756 (according to recommendations).<	TEMPORARILY ABANDON			
 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Concho Oil & Gas Corp. respectfully requests approval to acidize the TLSAU No. 49 according to the following procedure: Dig workover pit. MIRU pulling unit. POOH & LD rods. Install BOP. Tag TD & TOOH w/ tbg. Run bit & bailer and clean out 50' of rathole below bottom perf (if necessary). PU pkr and test tbg in hole to 5000 psi Set pkr 100' above top perf and test csg to 300#. Pump 500 gals Xylene, 10 bbls prod water w/ 5 gals TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr. St 12 hrs minimum. 8. Swab & flow back load. 9. Acidize w/ 2000 gals 15% Pentol 300 and flush to top perf w/ prod wtr. 10. Flow & swab back all load wtr. POOH w/ pkr. 12. Return well to production. 13. After two days squeeze w/ TH 756 (according to recommendations). Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Terri Stathem Telephone No. 915/683-7443 (This space for State use) APPPROVED BY TWE Content and the tabout the time of the true of the table to the table. 				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Concho Oil & Gas Corp. respectfully requests approval to acidize the TLSAU No. 49 according to the following procedure: 1. Dig workover pit. MIRU pulling unit. 2. POOH & LD rods. Install BOP. Tag TD & TOOH w/ tbg. 3. Run bit & bailer and clean out 50' of rathole below bottom perf (if necessary). 4. PU pkr and test tbg in hole to 5000 psi 5. Set pkr 100' above top perf and test csg to 300#. 6. Pump 500 gals Xylene, 10 bbls prod water w/ 5 gals TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr. 7. SI 12 hrs minimum. 8. Swab & flow back load. 9. Acidize w/ 2000 gals 15% Pentol 300 and flush to top perf w/ prod wtr. 10. Flow & swab back all load wtr. 11. POOH w/ pkr. 12. Return well to production. 13. After two days squeeze w/ TH 756 (according to recommendations). I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Analyst DATE 5/2/01 Type or print name Terri Stathern Telephone No. 915/683-7443 (This space for State use) APPPROVED BY Trace Scattaged TITLE Eovit. Eng. Spect. J DATE 5/14/2w/1				
Concho Oil & Gas Corp. respectfully requests approval to acidize the TLSAU No. 49 according to the following procedure: 1. Dig workover pit. MIRU pulling unit. 2. POOH & LD rods. Install BOP. Tag TD & TOOH w/ tbg. 3. Run bit & bailer and clean out 50' of rathole below bottom perf (if necessary). 4. PU pkr and test tbg in hole to 5000 psi 5. Set pkr 100' above top perf and test csg to 300#. 6. Pump 500 gals Xylene, 10 bbls prod water w/ 5 gals TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr. 7. SI 12 hrs minimum. 8. Swab & flow back load. 9. Acidize w/ 2000 gals 15% Pentol 300 and flush to top perf w/ prod wtr. 10. Flow & swab back all load wtr. 11. POOH w/ pkr. 12. Return well to production. 13. After two days squeeze w/ TH 756 (according to recommendations). I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Analyst Type or print name Terri Stathem Telephone No. 915/683-7443 (This space for State use) APPPROVED BY TYPA Scattering A TITLE Equil. Equil. Equil. Equil. Equil. Equil. Scatte.	of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
 Dig workover pit. MIRU pulling unit. POOH & LD rods. Install BOP. Tag TD & TOOH w/ tbg. Run bit & bailer and clean out 50' of rathole below bottom perf (if necessary). PU pkr and test tbg in hole to 5000 psi Set pkr 100' above top perf and test csg to 300#. Pump 500 gals Xylene, 10 bbls prod water w/ 5 gals TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr. St 12 hrs minimum. Swab & flow back load. Acidize w/ 2000 gals 15% Pentol 300 and flush to top perf w/ prod wtr. Flow & swab back all load wtr. POOH w/ pkr. Return well to production. After two days squeeze w/ TH 756 (according to recommendations). I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	•		C. 11	
 2. POOH & LD rods. Install BOP. Tag TD & TOOH w/ tbg. 3. Run bit & bailer and clean out 50' of rathole below bottom perf (if necessary). 4. PU pkr and test tbg in hole to 5000 psi 5. Set pkr 100' above top perf and test csg to 300#. 6. Pump 500 gals Xylene, 10 bbls prod water w/ 5 gals TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr. 7. SI 12 hrs minimum. 8. Swab & flow back load. 9. Acidize w/ 2000 gals 15% Pentol 300 and flush to top perf w/ prod wtr. 10. Flow & swab back all load wtr. 11. POOH w/ pkr. 12. Return well to production. 13. After two days squeeze w/ TH 756 (according to recommendations). 11 hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	Concho Oil & Gas Corp. respectfully requests approval to acidize the Dig workover pit. MIRU pulling unit.	LSAU No. 49 according to the	following procedure:	
 PU pkr and test tbg in hole to 5000 psi Set pkr 100' above top perf and test csg to 300#. Pump 500 gals Xylene, 10 bbls prod water w/ 5 gals TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr. State State State	2. POOH & LD rods. Install BOP. Tag TD & TOOH w/ tbg.			
 Set pkr 100' above top perf and test csg to 300#. Pump 500 gals Xylene, 10 bbls prod water w/ 5 gals TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr. SI 12 hrs minimum. Swab & flow back load. Acidize w/ 2000 gals 15% Pentol 300 and flush to top perf w/ prod wtr. Flow & swab back all load wtr. Flow & swab back all load wtr. POOH w/ pkr. Return well to production. After two days squeeze w/ TH 756 (according to recommendations). I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE				
 SI 12 hrs minimum. Swab & flow back load. Acidize w/ 2000 gals 15% Pentol 300 and flush to top perf w/ prod wtr. Flow & swab back all load wtr. POOH w/ pkr. Return well to production. After two days squeeze w/ TH 756 (according to recommendations). I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	5. Set pkr 100' above top perf and test csg to 300#.			
 8. Swab & flow back load. 9. Acidize w/ 2000 gals 15% Pentol 300 and flush to top perf w/ prod wtr. 10. Flow & swab back all load wtr. 11. POOH w/ pkr. 12. Return well to production. 13. After two days squeeze w/ TH 756 (according to recommendations). 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE		nd 2 drums 1C 405. Flush to to	p peri w/ prod wu.	
10. Flow & swab back all load wtr. 11. POOH w/ pkr. 12. Return well to production. 13. After two days squeeze w/ TH 756 (according to recommendations). I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Analyst DATE 5/2/01 Type or print name Terri Stathem Telephone No. 915/683-7443 (This space for State use) TITLE APPPROVED BY TITLE TITLE Envit. Envit. Envit. TITLE Spect. TITLE DATE 5/14/2001 TITLE	8. Swab & flow back load.	1 /		
11. POOH w/ pkr. 12. Return well to production. 13. After two days squeeze w/ TH 756 (according to recommendations). I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Type or print name Terri Stathem Title Production Analyst DATE 5/2/01 Type or print name Terri Stathem Title Fourier for State use) APPPROVED BY Mathematical Statistical TITLE Fourier Title Fourier TITLE DATE Signation Title Fourier Title Fourier Title Fourier Title Fourier Title Fourier Title Total Title Title Title Title Title Title Title <td></td> <td>prod wtr.</td> <td></td>		prod wtr.		
13. After two days squeeze w/ TH 756 (according to recommendations). I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE				
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	12. Return well to production.			
SIGNATURE Multiple TITLE Production Analyst DATE 5/2/01 Type or print name Terri Stathem Telephone No. 915/683-7443 (This space for State use) APPPROVED BY This is full field TITLE Eavir. Eag. Spec. I DATE 5/14/2001		()		
Type or print name Terri Stathem Telephone No. 915/683-7443 (This space for State use) APPPROVED BY mise (Statelise) TITLE Envir. Eng. Spec. I DATE 5/14/2001	13. After two days squeeze w/ TH 756 (according to recommend	tions).		
(This space for State use) APPPROVED BY misel Studdlighted TITLE Eavir. Eag. Spec. I DATE 5/14/2001				
(This space for State use) APPPROVED BY misel Student TITLE Envir. Eng. Spec. I DATE 5/14/2001	I hereby certify that the information above is true and complete to the	est of my knowledge and belief		
	I hereby certify that the information above is true and complete to the SIGNATURE	best of my knowledge and belief <u> Production Analyst</u> D		
	I hereby certify that the information above is true and complete to the SIGNATURE	best of my knowledge and belief <u> Production Analyst</u> D		