

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State ☒ Fee ☐
5. State Oil & Gas Lease No.	L-5018

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	2. Name of Operator C & K Petroleum, Inc. ✓	3. Address of Operator P. O. Drawer 3546, Midland, TX 79702	4. Location of Well UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 14 TOWNSHIP 3S RANGE 27-E N.M.P.
5. Elevation (Show whether DF, RT, GR, etc.) 4008 GR	6. Unit Agreement Name White Draw Unit	7. Farm or Lease Name White Draw Unit	8. Well No. 1
9. Field and Pool, or Wildcat Wildcat Abo	10. County Chaves		

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐	REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOB ☐ OTHER ☐
PLUG AND ABANDON ☒ CHANGE PLANS ☐	ALTERING CASING ☐ PLUG AND ABANDONMENT ☐ Procedures to plug & abandon ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/8/81 - Approval to P & A by NMOCC. Run 4-1/2 CI B.P. on tbq. attempt to set @ 4737. Could not set. Start out of hole w/tbg & B.P. B.P. set at 3669 while pulling out of hole. Finish pulling tbq. Shut down.

2/9/81 - Permission granted by Mr. Bill Grissitt, NMOCC to proceed to P & A as follows:

Test B.P. @ 3669 - if B.P. test OK, P & A:

1. Dump 50' cement plug top of B.P. 3669 & 3619 w/dump bailer.
 2. Cut 4-1/2" casing off at approx. 3350, pull & lay down. Run tubing, spot 35 sk plug at 4-1/2" csg. stub 3350.
 3. Spot 35 sk plug at 2492, top of Glorieta.
 4. Spot 75 sk plug 1450 back to 1350 - 50' in & 50' out 8-5/8" set @ 1399. This plug must be tagged.
 5. Spot 10 sk plug 20' to surface inside 8-5/8".
 6. Cut off 8-5/8" Bradenhead 36" below ground level. Well on 1/4" plate. Install dry hole marker as required by NMOCC.
 7. Clean location of all debris. Back fill pits, level location to original terrain as soon as possible.
- * Load hole w/mud

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Louis P. Cook TITLE Administrative Supervisor DATE 2/10/81.

APPROVED BY Mike Williams TITLE Oil and Gas Inspector DATE FEB 12 1981

CONDITIONS OF APPROVAL, IF ANY: * As noted above

Notify N.M.O.C.C. in sufficient time to witness
Plugging