

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. <b>30-005-60823</b>	
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
State Oil & Gas Lease No.	
Lease Name or Unit Agreement Name <b>Twin Lakes San Andres Unit</b>	
Well No. <b>22</b>	
Pool name or Wildcat <b>Twin Lakes San Andres ( Assoc. )</b>	
Well Location Unit Letter <b>AB</b> : <b>990</b> Feet From The <b>North</b> Line and <b>2310</b> Feet From The <b>East</b> Line Section <b>31</b> Township <b>8S</b> Range <b>29E</b> NMPM <b>Chaves</b> County	
Elevation (Show whether DF, RKB, RT, GR, etc.) <b>3972GR</b>	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER

Name of Operator

Hanagan Petroleum Corporation

Address of Operator

P.O. Box 1737 Roswell, N.M. 88202

Well Location

Unit Letter **AB** : **990** Feet From The **North** Line and **2310** Feet From The **East** Line

Section **31** Township **8S** Range **29E** NMPM **Chaves** County

Elevation (Show whether DF, RKB, RT, GR, etc.)

**3972GR**

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ANBANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Notify NMOCD - Artesia, 24 hrs. prior to commencement of procedure

1. Set CIBP @ 2620 cap w/ 35' cmt. ( Top perf 2708 - 2748 )
2. RIH circulate well w/ 9.8# mud
3. cut & pull 4 1/2 @ 2000'
4. RIH spot 100' plug 50' in 50' out cut woc tag **255x**
5. spot **160'** cmt from **160** to surface **170'**
6. cut off well head set dry hole marker & clean location



**\* Notice NMOCD to Witness Plugging Operations.**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Wayne Brooks*

TITLE **agent**

DATE **07-06-99**

TYPE OR PRINT NAME **Wayne Brooks**

TELEPHONE NO. **915-6848890**

(This space for State Use)

APPROVED BY

*Michael S. Wells*

TITLE

**Field Rep. II**

DATE

**9/29/99**

CONDITIONS OF APPROVAL, IF ANY: