

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

RECEIVED

FEB 23 1983

O. C. D.  
ARTESIA, OFFICE

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER- P&A

Name of Operator  
Yates Petroleum Corporation ✓  
Address of Operator  
207 South 4th St., Artesia, NM 88210

7. Unit Agreement Name

8. Farm or Lease Name  
Sacra SA

9. Well No.  
7-Y

Location of Well  
UNIT LETTER 0 610 FEET FROM THE South LINE AND 1650 FEET FROM  
THE East LINE, SECTION 22 TOWNSHIP 6S RANGE 25E NMPM.

10. Field and Pool, or Whdcat  
Pecos Slope Abo

15. Elevation (Show whether DF, RT, GR, etc.)  
3799' AGR

12. County  
Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to Plug and Abandon well as follows:  
Set a plug 50' in and 50' out at casing shoe set at 860'.  
If unsuccessful with the above plug, set a Bridge Plug at bottom of casing w/35 sacks cement on top.  
Set 100' of cement across casing part at 446'.  
Set surface plug w/regulation abandonment marker.

Verbal approval for plugging given by Mike Williams, NMOCD, Artesia 2-16-83.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ICED: Production Supervisor TITLE: Production Supervisor DATE: 2-22-83

APPROVED BY: Mike Williams TITLE: OIL AND GAS INSPECTOR DATE: MAR 1 1983

CONDITIONS OF APPROVAL, IF ANY: