

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐  
well well other Dry Hole

2. NAME OF OPERATOR  
McClellan Oil Corporation ✓

3. ADDRESS OF OPERATOR  
P.O. Drawer 730, Roswell, NM 88201


4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 660' FNL & 660' FWL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input checked="" type="checkbox"/>
(other)		

5. LEASE  
NM-11596  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
7. UNIT AGREEMENT NAME  
8. FARM OR LEASE NAME  
PJ ~~Govt~~ Federal  
9. WELL NO.  
3  
10. FIELD OR WILDCAT NAME  
South Pecos Slope Abo  
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 11-T9S-R25E  
12. COUNTY OR PARISH  
Chaves  
13. STATE  
NM  
14. API NO.  
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3529' G.L.



(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED  
DEC 15 10 05 AM '83  
BUREAU OF LAND MANAGEMENT  
ROS WELL DISTRICT

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

12/12/83: Plugged and Abandoned:  
Pulled 4-1/2" casing from 3100' to surface.  
Set 200' plug from 3000' to 3200' in and out of shoe.  
Set 200' plug from 810' to 1010' in and out of 8-5/8" shoe.  
Set 60' plug from 60' to surface.  
Installed dry hole marker. Will clean and level location after pits dry.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Paul R. Ragdale TITLE Operations Manager DATE 12/14/83

APPROVED (This space for Federal or State office use)

(Orig. Sgd.) PETER W. CHESTER  
APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

JAN 25 1985



\*See Instructions on Reverse Side