				C	
	c	State of New Mexico		Form C-103	
Submit 3 Copies To Appropriate			rtmont	Revised 1-1-89	
District Office	Energy, Mineral	s and Natural Resources Depa	runent		
DISTRICT I	OIL CONS	SERVATION DIVIS		WELL API NO.	
P.O. Box 1980, Hobbs, NM 88240		2040 South Pacheco			
		Santa Fe, NM 87505		30-005-62055	
DISTRICT II	k	Saina PC, INIVI 87505	-	8. Indicate Type of Lease	
811 South First, Artesia NM 88210		123456	$\mathbf{N}$	STATE - (X) FEE	
		3	Troles L		
DISTRICT III		10 A	6	9. State Oil & Gas Lease No.	
1000 Rio Brazos Rd., Aztec, NM 87410	0	S NOV 1004	3	VA 1047	
		DTG OF THE CLIM	213	VA—1047 10. Lease Name or Unit Agreement	
				Name:	
DO NOT USE THIS FORM FOR TROPOSALS TO BRILL SO TO BLACK TO BRILL SO TO					
	PROPOSALS		3		
5. Type of Well:		Other Other	814	West Elida Unit	
Oil Well	Gas Well 🕱	Other			
6. Name of Operator	•			10. Well No.	
				1	
Prairie Sun, Inc.     7. Address of Operator				11. D. 1	
7. Address of Operator				11. Pool name or Wildcat	
P. O. Box 8280 Roswell, NM 88202-8280				Wildcat	
8. Well Location					
Unit letter C :	660 feet from the	e North line and	<b>198</b> 0	feet from the West line	
		v whether DF, RKB, RT, GR, etc			
4726' GR					
Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTER			EQUENT	REPORT OF:	
	JG AND ABANDON	REMEDIAL WORK		ALTERING CASING	
( )	( )	( )		( )	
TEMPORARILY ABANDON CH	ANGE PLANS	COMMENCE DRILLING OPN	NS.	PLUG & ABAND.	
( )	( )	()		( )	
PULL OR ALTER CASING		CASING TEST AND CEMEN	T JOB		
()					
OTHER:		OTHER: Continued Ope	rations		

15/

· -- .

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.

## October 18, 1998 & October 19, 1998

Move in and rig up Ram Well Service pulling unit. Move in and rig up reverse equipment. Make up 7 7/8" bit, 8-4.75" drill collars and go in hole. Pick up tubing and tag at 710'. Pick up swivel and drill cement to 790' and fall free. Continue in hole to 1408'. Circulate out heavy mud to 1476'. Drill cement to 1650'. Circulate hole with clean water. Shut down. Pull out of hole and lay down drill collars and bit. Rig down and release pulling unit and rental equipment on 10-19-98. Well shut in with BOP.

1 0	
I hereby certify that the information above strue and complete to the best	st of my knowledge and belief.
SIGNATURE IM III	LEDATE10-21-98
Type or print name Gene Lee	Telephone No. <u>505-622-7355</u>
(This space for State use)	
(This space for State use) BC >   APPROVED Image: Comparison of the space of th	District Sepervisor DATE 11-6-98

Conditions of approval, if any: