

Submit 3 Copies  
To Appropriate  
District Office  
DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
811 South First, Artesia NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico  
Energy, Minerals and Natural Resources Department


**OIL CONSERVATION DIVISION**

2040 South Pacheco  
Santa Fe, NM 87505

CIST  
UP

Form C-103  
Revised 1-1-89

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		WELL API NO. <b>30-005-62055</b>
26. Indicate Type of Lease STATE - <input checked="" type="checkbox"/> FEE <input type="checkbox"/>		27. State Oil & Gas Lease No. VA-1047
29. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/>		28. Lease Name or Unit Agreement Name: West Elida Unit
30. Name of Operator <b>Prairie Sun, Inc.</b>		22. Well No. 1
31. Address of Operator <b>P. O. Box 8280 Roswell, NM 88202-8280</b>		23. Pool name or Wildcat Wildcat
32. Well Location Unit letter <u>C</u> : <u>660</u> feet from the <u>North</u> line and <u>1980</u> feet from the <u>West</u> line		
17. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>4726' GR</u>		



14-4-29

Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

**NOTICE OF INTENTION TO:**

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ( )	PLUG AND ABANDON ( )	REMEDIAL WORK ( )	ALTERING CASING ( )
TEMPORARILY ABANDON ( )	CHANGE PLANS ( )	COMMENCE DRILLING OPNS. ( )	PLUG & ABAND. ( )
PULL OR ALTER CASING ( )		CASING TEST AND CEMENT JOB	
OTHER: _____		OTHER: <u>Continued Operations</u>	

19. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.

**2-11-99 thru 2-13-99**

Move in and rig up Tyler Well Services pulling unit. Move in and rig up reverse equipment. Make up 7 7/8" bit, 8-4.75" drill collars and go in hole. Pick up tubing and tag at 2995'. Pick up swivel and circulate out fill to 2998'. Drill cement from 2998' to 3036' and fall free. Continue in hole at tag at 3552'. Circulate hole clean. Pull out of hole and lay down drill collars. Rig down and release pulling unit and the rental equipment on 2-13-99. Well shut in with BOP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gene Lee TITLE Agent DATE 2-16-99

Type or print name Gene Lee Telephone No. 505-622-7355  
(This space for State use)

APPROVED Jim W. Gunn District Supervisor  
BY BGO TITLE \_\_\_\_\_ DATE 3-11-99

Conditions of approval, if any: