

Submit 3 Copies  
To Appropriate  
District Office  
**DISTRICT I**  
P.O. Box 1980, Hobbs, NM 88240

State of New Mexico  
Energy, Minerals and Natural Resources Department

**OIL CONSERVATION DIVISION**

2040 South Pacheco  
Santa Fe, NM 87505

Form C-103  
Revised 1-1-89

**DISTRICT II**  
811 South First, Artesia NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

**30-005-62055**

29. Indicate Type of Lease  
STATE - ☒ FEE ☐

30. State Oil & Gas Lease No.  
VA-1047

31. Lease Name or Unit Agreement  
Name:

West Elida Unit

24. Well No.  
1

25. Pool name or Wildcat  
Wildcat

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS

33. Type of Well:  
Oil Well ☐ Gas Well ☒ Other

34. Name of Operator

**Prairie Sun, Inc.**

35. Address of Operator

**P. O. Box 8280 Roswell, NM 88202-8280**

*SECT. 14, 45-29E*

36. Well Location

Unit letter C : 660 feet from the North line and 1980 feet from the West line

18. Elevation (Show whether DF, RKB, RT, GR, etc.)  
4726' GR

Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

**NOTICE OF INTENTION TO:**

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK  
( )

PLUG AND ABANDON  
( )

REMEDIAL WORK  
( )

ALTERING CASING  
( )

TEMPORARILY ABANDON  
( )

CHANGE PLANS  
( )

COMMENCE DRILLING OPNS.  
( )

PLUG & ABAND.

PULL OR ALTER CASING  
( )

CASING TEST AND CEMENT JOB

OTHER: \_\_\_\_\_

OTHER: Continued Operations

20. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.

**3-04-99 thru 3-06-99**

Move in and rig up Key Well Service pulling unit. Move in and rig up reverse equipment. Make up 7 7/8 in. 4730' drill collars and go in hole. Pick up tubing and tag at 3018'. Pick up swivel and circulate out bridge to 3051' and fall free. Continue in hole at tag at 3552'. Circulate hole clean. Continue in hole and tagged at 3612'. Drill cement stringers to 3700'. Circulate hole clean and displace soured mud to reserve pit. Pull out of hole and lay down drill collars. Rig down and release pulling unit and the rental equipment on 3-06-99. Well shut in with BOP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gene Lee TITLE Agent DATE 3-06-99

Type or print name Gene Lee  
(This space for State use)

Telephone No. 505-622-7355

APPROVED  
BY

Jim W. Burns  
BON

TITLE

District Supervisor

DATE 4-30-99

Conditions of approval, if any:

