

Submit 3 Copies  
To Appropriate  
District Office  
DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

### OIL CONSERVATION DIVISION

2040 South Pacheco  
Santa Fe, NM 87505

WELL API NO. <b>30-005-62055</b>
32. Indicate Type of Lease STATE - <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
33. State Oil & Gas Lease No. VA-1047
34. Lease Name or Unit Agreement Name: West Elida Unit
26. Well No. 1
27. Pool name or Wildcat Wildcat

DISTRICT II  
811 South First, Artesia NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
37. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other	
38. Name of Operator ✓ <b>Prairie Sun, Inc.</b>	
39. Address of Operator <b>P. O. Box 8280 Roswell, NM 88202-8280</b>	<i>SECT. 14, 45-39E</i>
40. Well Location Unit letter <b>C</b> : <b>660</b> feet from the <b>North</b> line and <b>1980</b> feet from the <b>West</b> line	
19. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>4726' GR</b>	

Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

**NOTICE OF INTENTION TO:**


**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ( )	PLUG AND ABANDON ( )	REMEDIAL WORK ( )	ALTERING CASING ( )
TEMPORARILY ABANDON ( )	CHANGE PLANS ( )	COMMENCE DRILLING OPNS. ( )	PLUG & ABAND. ( )
PULL OR ALTER CASING ( )		CASING TEST AND CEMENT JOB	
OTHER: _____		OTHER: <u>Continued Operations</u>	

21. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.

**3-23-99 thru 3-24-99**

Move in and rig up Tyler Well Service pulling unit. Move in and rig up reverse equipment. Make up 7 7/8" 54.8 - 4.75" drill collars and go in hole. Pick up tubing and tag at 3700'. Drill cement stringers to 3790'. Circulate hole clean. Pull out of hole and lay down drill collars. Rig down and release pulling unit and the rental equipment on 3-25-99. Well shut in with BOP.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gene Lee TITLE Agent DATE 3-26-99

Type or print name Gene Lee Telephone No. 505-622-7355  
(This space for State use)

APPROVED BY TIM W. GUM DISTRICT II SUPERVISOR BOA TITLE \_\_\_\_\_ DATE 4-30-99

Conditions of approval, if any: