

UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Budget Bureau No. 1004-1  
Expires August 31, 1985  
2157

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT -" for such proposals.)

NM-0559993  
IF INDIAN, ALLOTTEE OR TRIBE NAME

UNIT AGREEMENT NAME

FARM OR LEASE NAME

MM Comm. Federal Com

2

10. FIELD AND POOL, OR WILDCAT

South Pecos Slope

11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA

Sec 35-T9S-R25E

12. COUNTY OR PARISH 13. STATE

Chaves NM

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

McClellan Oil Corporation

3. ADDRESS OF OPERATOR

P.O. Drawer 730, Roswell, NM 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface

1980' FNL & 660' FEL

14. PERMIT NO

15. ELEVATIONS (Show whether DF, RT, or etc.)

3614' G.L.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Propose to plug and abandon:

Well Data: 8-5/8" surface casing set at 1007'. Cement circulated.  
4-1/2" production casing set at 4400'. Cemented with 350 sx.  
TOC at 3500'. Squeeze holes at 3200'. Squeezed with 100 sx Class C. One  
inched bradenhead with 300 sx Class C Neat.  
Perfs: 4211' to 4243' with 10 holes.

Set 1st plug with 25 sx across perfs from 4150' to 4250'. Tag plug.  
Set 2nd plug with 25 sx across Glorieta (Top-1615') from 1565' to 1665'.  
Set 3rd plug with 25 sx across 8-5/8" shoe from 957' to 1057'.  
Set surface plug with 10 sx from 0 to 60'. Clean location and install dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Operations Manager

DATE 7/18/86

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

APPROVED  
PETER W. CHESTER

JUL 22 1986

BUREAU OF LAND MANAGEMENT  
ROSWELL RESOURCE AREA