NO. OF COPIES RECEIVED		AMENDED	-		•	
DISTRIBUTION		NEW MEXICO OIL CONS	ERVATION CORMISSIO	N	Form C-101	
SANTA FE				1	Revised 1-1-65	
FILE			MAY 3 1 1985		5A. Indicate Type of Lease	
	2		MAI U I 1000		STATE	FEE X
OPERATOR			O. C. D.		.5. State Oil &	Gus L e ase No.
L			ARTESIA, OFFICE	_	huun	anna ann ann ann ann ann ann ann ann an
APPLICATION FOR PERMIT TO DRILL, DEEPEN, OR PLUG BACK					///////	
1a. Type of Work						ment Name
	X	DEEPEN	PLUG	васк 🗍		
b. Type of Well					8. Farm or Lea	
OIL X GAS MULTIPLE WELL O.HER ZONE ZONE					Plains SL 19	
Tenneco Oil Company Amended					9. Well No. 1	
3. Address of Operator						Pool, or Wildcat
7990 IH 10 West, San Antonio, Tx 78230					Wildcat - Duronica	
4. Location of Well B 300					mmm	THE REAL
UNIT LETTER LOCATED JQU FEET FROM THE ΠΟΙΤΠ LINE					<u> </u>	
AND 2200 FEET FRO	м тне East	LINE OF SEC. 19	TWP. 105 RGE. 2	8E NMPM	١١١١١١١	HHHHHHH
					12. County	<u> </u>
YTTTTTTTTTTTTTTTTT	<i>HIIIIII</i>				Chaves	
					mm	<u>MMMMM</u>
λ11/1/1/1/1/1/1/			9. Proposed Depth 19A. Formation 7000' Devonia		1-	10. Rotary or C.T.
21. Elevations (Show whether D	E_{RT} etc.) 214	Kind & Status Plug. Bond	21B. Drilling Contractor	Devonia		Rotary
3760.4 GR		anket	Unknown	•	22. Approx. D	Date Work will stort
23.		I			37257	
		PROPOSED CASING AN	D CEMENT PROGRAM			
SIZE OF HOLE	SIZE OF CASH	NG WEIGHT PER FOO	T SETTING DEPTH	SACKS OF	CEMENT	EST. TOP
<u> 17 ½" </u>	13 3/8"	54.5	320'	340 sxs	Class C	surface
17 ¹ / ₂ "	8 5/8"	24	1950'	<u>565 sxs</u>	Class C	<u>circulated</u>
7 7/8"	5 ¹ ₂ "	15.5	7000'		Class BJ	circulated
1. MIRU.		•	•	"Lite" 200 sxs	H Class H	
2. Must have pe	ermit prior to	spud. Notify N	lew Mexico Oil C	onservat	ion Commis	ssion
(N.M.O.C.C.)	at (505) 748	-1283 at least 8	hours prior to	spud if	possible.	. If
anticipated	spud date fal	lls on weekend or	r before 8:00 a.	m. or at	fter 5:00	p.m.
		nours to obtain 2			• .	•
3. Drill 17 1/2	2" hole to +/	- 320' (See Mud	Program) and se	t +/-320)' of 13 3	3/8",
54.5 #, K-5	5, STC casing	. Centralize an	d cement to sur	face as	per cemer	nting
	Notify N.M.O	.C.C. at least 8	3 hours prior to	o running	g or cemer	nting
casing.	full company	ian aftau wunnin				NV1
4. Slack off in 5. Wait on cem	rui compress	sion after running otal of at least	y casing.	m initi	ating a d	the Ny Ad
J. Wait On Cem Minimum com	nnessive strei	ngth of 500 PSIG	must be obtained	nrior t	aliny a i o tostina	
6. Cut off 13	3/8" and inst	all 13 3/8" x 13		prior i sing bo	$v = 10^{-2^{\circ}}$	
1-2" ball va	lve. and 1-2"	all 13 3/8" x 13 solid bull plug.	(Will need 13 5	/8" x 11	" 3M DSA 1	
						, K K A
N ABOVE SPACE DESCRIBE D			inued on back of			,
N ABOVE SPACE DESCRIBE P IVE ZONE. GIVE BLOWOUT PREVEN	TER PROGRAM, IF ANY.	TO PROPOSAL IS TO DEEPEN C	IN FLUG BACK, GIVE DATA ON	PRESENT PRO	DUCTIVE ZONE AN	D PROPOSED NEW PRODUC+
hereby certify that the informat.	ion above is true and	omplete to the best of my k	npwledge and bellef.			
1 MA-Las	V holit	Explora	tion Geologist		Mav 28	, 1985
igned of Winne	J roval	<u> </u>		D	Date	,
(This space for	•	(*(*)**	-			
	ORIGINAL SI				B6 //	31 1085
PPROVED BY	BY LARRY BF				ATE MAT	31 1985
ONDITIONS OF APPROVAL, I	F ANY:	- -				
	Ball of Stormach Cares					

- 7. Nipple up 11" 3M SRRA BOPE w/manifold (3M). Test weld, well head, blind rams and choke manifold to 500#. Use rig pump. Record test on IADC reports and details on TOC Daily Drlg. Reports.
- 8. RIH w/11" bit-BHA to cement (top of float collar). Test 13 3/8" csg. to 500#. Test pipe rams and hydril 500#. If test ok (no more than 10% reduction of pressure in 30 min.) continue. If no test on csg., consult SWD. Have H_2S 9. Drill out float equipment and cmt.
- 10. Drill 11" hole to +/-1950' (see attached Mud Program).
- 11. Sweep hole as necessary to insure proper hole cleaning.
- 12. SLM 0.0.H. and RU run +/-1950' of 8 5/8" 24# and 32#, K-55, ST&C csg.
- 13. Run csg., centralize and cement as per attached Casing and Cement Program. Notify N.M.O.C.C. at (505) 748-1283 prior to starting operations.
- 14. WOC a minimum of 8 hours. Cut of 13 3/8" well head remove same. Install 8 5/8" x 10 3/4" (3M) SOW well head bell nipple. Orange peel 13 3/8" to 8 5/8" csg. w/l" nipple and value on 13 3/8" csg. Will need 10 3/4 x 11" Larking Drilling Flange adaptor to N.U. BOPE.
- 15. NU same BOPE w/RAM rubbers to fit DP Yellow-jacket stack and choke manifold to WP.
- 16. RIH w/7-7/8 bit, BHA to cmt. (top of float collar). Test csg to 1500#. If test ok continue. If no test, consult SWD.
- 17. Drill out float equipment and cmt.
- 18. Drill 7 7/8" hole to Devonian at 6800'-7000'. Consult SWD and geolgoist for TD (see Mud Program).
- 19. CCM to run logs.
- 20. SLM out of hole.
- 21. Run logs as per CAT II, Geologist, and SWD.
- 22. If DST is to be performed in the Devonian CCM., clean hole and SLM out of hole. Chain out first 5 stds off bottom and POOH. PU, MU, & RIH w/DST tools. Try to be on bottom and ready to open tool at daybreak. Open tool only in davlight hours. *(See DST Data)*
- 23. Prior to initiating DST make sure safety precautions have been taken:a) No Smokingd) No Exposed Lights

e) H₂S Protection

- b) No Welding
- c) No Open Flame
- 24. Run DST as per SWD.
- 25. POOH w/5 stds DP. Consult SWD prior to this time concerning pulling to fluid or circulating recovery once initial 5 stds have been pulled.
- 26. POOH w/DST tools.
- 27. LD DST tools.
- 28. RIH w/7 7/8" bit & BHA.
- 29. If well is to be cased, proceed to step 30. If well is to be P&A'd, have geologist pick all geologic TOPS from electric logs and consult N.M.O.C.C. for proper procedure. Also consult SWD on possibility of plugging back into 8 5/8" csg. only-due to possibility of selling well bore to offset operator holding shallow lease.
- 30. RIH w/7 7/8" bit and BHA for a clean up trip.
- 31. CCM to run 5 1/2" production csg.
- 32. POH. Lay down DP & DC.
- 33. RU & run 5 1/2 production csg. *NOTE: Make final cmt. cal. and design for 5 1/2" production csg. after logging. TOC at +/-3000'.
- 34. Cmt as per Cement Program. ND BOP's. Set slips on 5 1/2. Cut off 5 1/2. Install Tbg spool. Release rig.
- 35. Completion as per SWD.