

## OIL CONSERVATION DIVISION

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

BLM 1

RECEIVED BY  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

SEP 23 1985

O. C. D.

ARTESIA, OFFICE

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
Aztec	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Und. Diablo SA	
12. County	
Chaves	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL UP TO DEPTH OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER- Dry Hole	
2. Name of Operator	
Hamilton Pumping Service	
3. Address of Operator	
P. O. Box 2461, Roswell, NM 88201	
4. Location of Well	
UNIT LETTER P 330 FEET FROM THE South LINE AND 990 FEET FROM	
THE East LINE, SECTION 22 TOWNSHIP 10-S RANGE 27-E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	
3830.6 GL	
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	
TEMPORARILY ABANDON <input type="checkbox"/>	
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER <input type="checkbox"/>	
PLUG AND ABANDON <input checked="" type="checkbox"/>	
CHANGE PLANS <input type="checkbox"/>	
OTHER <input type="checkbox"/>	
SUBSEQUENT REPORT OF:	
REMEDIAL WORK <input type="checkbox"/>	
COMMENCE DRILLING OPS. <input type="checkbox"/>	
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	
ALTERING CASING <input type="checkbox"/>	
PLUG AND ABANDONMENT <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 2197', propose to plug and abandon as follows:

Circulate hole with <sup>mud</sup>water, set 25 sx. plug 2090' - 1990'  
set 25 sx. plug 1620' - 1520'  
set 25 sx. plug 1150' - 1050'  
set 25 sx. plug 526' - 421'  
10 sx. plug @ surface.

Will then install dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Sharon Hamilton TITLE Clerk DATE 9-20-85APPROVED BY \_\_\_\_\_ TITLE OIL AND GAS INSPECTOR DATE SEP 25 1985

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.C. in sufficient time to witness

Plugging