

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

RECEIVED BY
FEB 27 1987
O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-79

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	
LAND OFFICE	
OPERATOR	☒

a. Indicate Type of Lease
State ☒ Fee ☐
b. State Oil & Gas Lease No.
LG 4336

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation	8. Farm or Lease Name Red Bluff State Unit
3. Address of Operator 105 S. 4th St., Artesia, NM 88210	9. Well No. 1
4. Location of Well UNIT LETTER <u>P</u> , <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>11</u> TOWNSHIP <u>7S</u> RANGE <u>24E</u> NMPM.	10. Field and Pool, or Wildcat Pecos Slope Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3970.4' GR	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon as follows:

- (1) Spot cement plug at 3625' to cover perms. 3561-64'. Use 25 sx. Tag plug. Plug must come up to 3500'.
- (2) Stretch 4½" casing and knock off approximately 100' above free point. Pull free casing.
- (3) Spot plug through tubing 50' in and out of 4½" casing stub. Tag this plug.
- (4) Spot plug through tubing 50' in and out of 7 5/8" casing shoe from 1470-1370'. Tag this plug.
- (5) Spot plug through tubing from 1000-900'.
- (6) Attempt to pressure up on 7 5/8" x 10 3/4" casing annulus to 500 psi. If pressure holds, spot 50' plug at surface. If annulus can be pumped into; pump 200 sx cement into annulus and shut in. Spot 50' plug at surface.

NOTE: Fill hole with mud between plugs.

All plugs except surface plug at least 25 sx.

Notify NMOCD-Artesia 24 hours prior to starting plugging operations.

Notify NMOCD in sufficient time to witness

Plugging

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Albert R. Hall TITLE Engineer DATE 2-27-87

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE MAR 03 1987

CONDITIONS OF APPROVAL, IF ANY:

