·				ONSERVATI	0.0.0			Form C-101	
015 3 4 11 T A	THINUTION FE		SAN	ITA FE, NEW A	EXI 00 48 7-50			SA, INGICULA	
TILE				l F	EB 26 1987				6 Gus Loune No.
LAND	DIFICE				O. C. D.			arrearre	
OPERA				DRILL, DEEPEN,		<u>cr</u>			
a. Type of 1	and the second se	NTURPE	<u>(MI1 10</u>	DRILL, DELTEN				7. Unit Agre	ement Name
b. Type of 1	DRILL)				PLUG B	ack 🗌	8, Farm of L	ease Name
oil Free		07 46			SINGLE X	MULT		Charol	ette
Hanie of C	peralot							9. Well No. 1	
MC.	Kay Oil Corpo	oration			18			10. Field ar	d Pool, or Wildcai
Ρ.	0. Box 2014,						&	W. Pecos	Slope Abo
Location	of Wells UNIT LETT		LOC.	1980	FLET FROM THE	East	LINE		
1800)	THE North) LIN	corsec. 17	TWP. 65	ec. 23	E NMPM		<u>IIIIIIII</u>
ÎIIÎÎ	MANNI	<u>IIIIIII</u>	<u>IIIII</u>			<u>IIII</u>	IIIII	12. County	
ΠÜ			HH			HHH	HHH	Chave	i fi fi fi finn
			HHH					illilli.	
ttitt.	itt (f f f f f f f f f f f f f f f f f f	ŤŤŤŤŤŤŤ	tt tt f	tittittitti	14. Proposed Der	oth 19	A. Formatic	0	20. holay or C.T.
IIII	nsjskow whether Dr.	<u>1/11111</u>		6 Status Plug. Bond	3,400 ¹ 21B. Drilling Cor		Abo	22 Appin	Rotary
	09 ¹ GL	, <i>A I</i> , <i>e</i> ic. <i>j</i>		(et	Grande D		,		
3.			_	ROPOSED CASING AN		,	,		
							EACKE O	E CEVENT	EST. TOP
<u> </u>	OF HOLE	SIZE OF		WEIGHT PER FOO 24.0 J-55	850 ±		1	icks	
7.7		4 1/		9.5 J-55	TD		250 sa	icks	circ
	, 								
	5 (11 10 1/	/ 11 1 1 .	ocot		anatum and		- -	face	
1.		1	\mathcal{B}	and run 8 5/8"	casing and	cement	to sur	face.	
2.	Wait on cem	ent for 1	8 Chours						
	Wait on cem	ent for í sing Doub	8 Chours						1000 psi
2.	Wait on cem Nipple up u for 30 minu	ent for I sing Doub tes.	8 A hours 1e Ram 1		nter and pr	essure	test ca		1000 psi
2. 3.	Wait on cem Nipple up u for 30 minu Drill 7 7/8 Run 4 1/2"	ent for Î sing Doub tes. " hole to casing if	<pre>8 hours 1e Ram 1 3,400' warrant</pre>	Blow Out Preve to adequately ted or plug an	nter and pr test the A d abandoned	essure bo form	test ca na ti on.	ising to	l Conservation
2. 3. 4.	Wait on cem Nipple up u for 30 minu Drill 7 7/8 Run 4 1/2"	ent for Î sing Doub tes. " hole to casing if	<pre>8 hours 1e Ram 1 3,400' warrant</pre>	3low Out Preve to adequately	nter and pr test the A d abandoned	essure bo form as din	test ca nation. rected b	using to by the Oi	1 Conservation . Fosted ID-1 NL, API
2. 3. 4.	Wait on cem Nipple up u for 30 minu Drill 7 7/8 Run 4 1/2"	ent for Î sing Doub tes. " hole to casing if	<pre>8 hours 1e Ram 1 3,400' warrant</pre>	Blow Out Preve to adequately ted or plug an	nter and pr test the A d abandoned	essure bo form as din	test ca nation. rected b	using to by the Oi	1 Conservation . Fosted ID-1 NL, API
2. 3. 4.	Wait on cem Nipple up u for 30 minu Drill 7 7/8 Run 4 1/2"	ent for Î sing Doub tes. " hole to casing if	<pre>8 hours 1e Ram 1 3,400' warrant</pre>	Blow Out Preve to adequately ted or plug an	nter and pr test the A d abandoned	essure bo form as dim	test ca mation. rected b	using to by the Oi $\sum \frac{18}{8/27/8}$	1 Conservation . Fosted ID-1 NL, API 2DAYS 3-6 87 37
2. 3. 4.	Wait on cem Nipple up u for 30 minu Drill 7 7/8 Run 4 1/2"	ent for Î sing Doub tes. " hole to casing if	<pre>8 hours 1e Ram 1 3,400' warrant</pre>	Blow Out Preve to adequately ted or plug an	nter and pr test the A d abandoned	essure bo form as dim	test ca mation. rected b	using to by the Oi	1 Conservation . Fosted ID-1 NL, API 2DAYS 3-6 87 37
2. 3. 4. 5.	Wait on cem Nipple up u for 30 minu Drill 7 7/8 Run 4 1/2" Division of	ent for 1 sing Doub tes. " hole to casing if the Ener	E hours le Ram 1 3,400' warrant gy and 1	Blow Out Preve to adequately ted or plug an	nter and protect the A d abandoned tment.	essure bo form as din (Nacco	test ca nation. rected to Differences 3 poilli	oy the Oi	1 Conservation Posted ID-1 NL, API 2DAYS 3-6 87 37 RWAY
2. 3. 4. 5.	Wait on cem Nipple up u for 30 minu Drill 7 7/8 Run 4 1/2" Division of	ent for 1 sing Doub tes. " hole to casing if the Ener	B hours le Ram 1 3,400' warrant gy and l	Blow Out Preve to adequately ted or plug an Minerals Depar	nter and protection of the A diabandoned tment.	essure bo form as din (Hang)	test ca nation. rected to Differences 3 poilli	oy the Oi	1 Conservation Posted ID-1 NL, API 2DAYS 3-6 87 87 RWAY
2. 3. 4. 5.	Wait on cem Nipple up u for 30 minu Drill 7 7/8 Run 4 1/2" Division of	ent for sing Doub tes. " hole to casing if the Ener	B hours 1e Ram 1 3,400' warrant gy and 1 beckets if f	Blow Out Preve to adequately ted or plug an Minerals Depar	nter and protect the A d abandoned tment.	essure bo form as din (Hang)	test ca nation. rected to Differences 3 poilli	oy the Oi	1 Conservation Posted ID-1 NL, API 2DAYS 3-6 87 87 RWAY
2. 3. 4. 5.	Wait on cem Nipple up u for 30 minu Drill 7 7/8 Run 4 1/2" Division of	ent for sing Doub tes. " hole to casing if the Ener	B hours 1e Ram 1 3,400' warrant gy and 1 beckets if f	Blow Out Preve to adequately ted or plug an Minerals Depar	nter and protect the A d abandoned tment.	essure bo form as din (Hang)	test ca nation. rected to Differences 3 poilli	oy the Oi	1 Conservation Posted ID-1 NL, API 2DAYS 3-6 87 87 RWAY
2. 3. 4. 5.	Wait on cem Nipple up u for 30 minu Drill 7 7/8 Run 4 1/2" Division of	ent for 1 sing Doub tes. " hole to casing if the Ener " hole Ener " hole to casing if the Ener	B hours 1e Ram 1 3,400' warrant gy and 1 constant and comp	Blow Out Preve to adequately ted or plug an Minerals Depar	nter and protect the A d abandoned tment.	essure bo form as din (Hang)	test ca nation. rected to Differences 3 poilli	by the Oi $D = POR \frac{78}{8}$ $B = \frac{778}{100}$ $B = \frac{78}{100}$ $B = \frac{78}{100}$	1 Conservation Posted ID-1 NL, API 2DAYS 3-6 87 37 RWAY AND ACCOSE OF A 5-87
2. 3. 4. 5.	Wait on cem Nipple up u for 30 minu Drill 7 7/8 Run 4 1/2" Division of	ent for 1 sing Doub tes. " hole to casing if the Ener " <i>manfle</i> Store Use, Origina Mike	B hours 1e Ram 1 3,400' warrant gy and 1 b and comp al Signed e William	Blow Out Preve to adequately ted or plug an Minerals Depar Minerals Depar <i>TuleLandm</i> By	nter and protect the A d abandoned tment.	essure bo form as din (1944) (test ca nation. rected b 2000000000000000000000000000000000000	by the Oi $D = POR \frac{78}{8}$ $B = \frac{778}{100}$ $B = \frac{78}{100}$ $B = \frac{78}{100}$	1 Conservation Posted ID-1 NL, API 2DAYS 3-6 87 87 RWAY
2. 3. 4. 5. hereby certa igned	Wait on cem Nipple up u for 30 minu Drill 7 7/8 Run 4 1/2" Division of	ent for 1 sing Doub tes. " hole to casing if the Ener " <i>manfle</i> Store Use, Origina Mike	B hours 1e Ram 1 3,400' warrant gy and 1 b and comp a Signed	Blow Out Preve to adequately ted or plug an Minerals Depar Minerals Depar <i>TuleLandm</i> By	nter and protect the A d abandoned tment.	essure bo form as din (1944) (test ca nation. rected b 2000000000000000000000000000000000000	by the Oi $D = POR \frac{78}{8}$ $B = \frac{778}{100}$ $B = \frac{78}{100}$ $B = \frac{78}{100}$	1 Conservation Posted ID-1 NL, API 2DAYS 3-6 87 37 RWAY AND ACCOSE OF A 5-87

+ U, HUX 2088

ENERGY AND MINERALS					MEXICO 8 er houndaries el			Revised 10-1-74
Operator		All dister	nces must n	Lease				₩+11 No. #1
McKAY OIL	<u>CORP</u> , 7	Township	6 SOUTH	Hang	CHAROLETTE 23 EAST	County	CHA	
Actual Fastage Locution a 1800 feet		NORTH	line co	a 1980	·	ot from the	EAST	line
Ground Level Elev. 4109	Producing For Abo	malion		P ool West	Pecos Slo	ope Abo		Dedicaled Acreage: 160 Acrea
1. Outline the act	enge dedica	ted to the	subject	Well-lg-co	fored pencil	a hachure	marks on the	plat below.
 If more than o interest and roy If more than on dated by communicated by communicate	ne lease is ralty). e lease of d mitization, u No If er o,'' list the	dedicated ifferent ov nitization, nswer is "	to the w wnership i force-poo yes;" type	ell, outline FEB 2 s dedicate olinga rtes ti e of consoli	EioPhe well, A. OFFICE	bave the i	nterests of	ercol (both as to working all owners been consoli- ed. (Use reverse side of
this form if nec No allowable w forced-pooling,	II be assign	ed to the w or until a	vell until a non-stand	all interest ard unit, e	s have been liminating su	consolidat ch interest	ed (by comm s, has been a	approved by the Division
			1800°		 		tained here been of my letty Name	in is true and complete to the knowledge and belief. W. Maxelin An L. Schultz
	 	•	Fee		1 1980''	~~>	Landman Compony McKay Date 2-25-8	Oil Corporation
	1 1 1 1 1 1 1 1 1 1 1 1 1 1						shown on t notes of o under my s	N.D. JAOU MEXICO MEX
0 330 L60 00	320 16 80 188	6 231 0 76	40 20	000 1500	1 1000	γ ι, τ. τ. τ . ζ γου ο	Certificate	

. ;

.

i.

.

:

•





BOP DIAGRAM

3000# Working Pressure Rams Operated Daily

EXHIBIT D