

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
None

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT DEPTH. USE "APPLICATION FOR PERMIT - C" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator Samedan Oil Corporation 3. Address of Operator 10 Desta Drive Suite 240 East, Midland, Texas 79705 4. Location of Well UNIT LETTER 0 560 FEET FROM THE South LINE AND 2080 FEET FROM THE East LINE, SECTION 24 TOWNSHIP 5 RANGE 25 NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3724.6 GR	RECEIVED BY JUN 23 1987 O. C. D. ARTESIA, OFFICE	7. Unit Agreement Name 8. Farm or Lease Name State SEA Cattle Co. 9. Well No. 1 10. Field and Pool, or Wildcat Und. Pecos Slope Abo 12. County Chaves
---	---	---

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-16-87 Set plug at at 4000' - 3750' with 35 sx cement. Tag plug @ 3750'.
Set 25 sx cement plug at 3128' - 3028'. Tag plug @ 3028'.
5-16-87 TIH with 2-1/16" tbq. Set 25 sx cement plug from 1075' to 975'. Tag up on cement plug 963'. Cut well head off install 5 sx cement plug @ surface and install marker. Clean up location.

Post IO-2
7-10-87
PAA

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Unto Diamond TITLE Division Production Clerk DATE 6/19/87
APPROVED BY Danell Moore TITLE Geologist DATE 12/14/88
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 22 1987
OCD
HOBBS OFFICE