Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, ...nerals and Natural Resources Department

Form C-103	/
Form C-103 Revised 1-1-89	, ~

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088

WELL API NO.

30-005-62547

DISTRICT II Santa Fe, New Mexico 8/304-2088	
O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease STATE X FEE
ISTRICT III 00 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
00 NO DIZZO KU., AZICC, NWI 6/410	
CUNDRY NOTICES AND DEPORTS ON MELLS	LG-9575
SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well:	
OE GAS WELL X OTHER	China Draw AEP State
Name of Operator	8. Well No.
VATES PETROLEUM CORPORATION	· 4
Address of Operator	9. Pool name or Wildcat
105 South 4th St., Artesia, NM 88210	Pecos Slope Abo
	.
Unit Letter N : 660 Feet From The South Line and 1980	Feet From The West Line
novice 36 m to 60 n 2011	311 mm c
Section 36 Township 6S Range 22E	NMPM Chaves County
4132.2' GR	
	anost or Other Date
	•
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
RFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
MPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
	MENT JOB
LL OR ALTER CASING CASING TEST AND CE	
LL OR ALTER CASING CASING TEST AND CE	
LL OR ALTER CASING CASING TEST AND CE HER: OTHER: Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, included the complete of the c	
LL OR ALTER CASING CASING TEST AND CE HER: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.	
LL OR ALTER CASING CASING TEST AND CE HER: OTHER: Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, included the complete of the c	
CASING TEST AND CE HER: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103. Propose to plug and abandon as follows:	
CASING TEST AND CE HER: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusivery) SEE RULE 1103. Propose to plug and abandon as follows: 1. TOOH with 2-3/8" tubing.	ding estimated date of starting any proposed
CASING TEST AND CE HER: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includingly) Propose to plug and abandon as follows: 1. TOOH with 2-3/8" tubing. 2. Set a CIBP at 2775'. Tag CIBP. Load casing with 9.5#	ding estimated date of starting any proposed
CASING TEST AND CE HER: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includingly work) SEE RULE 1103. Propose to plug and abandon as follows: 1. TOOH with 2-3/8" tubing. 2. Set a CIBP at 2775'. Tag CIBP. Load casing with 9.5# 3. Set a 10 sack Class C cement plug at 2775'.	ding estimated date of starting any proposed salt gel mud.
CASING TEST AND CE HER: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusively) SEE RULE 1103. Propose to plug and abandon as follows: 1. TOOH with 2-3/8" tubing. 2. Set a CIBP at 2775'. Tag CIBP. Load casing with 9.5# 3. Set a 10 sack Class C cement plug at 2775'. 4. Nipple down 4-1/2" casing head. Stretch 4-1/2" casing	ding estimated date of starting any proposed salt gel mud.
CASING TEST AND CE HER: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclus work) SEE RULE 1103. Propose to plug and abandon as follows: 1. TOOH with 2-3/8" tubing. 2. Set a CIBP at 2775'. Tag CIBP. Load casing with 9.5# 3. Set a 10 sack Class C cement plug at 2775'. 4. Nipple down 4-1/2" casing head. Stretch 4-1/2" casing Recover and lay down 4-1/2" casing.	ding estimated date of starting any proposed salt gel mud. and calculate freepoint.
CASING TEST AND CE HER: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclus work) SEE RULE 1103. Propose to plug and abandon as follows: 1. TOOH with 2-3/8" tubing. 2. Set a CIBP at 2775'. Tag CIBP. Load casing with 9.5# 3. Set a 10 sack Class C cement plug at 2775'. 4. Nipple down 4-1/2" casing head. Stretch 4-1/2" casing Recover and lay down 4-1/2" casing. 5. Set a 50 sack Class C cement plug from 50' below casing	ding estimated date of starting any proposed salt gel mud. and calculate freepoint.
CASING TEST AND CE HER: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includingly work) SEE RULE 1103. Propose to plug and abandon as follows: 1. TOOH with 2-3/8" tubing. 2. Set a CIBP at 2775'. Tag CIBP. Load casing with 9.5# 3. Set a 10 sack Class C cement plug at 2775'. 4. Nipple down 4-1/2" casing head. Stretch 4-1/2" casing Recover and lay down 4-1/2" casing. 5. Set a 50 sack Class C cement plug from 50' below casing 6. Set a 50 sack Class C cement plug from 960-860'.	ding estimated date of starting any proposed salt gel mud. and calculate freepoint.
CASING TEST AND CE HER: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includingly work) SEE RULE 1103. Propose to plug and abandon as follows: 1. TOOH with 2-3/8" tubing. 2. Set a CIBP at 2775'. Tag CIBP. Load casing with 9.5# 3. Set a 10 sack Class C cement plug at 2775'. 4. Nipple down 4-1/2" casing head. Stretch 4-1/2" casing Recover and lay down 4-1/2" casing. 5. Set a 50 sack Class C cement plug from 50' below casing 6. Set a 50 sack Class C cement plug from 960-860'.	ding estimated date of starting any proposed salt gel mud. and calculate freepoint.
CASING TEST AND CE HER: Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, include work) SEE RULE 1103. Propose to plug and abandon as follows: 1. TOOH with 2-3/8" tubing. 2. Set a CIBP at 2775'. Tag CIBP. Load casing with 9.5# 3. Set a 10 sack Class C cement plug at 2775'. 4. Nipple down 4-1/2" casing head. Stretch 4-1/2" casing Recover and lay down 4-1/2" casing. 5. Set a 50 sack Class C cement plug from 50' below casing 6. Set a 50 sack Class C cement plug from 960-860'. 7. Set a 10 sack Class C cement plug at surface. 8. Install regulation abandonment marker.	ding estimated date of starting any proposed salt gel mud. and calculate freepoint. g cut to 50' above.
CASING TEST AND CE HER: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includingly work) SEE RULE 1103. Propose to plug and abandon as follows: 1. TOOH with 2-3/8" tubing. 2. Set a CIBP at 2775'. Tag CIBP. Load casing with 9.5# 3. Set a 10 sack Class C cement plug at 2775'. 4. Nipple down 4-1/2" casing head. Stretch 4-1/2" casing Recover and lay down 4-1/2" casing. 5. Set a 50 sack Class C cement plug from 50' below casing 6. Set a 50 sack Class C cement plug from 960-860'. 7. Set a 10 sack Class C cement plug at surface.	ding estimated date of starting any proposed salt gel mud. and calculate freepoint. g cut to 50' above.
CASING TEST AND CE THER: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103. Propose to plug and abandon as follows: 1. TOOH with 2-3/8" tubing. 2. Set a CIBP at 2775'. Tag CIBP. Load casing with 9.5# 3. Set a 10 sack Class C cement plug at 2775'. 4. Nipple down 4-1/2" casing head. Stretch 4-1/2" casing Recover and lay down 4-1/2" casing. 5. Set a 50 sack Class C cement plug from 50' below casing 6. Set a 50 sack Class C cement plug from 960-860'. 7. Set a 10 sack Class C cement plug at surface. 8. Install regulation abandonment marker. NOTIFY OCD-ARTESIA (505-748-1283) 24 HOURS PRIOR TO COMMENCE.	ding estimated date of starting any proposed salt gel mud. and calculate freepoint. g cut to 50' above.
CASING TEST AND CE HER: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incline work) SEE RULE 1103. Propose to plug and abandon as follows: 1. TOOH with 2-3/8" tubing. 2. Set a CIBP at 2775'. Tag CIBP. Load casing with 9.5# 3. Set a 10 sack Class C cement plug at 2775'. 4. Nipple down 4-1/2" casing head. Stretch 4-1/2" casing Recover and lay down 4-1/2" casing. 5. Set a 50 sack Class C cement plug from 50' below casing 6. Set a 50 sack Class C cement plug from 960-860'. 7. Set a 10 sack Class C cement plug at surface. 8. Install regulation abandonment marker. NOTIFY OCD-ARTESIA (505-748-1283) 24 HOURS PRIOR TO COMMENCE hereby certify that the information above is true and complete to the best of my knowledge and belief.	salt gel mud. and calculate freepoint. g cut to 50' above. CING PLUGGING OPERATIONS
CASING TEST AND CE THER: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103. Propose to plug and abandon as follows: 1. TOOH with 2-3/8" tubing. 2. Set a CIBP at 2775'. Tag CIBP. Load casing with 9.5# 3. Set a 10 sack Class C cement plug at 2775'. 4. Nipple down 4-1/2" casing head. Stretch 4-1/2" casing Recover and lay down 4-1/2" casing. 5. Set a 50 sack Class C cement plug from 50' below casing 6. Set a 50 sack Class C cement plug from 960-860'. 7. Set a 10 sack Class C cement plug at surface. 8. Install regulation abandonment marker. NOTIFY OCD-ARTESIA (505-748-1283) 24 HOURS PRIOR TO COMMENCE TITLE Operations To COMMENCE TITLE	salt gel mud. and calculate freepoint. g cut to 50' above. CING PLUGGING OPERATIONS echnician DATE Jan. 27, 1998
CASING TEST AND CE HER: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incline work) SEE RULE 1103. Propose to plug and abandon as follows: 1. TOOH with 2-3/8" tubing. 2. Set a CIBP at 2775'. Tag CIBP. Load casing with 9.5# 3. Set a 10 sack Class C cement plug at 2775'. 4. Nipple down 4-1/2" casing head. Stretch 4-1/2" casing Recover and lay down 4-1/2" casing. 5. Set a 50 sack Class C cement plug from 50' below casing 6. Set a 50 sack Class C cement plug from 960-860'. 7. Set a 10 sack Class C cement plug at surface. 8. Install regulation abandonment marker. NOTIFY OCD-ARTESIA (505-748-1283) 24 HOURS PRIOR TO COMMENCE hereby certify that the information above is professed complete to the best of my knowledge and belief.	salt gel mud. and calculate freepoint. g cut to 50' above. CING PLUGGING OPERATIONS
CASING TEST AND CE OTHER: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103. Propose to plug and abandon as follows: 1. TOOH with 2-3/8" tubing. 2. Set a CIBP at 2775'. Tag CIBP. Load casing with 9.5# 3. Set a 10 sack Class C cement plug at 2775'. 4. Nipple down 4-1/2" casing head. Stretch 4-1/2" casing Recover and lay down 4-1/2" casing. 5. Set a 50 sack Class C cement plug from 50' below casing 6. Set a 50 sack Class C cement plug from 960-860'. 7. Set a 10 sack Class C cement plug at surface. 8. Install regulation abandonment marker. NOTIFY OCD-ARTESIA (505-748-1283) 24 HOURS PRIOR TO COMMENT OF TITLE OPERATIONS TO THE SPECE FOR STATE USE) CONSTURE Rusty Klein This spece for State Use)	salt gel mud. and calculate freepoint. g cut to 50' above. CING PLUGGING OPERATIONS echnician DATE Jan. 27, 1998