			CISF		
ubmit 3 Copies To Appropriate District	State of New Mer	xico	- An	Form C-103	
Office	Energy, Minerals and Natural Resources		VY	Revised March 25, 1999	
District I	Lifergy, whiterais and reacting resources		WELL API NO.		
625 N. French Dr., Hobbs, NM 88240 District II	OU CONCEDUATION DIVISION		30-005-62589		
11 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of	Lease	
District III	1220 South St. Francis Dr.		STATE FEE X		
000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87	7505	6. State Oil & Ga	s Lease No.	
220 S. St. Francis Dr., Santa Fe, NM					
7505	CES AND REPORTS ON WELLS		7. Lease Name or	Unit Agreement Name:	
NO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			,,	5	
DIFFERENT RESERVOIR. USE "APPLIC	JSE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				
PROPOSALS.)	6171	18 19 20 3	McConkey HX		
. Type of Well: Oil Well Gas Well X	Other				
Oil Well Gas Well X Name of Operator	- Ounci		7. Well No.		
Yates Petroleum Corpor	ration /	na <b>x</b> ng k	#4		
Address of Operator		FIVED	8. Pool name or	Wildcat	
-	ia, NM 88210	RIESIA	Undesiana	led Foor Ranch	
105 5. 4 <sup>10</sup> Sileer Alles			Pre-Permian		
. Well Location				· · · · · · · ·	
. Well Location					
Unit Letter L : 19	<b>80</b> feet from the <b>South</b> li	ine and 660	feet from the We	st line	
Section 10	Township <b>9S</b> Range		MPM Chaves	County	
	10. Elevation (Show whether D	R, RKB, RT, GR, et	<i>c.)</i>		
	3813				
11. Check A	ppropriate Box to Indicate N	ature of Notice,	Report or Other	Data	
NOTICE OF IN		SUE	BSEQUENT RE	PORT OF:	
		REMEDIAL WOR			
	CHANGE PLANS				
		CASING TEST A			
	COMPLETION			<u> </u>	
OTHER:		OTHER: Perfor	ate, acidize	X	
				ding estimated data of	
Describe proposed or completed of	nerations (Clearly state all nertine	IN OPTIMIS AND PIVE			
Describe proposed or completed of terring any proposed work) SFE	perations. (Clearly state all pertine RULE 1103 For Multiple Comple	etions: Attach well	bore diagram of prop	osed completion or	
starting any proposed work). SEE	perations. (Clearly state all pertine RULE 1103. For Multiple Comple	etions: Attach well	bore diagram of prop	osed completion or	
starting any proposed work). SEE recompilation.	RULE 1103. For Multiple Comple	etions: Attach well	bore diagram of prop	osed completion or	
starting any proposed work). SEE recompilation. 11/27/00 – RU pulling unit. TIH w	RULE 1103. For Multiple Complete th bit and scraper. Tag PBTD at a	etions: Attach well	bore diagram of prop	osed completion or	
tarting any proposed work). SEE ecompilation. 11/27/00 – RU pulling unit. TIH w 11/28/00 – Run GR/CBL/CCL. TC Perf Ordovician 6269-6274', 24 h	RULE 1103. For Multiple Complet th bit and scraper. Tag PBTD at 6 OC 4015'. Holes, .41" holes. Spot 200 gals 20	etions: Attach well 6430'. 0% IC HCL. Swab	bore diagram of prop	osed completion or	
starting any proposed work). SEE recompilation. 1 1/27/00 – RU pulling unit. TIH w 1 1/28/00 – Run GR/CBL/CCL. TC Perf Ordovician 6269-6274', 24 h 1 2/1/00 – Set CIBP at 6250'. Per	RULE 1103. For Multiple Complet th bit and scraper. Tag PBTD at a OC 4015'. Holes, .41" holes. Spot 200 gals 20 F Ordovician 6152-6158', 24 holes	etions: Attach well 6430'. 0% IC HCL. Swab s, .41" holes.	bore diagram of prop	osed completion or	
starting any proposed work). SEE recompilation. 11/27/00 – RU pulling unit. TIH w 11/28/00 – Run GR/CBL/CCL. TC Perf Ordovician 6269-6274', 24 h 12/1/00 – Set CIBP at 6250'. Per	RULE 1103. For Multiple Complet th bit and scraper. Tag PBTD at 6 OC 4015'. Holes, .41" holes. Spot 200 gals 20	etions: Attach well 6430'. 0% IC HCL. Swab s, .41" holes.	bore diagram of prop	osed completion or	
starting any proposed work). SEE recompilation. 11/27/00 – RU pulling unit. TIH w 11/28/00 – Run GR/CBL/CCL. TC Perf Ordovician 6269-6274', 24 h 12/1/00 – Set CIBP at 6250'. Per 12/4/00 - Spot 7 bbls 20% IC HCI 12/10/00 – Elow test well.	RULE 1103. For Multiple Complet th bit and scraper. Tag PBTD at OC 4015'. Holes, .41" holes. Spot 200 gals 20 F Ordovician 6152-6158', 24 holes Swab. Well started flowing. RI	etions: Attach well 6430'. 0% IC HCL. Swab s, .41" holes. D and move off.	bore diagram of prop	osed completion or	
starting any proposed work). SEE recompilation. 11/27/00 – RU pulling unit. TIH w 11/28/00 – Run GR/CBL/CCL. TO Perf Ordovician 6269-6274', 24 h 12/1/00 – Set CIBP at 6250'. Per 12/4/00 - Spot 7 bbls 20% IC HCI 12/10/00 – Flow test well. 1/9/01 – RU acid crew. Acidize	RULE 1103. For Multiple Complet th bit and scraper. Tag PBTD at a OC 4015'. Holes, .41" holes. Spot 200 gals 20 F Ordovician 6152-6158', 24 holes	etions: Attach well 6430'. 0% IC HCL. Swab s, .41" holes. D and move off.	bore diagram of prop	osed completion or	
starting any proposed work). SEE recompilation. 11/27/00 – RU pulling unit. TIH w 11/28/00 – Run GR/CBL/CCL. TC Perf Ordovician 6269-6274', 24 h 12/1/00 – Set CIBP at 6250'. Per 12/4/00 - Spot 7 bbls 20% IC HCl 12/10/00 – Flow test well. 1/9/01 – RU acid crew. Acidize and flow test well.	RULE 1103. For Multiple Complet th bit and scraper. Tag PBTD at OC 4015'. Holes, .41" holes. Spot 200 gals 20 F Ordovician 6152-6158', 24 holes Swab. Well started flowing. RI	etions: Attach well 6430'. 0% IC HCL. Swab s, .41" holes. D and move off.	bore diagram of prop	osed completion or	
starting any proposed work). SEE recompilation. 11/27/00 – RU pulling unit. TIH w 11/28/00 – Run GR/CBL/CCL. TC Perf Ordovician 6269-6274', 24 h 12/1/00 – Set CIBP at 6250'. Per 12/4/00 - Spot 7 bbls 20% IC HCI 12/10/00 – Flow test well. 1/9/01 – RU acid crew. Acidize and flow test well. 2/7/01 – MI and RU pulling unit.	RULE 1103. For Multiple Complet th bit and scraper. Tag PBTD at a DC 4015'. Ioles, .41" holes. Spot 200 gals 20 F Ordovician 6152-6158', 24 holes Swab. Well started flowing. RI Ordovician perfs 6152-6158' with	etions: Attach well 6430'. 0% IC HCL. Swab 5, .41" holes. D and move off. n 2000 gals 20% IC	bore diagram of prop . No shows. HCL. + 72,000 SCF N	osed completion or 12. Flow back acid	
starting any proposed work). SEE recompilation. 11/27/00 – RU pulling unit. TIH w 11/28/00 – Run GR/CBL/CCL. TO Perf Ordovician 6269-6274', 24 h 12/1/00 – Set CIBP at 6250'. Per 12/4/00 - Spot 7 bbls 20% IC HCI 12/10/00 – Flow test well. 1/9/01 – RU acid crew. Acidize and flow test well. 2/7/01 – MI and RU pulling unit. 2/8/01 – Perf Ordovician 6042-6	RULE 1103. For Multiple Complet th bit and scraper. Tag PBTD at a DC 4015'. ioles, .41" holes. Spot 200 gals 20 F Ordovician 6152-6158', 24 holes Swab. Well started flowing. RI Ordovician perfs 6152-6158' with	etions: Attach well 6430'. 0% IC HCL. Swab 5, .41" holes. D and move off. n 2000 gals 20% IC es and 6098-6114	bore diagram of prop . No shows. HCL. + 72,000 SCF N ', 64 holes, .42'' hole	osed completion or V2. Flow back acid s.	
starting any proposed work). SEE recompilation. 11/27/00 – RU pulling unit. TIH w 11/28/00 – Run GR/CBL/CCL. TO Perf Ordovician 6269-6274', 24 h 12/1/00 – Set CIBP at 6250'. Per 12/4/00 - Spot 7 bbls 20% IC HCI 12/10/00 – Flow test well. 1/9/01 – RU acid crew. Acidize and flow test well. 2/7/01 – MI and RU pulling unit. 2/8/01 – Perf Ordovician 6042-6 2/9/01 – Spot 2 bbls 20% IC HCL	RULE 1103. For Multiple Complet th bit and scraper. Tag PBTD at a DC 4015'. Ioles, .41" holes. Spot 200 gals 20 F Ordovician 6152-6158', 24 holes Swab. Well started flowing. RI Ordovician perfs 6152-6158' with 048', 24 holes, 6064-6080', 64 hole . Straddle perfs 6098-6114'. Con	etions: Attach well 6430'. 0% IC HCL. Swab s, .41" holes. D and move off. n 2000 gals 20% IC es and 6098-6114 nmunicated with	bore diagram of prop . No shows. HCL. + 72,000 SCF N ', 64 holes, .42'' hole	osed completion or V2. Flow back acid s.	
starting any proposed work). SEE recompilation. (1/27/00 – RU pulling unit. TIH w (1/28/00 – Run GR/CBL/CCL. TC Perf Ordovician 6269-6274', 24 h (2/1/00 – Set CIBP at 6250'. Per (12/4/00 - Spot 7 bbls 20% IC HCI (12/10/00 – Flow test well. (19/01 – RU acid crew. Acidize and flow test well. (2/7/01 – MI and RU pulling unit. (2/8/01 – Perf Ordovician 6042-6 (2/9/01 – Spot 2 bbls 20% IC HCL 6042-6114'. Acidize with 3800 g	RULE 1103. For Multiple Complet th bit and scraper. Tag PBTD at a DC 4015'. ioles, .41" holes. Spot 200 gals 20 F Ordovician 6152-6158', 24 holes Swab. Well started flowing. RI Ordovician perfs 6152-6158' with	etions: Attach well 6430'. 0% IC HCL. Swab s, .41" holes. D and move off. n 2000 gals 20% IC es and 6098-6114 nmunicated with	bore diagram of prop . No shows. HCL. + 72,000 SCF N ', 64 holes, .42'' hole	osed completion or V2. Flow back acid s.	
starting any proposed work). SEE recompilation. 11/27/00 - RU pulling unit. TIH w 11/28/00 - Run GR/CBL/CCL. TO Perf Ordovician 6269-6274', 24 h 12/1/00 - Set CIBP at 6250'. Per 12/4/00 - Spot 7 bbls 20% IC HCI 12/10/00 - Flow test well. 1/9/01 - RU acid crew. Acidize and flow test well. 2/7/01 - MI and RU pulling unit. 2/8/01 - Perf Ordovician 6042-6 2/9/01 - Spot 2 bbls 20% IC HCL 6042-6114'. Acidize with 3800 g 2/12/01 - Set RBP at 5535'. See Attached	RULE 1103. For Multiple Complet th bit and scraper. Tag PBTD at a loles, .41" holes. Spot 200 gals 20 6 Ordovician 6152-6158', 24 holes Swab. Well started flowing. RI Ordovician perfs 6152-6158' with 048', 24 holes, 6064-6080', 64 hole . Straddle perfs 6098-6114'. Con gals 20% IC HCL + 200 ball sealers	etions: Attach well 6430'. 0% IC HCL. Swab 5, .41" holes. D and move off. n 2000 gals 20% IC es and 6098-6114 nmunicated with s. Swab.	bore diagram of prop . No shows. HCL. + 72,000 SCF N ', 64 holes, .42'' hole upper perfs. Move	osed completion or V2. Flow back acid s.	
starting any proposed work). SEE recompilation. 11/27/00 - RU pulling unit. TIH w 11/28/00 - Run GR/CBL/CCL. TO Perf Ordovician 6269-6274', 24 h 12/1/00 - Set CIBP at 6250'. Per 12/4/00 - Spot 7 bbls 20% IC HCI 12/10/00 - Flow test well. 1/9/01 - RU acid crew. Acidize and flow test well. 2/7/01 - MI and RU pulling unit. 2/8/01 - Perf Ordovician 6042-6 2/9/01 - Spot 2 bbls 20% IC HCL 6042-6114'. Acidize with 3800 g 2/12/01 - Set RBP at 5535'. See Attached	RULE 1103. For Multiple Complet th bit and scraper. Tag PBTD at a loles, .41" holes. Spot 200 gals 20 6 Ordovician 6152-6158', 24 holes Swab. Well started flowing. RI Ordovician perfs 6152-6158' with 048', 24 holes, 6064-6080', 64 hole . Straddle perfs 6098-6114'. Con gals 20% IC HCL + 200 ball sealers	etions: Attach well 6430'. 0% IC HCL. Swab 5, .41" holes. D and move off. n 2000 gals 20% IC es and 6098-6114 nmunicated with s. Swab.	bore diagram of prop . No shows. HCL. + 72,000 SCF N ', 64 holes, .42'' hole upper perfs. Move	osed completion or V2. Flow back acid s.	
starting any proposed work). SEE recompilation. 11/27/00 - RU pulling unit. TIH w 11/28/00 - Run GR/CBL/CCL. TO Perf Ordovician 6269-6274', 24 h 12/1/00 - Set CIBP at 6250'. Per 12/4/00 - Spot 7 bbls 20% IC HCI 12/10/00 - Flow test well. 1/9/01 - RU acid crew. Acidize and flow test well. 2/7/01 - MI and RU pulling unit. 2/8/01 - Perf Ordovician 6042-6 2/9/01 - Spot 2 bbls 20% IC HCL 6042-6114'. Acidize with 3800 g 2/12/01 - Set RBP at 5535'. See Attached	RULE 1103. For Multiple Complet th bit and scraper. Tag PBTD at a OC 4015'. Holes, .41" holes. Spot 200 gals 20 F Ordovician 6152-6158', 24 holes Swab. Well started flowing. RI Ordovician perfs 6152-6158' with 048', 24 holes, 6064-6080', 64 hole Straddle perfs 6098-6114'. Con gals 20% IC HCL + 200 ball sealers	etions: Attach well 6430'. 0% IC HCL. Swab s, .41" holes. D and move off. n 2000 gals 20% IC es and 6098-6114 mmunicated with s. Swab. e best of my knowl	bore diagram of prop . No shows. HCL. + 72,000 SCF N , 64 holes, .42" hole upper perfs. Move edge and belief.	vsed completion or v2. Flow back acid s. tools and straddle perfs	
starting any proposed work). SEE recompilation. 11/27/00 - RU pulling unit. TIH w 11/28/00 - RU GR/CBL/CCL. TO Perf Ordovician 6269-6274', 24 h 12/1/00 - Set CIBP at 6250'. Per 12/4/00 - Spot 7 bbls 20% IC HCI 12/10/00 - Flow test well. 1/9/01 - RU acid crew. Acidize and flow test well. 2/7/01 - MI and RU pulling unit. 2/8/01 - Perf Ordovician 6042-6 2/9/01 - Spot 2 bbls 20% IC HCL 6042-6114'. Acidize with 3800 g 2/12/01 - Set RBP at 5535'. See Attached	RULE 1103. For Multiple Complet th bit and scraper. Tag PBTD at a OC 4015'. Holes, .41" holes. Spot 200 gals 20 F Ordovician 6152-6158', 24 holes Swab. Well started flowing. RI Ordovician perfs 6152-6158' with 048', 24 holes, 6064-6080', 64 hole Straddle perfs 6098-6114'. Con gals 20% IC HCL + 200 ball sealers	etions: Attach well 6430'. 0% IC HCL. Swab s, .41" holes. D and move off. n 2000 gals 20% IC es and 6098-6114 mmunicated with s. Swab. e best of my knowl	bore diagram of prop . No shows. HCL. + 72,000 SCF N , 64 holes, .42" hole upper perfs. Move edge and belief.	osed completion or 12. Flow back acid s.	
starting any proposed work). SEE recompilation. 11/27/00 – RU pulling unit. TIH w 11/28/00 – Run GR/CBL/CCL. TC Perf Ordovician 6269-6274', 24 h 12/1/00 – Set CIBP at 6250'. Per 12/4/00 - Spot 7 bbls 20% IC HCI 12/10/00 – Flow test well. 1/9/01 – RU acid crew. Acidize and flow test well. 2/7/01 – MI and RU pulling unit. 2/8/01 – Perf Ordovician 6042-6 2/9/01 – Spot 2 bbls 20% IC HCL 6042-6114'. Acidize with 3800 g 2/12/01 – Set RBP at 5535'. See Attached Thereby certify that the information SIGNATURE	RULE 1103. For Multiple Complet th bit and scraper. Tag PBTD at a DC 4015'. Holes, .41" holes. Spot 200 gals 20 F Ordovician 6152-6158', 24 holes Swab. Well started flowing. RI Ordovician perfs 6152-6158' with 048', 24 holes, 6064-6080', 64 hole Straddle perfs 6098-6114'. Com gals 20% IC HCL + 200 ball sealers on above is true and complete to the Muppin	etions: Attach well 6430'. 0% IC HCL. Swab s, .41" holes. D and move off. n 2000 gals 20% IC es and 6098-6114 mmunicated with s. Swab. e best of my knowl Engineering Te	bore diagram of prop . No shows. HCL. + 72,000 SCF M ', 64 holes, .42'' hole upper perfs. Move edge and belief. chnician _DATE	vsed completion or v2. Flow back acid s. tools and straddle perfs	
starting any proposed work). SEE recompilation. 11/27/00 – RU pulling unit. TIH w 11/28/00 – Run GR/CBL/CCL. TO Perf Ordovician 6269-6274', 24 h 12/1/00 – Set CIBP at 6250'. Per 12/4/00 - Spot 7 bbls 20% IC HCI 12/10/00 – Flow test well. 1/9/01 – RU acid crew. Acidize and flow test well. 2/7/01 – MI and RU pulling unit. 2/8/01 – Perf Ordovician 6042-6 2/9/01 – Spot 2 bbls 20% IC HCL 6042-6114'. Acidize with 3800 (s 2/12/01 – Set RBP at 5535'. See Attached I hereby certify that the information SIGNATURE Type or print name Susan H (This space for State use)	RULE 1103. For Multiple Complet th bit and scraper. Tag PBTD at a DC 4015'. Holes, .41" holes. Spot 200 gals 20 F Ordovician 6152-6158', 24 holes . Swab. Well started flowing. RI Ordovician perfs 6152-6158' with 048', 24 holes, 6064-6080', 64 hole . Straddle perfs 6098-6114'. Con gals 20% IC HCL + 200 ball sealers on above is true and complete to the Mupting TITLEE erpin	etions: Attach well 6430'. 0% IC HCL. Swab s, .41" holes. D and move off. n 2000 gals 20% IC es and 6098-6114 mmunicated with s. Swab. e best of my knowl Engineering Te	bore diagram of prop . No shows. HCL. + 72,000 SCF M ', 64 holes, .42'' hole upper perfs. Move edge and belief. chnician _DATE	vsed completion or 12. Flow back acid s. tools and straddle perfs September 14, 2001 e No. 505-748-1471	
tarting any proposed work). SEE ecompilation. 1/27/00 – RU pulling unit. TIH w 1/28/00 – Run GR/CBL/CCL. TO Perf Ordovician 6269-6274', 24 h 12/1/00 – Set CIBP at 6250'. Per 12/4/00 - Spot 7 bbls 20% IC HCI 12/10/00 – Flow test well. 1/9/01 – RU acid crew. Acidize and flow test well. 2/7/01 – MI and RU pulling unit. 2/8/01 – Perf Ordovician 6042-6 2/9/01 – Spot 2 bbls 20% IC HCL 6042-6114'. Acidize with 3800 (s 2/12/01 – Set RBP at 5535'. See Attached I hereby certify that the information SIGNATURE Type or print name SUSCI H	RULE 1103. For Multiple Complet th bit and scraper. Tag PBTD at a DC 4015'. Holes, .41" holes. Spot 200 gals 20 F Ordovician 6152-6158', 24 holes Swab. Well started flowing. RI Ordovician perfs 6152-6158' with 048', 24 holes, 6064-6080', 64 hole Straddle perfs 6098-6114'. Com gals 20% IC HCL + 200 ball sealers on above is true and complete to the Muppin	etions: Attach well 6430'. 0% IC HCL. Swab 5, .41" holes. D and move off. n 2000 gals 20% IC es and 6098-6114 nmunicated with s. Swab. e best of my knowl Engineering Te	bore diagram of prop . No shows. HCL. + 72,000 SCF M ', 64 holes, .42'' hole upper perfs. Move edge and belief. chnician _DATE	vsed completion or 12. Flow back acid s. tools and straddle perfs September 14, 2001	

Yates Petroleum Corporation McConkey HX #4 API – 30-005-62584 Section 10 T9S R26E Chaves County, NM

## **Describe Proposed or Completed Operations:**

2/13/01 - Perf Wolfcamp 5436-5446', 22 holes, .42" holes. Acidized with 1000 gals 15% IC HCL + ball sealers. Swab.

2/15/01 - Acidize Wolfcamp perfs 5436-5446' with 5000 gals 15% IC HCL.. Swab.

2/20/01 - TOH with RBP. TIH with packer, 2-7/8" tubing, 40' blast jts., and sliding sleeve. Set packer at 5993' and sliding sleeve at 5419'. Ordovician perfs flowing up tubing, Wolfcamp perfs flowing up casing.

2/21/01 – Close sliding sleeve. Rig down pulling unit and turn well to production.

3/21/01 – Set blanking plug in packer at 5993'. Sliding sleeve is open. Turn well to production.

3/30/01 – Pulled blanking plug. Turn well to production.