

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

C/SF
DD

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

FEB -7 '90

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-005-62707

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.
L-6772

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Whitworth RU State

1. Type of Well:
OIL WELL GAS WELL OTHER P&A

8. Well No.
5

2. Name of Operator
YATES PETROLEUM CORPORATION

9. Pool name or Wildcat
Und. Foor Ranch Wolfcamp

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter 0 : 660 Feet From The South Line and 1980 Feet From The East Line

Section 12 Township 9S Range 26E NMPM Chaves County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3828.3' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 5450'. Propose to plug and abandon well as follows:
Spot cement plug from 4880-4985' to cover Wolfcamp perms 4933-35'. 25 sv. @ 4749' + Tag
Freepoint casing (cement top at 4158' by CBL).
Cut casing 100' above freepoint and pull.
Spot 100' cement plug 50' in and out of stub. Tag plug. 25 sv. m. in
Load hole w/NMOCD approved plugging mud.
Spot cement plug from 2275-2430' across Yeso and Glorieta tops. 25 sv.
Spot cement plug from 1130-1240' across 8-5/8" shoe. Tag plug. 25 sv.
Set 15 sack plug at surface and install abandonment marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 2-6-90

TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)
APPROVED BY MIKE WILLY SUPERVISOR, DISTRICT I TITLE SUPV DATE FEB 16 1990

CONDITIONS OF APPROVAL, IF ANY:
Notify N.M.O.C.C. in sufficient time to witness
Pl.