

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

2040 South Pacheco  
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO. 30-005-20346

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
16496

7. Lease Name or Unit Agreement Name  
Double L Queen Unit Tract 23  
Fed Agree 8910160560

8. Well No. 3

9. Pool name or Wildcat  
Double L Queen

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3906

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☐ Gas Well ☐ Other WIW

2. Name of Operator  
Saga Petroleum LLC

3. Address of Operator  
415 W Wall, Suite 1900  
Midland, TX 79701

4. Well Location

Unit Letter A 330 feet from the N line and 289 feet from the E line

Section 6 Township 15S Range 29E NMPM County CHAVES

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3906

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOBS ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.

Intent to P&A this SI WIW (well converted to WIW 10/78)

MIRU, POOH w/rods, NU BOP, POOH w/tbg (4-1/2" 9.5# csg @ 2040' w/200 sx)

Set CIBP @ 1950' w/35' cmt on top

RIH, circ well w/9.8# mud

POOH to 1300', spot 100' cmt plug, perf 5-1/2" csg @ 1300', squeeze 100' cmt plug inside & outside 5-1/2" csg, tag

POOH to 200', spot 100' cmt plug - perf & squeeze @ 200' - fill annulus w/cmt - tag plug

(8-5/8" 24# csg @ 358' w/275 sx)

Perf 5-1/2" csg @ 50', circ cmt to surface

Cut off WH, install dry hole marker

OCD will be notified 24 hrs prior to begin P&A operations

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Husband TITLE Production Analyst

DATE 03/23/2001

Type or print name Bonnie Husband

Telephone No. (915)684-4293

(This space for State use)

APPROVED BY [Signature] TITLE Field Rep

DATE 3 August 2001

Conditions of approval, if any:

